



ENVIRONMENTAL INCIDENT REPORT - CARBON COUNTY - NATURAL GAS RELEASE

Report Taken By:	Michael Swistak		
Date / Time Reported:	4/23/2024 15:0		

REPORTING PARTY DATES AND TIMES

Reporting Party:	Julie Coon	Title:	
Company:	Williams Companies	Phone:	(918) 573-5000
Date & Time Discovered:	4/23/2024 11:45		

RESPONSIBLE PARTY

Name:		Phone:	
Address:			

INCIDENT LOCATION

Incident Address:			
Nearest Town:	MYTON	County:	DUCHESNE
Highway:		Mile Marker:	
UTM:	(E) 580428 (N) 4417155	Land Ownership:	SITLA

INCIDENT SUMMARY

Caller stated that a pressure relief valve on a junction for a pipeline released 14.9 million cubic feet of natural gas. The cause of the release is being attributed to a bottleneck from an out of service station in the area. The leak has been stopped and the line isolated. No other notifications made from the RP.

NRC #1397151

CHEMICAL(S) REPORTED

Natural Gas 14.9 Other: (Describe) Million cubic feet

IMPACTED MEDIA	Media	Media Other	Land Use	Waterway Name	Near Water	Distance	NRC Rpt. #
	Outdoor Air	N/A	Oil & Gas Production Field	N/A		N/A	1397151

NOTIFICATIONS MADE

Agency	Contact	Date	Time	By	Active?
DAQ	Jay Morris	4/23/2024	15:35	Michael Swistak	



Utah Department of Environmental Quality
Division of Environmental Response and Remediation
195 North 1950 West Salt Lake City, Utah 84116
Bus. Hours: 801-536-4100
Report Spills 24/7/365: 801-536-4123

Report Number 17036

ACTIONS TAKEN	Date	Agency	Action	Action Details
	4/25/2024	DERR	Update	UPDATED INFO IS AS FOLLOWS FROM NRC: #1397280 RELIEF VALVE RV417 AT THE GREEN RIVER STATION LIFTED RELEASING APPROX. 14.3 MILLION STANDARD CUBIC FT OF GAS OVER THE COURSE OF AN HOUR. BOTH PSV'S OPERATED AS DESIGNED BOTH RELEASES OCCURRED BETWEEN 1200 PM AND 1300 PM (MT). THEY CURRENTLY BELIEVE THE CAUSE OF THE EVENT WAS FROM HIGH PRESSURE ON THE PIPELINE THAT WAS DUE IN PART TO COMPRESSOR SHUT DOWNS AT A COMPRESSOR STATION ON THE SYSTEM. IN ADDITION TO THE COMPRESSOR SHUTDOWN AT ONE STATION, ANOTHER COMPRESSOR STATION WAS SHUTDOWN FOR PLANNED MAINTENANCE. A DELIVERY TO A CUSTOMER WAS CLOSED FOR A PROJECT DURING THE SAME TIME PERIOD. THE RESULT OF THESE OUTAGES LEAD TO ELEVATED BUT INTOLERANCE PRESSURES ON MAIN LINE 40. THE UNEXPECTED SHUTDOWN OF THE COMPRESSOR STATION FURTHER ELEVATED PRESSURE IN THE LINE. THESE INCIDENTS HAVE SINCE BEEN COMBINED DUE TO THE SHARED CAUSAL FACTORS. INVESTIGATION IS STILL ON GOING AS TO CONCLUSIVE FACTORS AND AN UPDATE WILL BE PROVIDED IN 30-DAY REPORT