

U_Arduino_Nucleo Connectors
Test Arduino_Nucleo Connectors.SchDoc

U_Sensors
Test Sensors.SchDoc

U_Adapter Board
Test Adapter Board.SchDoc




I2C1
I2C2
I2Caux
SPI
not used



Title
X-NUCLEO-IKS5A1

Size A3	Number	Revision
Date 7/03/2025	Sheet of	
File C:\Users\...\Test TOP_IKS5A1.SchDoc	Drawn By:	


IIS2DULPX - ACCELEROMETER




ISM6HG256X - IMU Accelerometer + Gyroscope (HUB 1)



ILPS22QS - PRESSURE





IIS2MDC - MAGNETOMETER






Accelerometer + Gyroscope (HUB 2)

ISM330IS - ISPU



2x52mm



ALL shunt of JP3, JP4 and JP5 (2mm) must be closed

I2C routing description

Place the shunt in order to select the master for the sensors U7, U8, 10, U12 and Adapter.
HUB1 must be connected to GND if not used!

Title

X-NUCLEO-IKS5A1

Size

A3

Revision

Date:

7/03/2025

Sheet of








1

File:

C:\Users\...\Test Sensors.SchDoc





Drawn By:

Arduino & Morpho Connectors





Close pin12 (A_INT2)

Title <i>X-NUCLEO-IKS5A1</i>		
Size A3	Number	Revision
Date 7/03/2025	Sheet of	
File: C:\Users\...\Test Arduino Nucleo Connected to SD Card	of 1	



JP6, JP8, JP9 and JP10 CLOSE shunt pin1 and pin2



Title <i>X-NUCLEO-IKS5A1</i>		
Size A3	Number	Revision
Date 7/03/2025	Sheet of	
File C:\Users\...\Test Adapter Board.SchDoc	Drawn By	