# Environment (base on Fedora 25)

# step1. Install packages

dnf update

dnf install gcc-c++

dnf install ncurses-devel

dnf install flex

dnf install zlib-devel

dnf install byacc

dnf install bison

dnf install cmake

dnf install sharutils

dnf install Izma

dnf install Izma-devel

dnf install xz-devel

dnf install rcs

dnf install gperf

dnf groupinstall "Development tools"

### step2. disabled selinux

# vi /etc/selinux/config

SELINUX=disabled

#### step3. make downgrade

# dnf --nogpgcheck --releasever=13 downgrade make

#### step4. install automake14-1.4p6-20.fc13.noarch.rpm

# rpm -ivh automake14-1.4p6-20.fc13.noarch.rpm

step5. Switch to "root" privileges

# step6. Uncompress GPL file to /home

# tar -C /home -zxvf 20170329\_BR6477AC\_Edimax\_GPL.tar.gz

#### step7. Compiler firmware

# cd /home/20170329\_BR6477AC\_Edimax\_GPL /BR6477AC\_Edimax

# ./BUILD.sh BR-6208ACv2

# Step8. If compiler successfully that you will find the file at below path, if not please re-check the steps

/home/BR6477AC\_Edimax/image/BR6278AC/Edimax/Tester/BR6278AC\_Edimax\_1.02\_GPL\_upg.bin