2884 NND

Assessment Report

(Print Date: 30/06/2022, 11:38:53)




Original Image AI Detected Damages Assessment Report Damage Damage Repair Parts Status Status Front Bumper Replace Bumper Crack **Bonnet Dent Minor** Repair Bumper Front Grill Replace Crack Unidentified Panel Gap Repair Panel Minor **Damage Damage** Repair **Parts** Status Status Right **Dent Minor** Repair Fender Minor **Damage Damage** Repair **Parts** Status Status Rear Scratch Repair Bumper Major


2884 NND





Damage Parts	Damage Status	Repair Status		
Front Bumper	Panel Gap, Scratch	Repair		
Tyre	Panel Gap	Repair		
Left Fender	Panel Gap	Repair		
Unidentified Panel	Dent Medium, Dent Minor	Repair		
Medium				





Damage Parts	Damage Status	Repair Status
Front Bumper	Bumper Crack	Replace
Bonnet	Dent Medium, Dent Minor	Repair
Front Grill	Bumper Crack	Replace
Unidentified Panel	Panel Gap, Scratch	Repair
Medium		





Damage	Damage	Repair		
Parts	Status	Status		
No Damage				





Damage Parts	Damage Status	Repair Status		
Rear Bumper	Crack, Scratch	Replace		
Right Tail Lamp	Crack	Replace		
Right Quarter Panel	Crack, Scratch	Replace		
Major				

