

FID-10: No Connection to Unit - Hardware Module: AEHC

This document section is exclusively about Fault ID FID-10 occurring in Hardware Module AEHC. Applicable SW is 25R3, 26R1, 26R2. Waiting Period is 120 Minutes (2 Hours). Use this file when query contains AEHC.

Fault ID: FID-10

Hardware Module: AEHC

Applicable SW: 25R3, 26R1, 26R2

Waiting Period: 120 Minutes (2 Hours)

System Status: No Connection to Unit at AEHC

Recovery Steps for AEHC:

Step 1 for AEHC: Collect Pre and Post Snapshot for AEHC.

Step 2 for AEHC: Engage R&D; ASAP (No recovery before engaging R&D; for AEHC).

Step 3 for AEHC: Wait up to 2 hours for self-recovery (No TSH required within waiting period).

Step 4 for AEHC: Check if RU unit is reachable/pinging, then collect RU logs for AEHC.

Important Transition Note for this Module:

During troubleshooting of FID-10 for this module, if FID-10 turns into FID-1850 / FID-23 / FID-2934 / FID-2935 / FID-2942, it means connectivity to RU is established. Action: Collect RU logs and snapshot at this point for R&D; investigation.

Keywords for retrieval: FID-10, AEHC, RU reachable, RU logs, R&D; engagement, 120 Minutes, FID-1850, FID-23, FID-2934, FID-2935, FID-2942

--- END OF CHUNK FOR MODULE AEHC ---