

NORTHSTAR INSURANCE LIMITED

PLUMBING INSPECTION REPORT

Claim Reference: CLM-1001

Date of Inspection: 14 March 2026

Property: 42 Gulberg Avenue, Lahore

Inspector: M. Farooq, Licensed Plumber

FINDINGS

A copper supply pipe running beneath the kitchen floor has failed at a soldered joint. The failure is a clean circumferential rupture. There is no corrosion, scaling or staining around the joint.

In my opinion the pipe ruptured suddenly. Water escaped at mains pressure and flooded the kitchen and hallway within a short period. The occupier reports that the floor was dry the previous evening.

There is no evidence of long standing damp. Skirting boards away from the immediate area remain sound and dry.

CONCLUSION

The escape of water was sudden and accidental. Estimated cost of repair and making good is PKR 184,000.