

NORTHSTAR INSURANCE LIMITED

PLUMBING INSPECTION REPORT

Claim Reference: CLM 1000

Date of Inspection: 22 March 2025

WORKING

The supply pipe beneath the kitchen has failed. Water has leaked from the pipe, running and into the adjacent room. The water has caused damage to the floor and the wall. The water has also caused damage to the ceiling.

CONCLUSION

Further investigation is required to determine the cause of failure and the extent of damage. The cause of failure can be identified with confidence by the inspector.