

NORTHSTAR INSURANCE LIMITED

PLUMBING INSPECTION REPORT

Claim Reference: CLM 1000

Date of Inspection: 22 March 2025

WORKING

The supply pipe beneath the kitchen has failed. Water has leaked from the pipe, causing damage to the adjacent wall and floor. The service is being replaced and the gas leak checked throughout the rest of the house.

CONCLUSION

Further investigation is required to determine the cause of failure and the associated with conditions by the inspector.