

# Skywire® LTE CAT M1 NL-SW-LTE-QBG95-B Product Change Notification

NimbeLink Corp
Updated: April 2022



© NimbeLink Corp. 2022. All rights reserved.

NimbeLink Corp. provides this documentation in support of its products for the internal use of its current and prospective customers. The publication of this document does not create any other right or license in any party to use any content contained in or referred to in this document and any modification or redistribution of this document is not permitted.

While efforts are made to ensure accuracy, typographical and other errors may exist in this document. NimbeLink reserves the right to modify or discontinue its products and to modify this and any other product documentation at any time.

All NimbeLink products are sold subject to its published Terms and Conditions, subject to any separate terms agreed with its customers. No warranty of any type is extended by publication of this documentation, including, but not limited to, implied warranties of merchantability, fitness for a particular purpose and non-infringement.

NimbeLink and Skywire are registered trademarks of NimbeLink Corp. All trademarks, service marks and similar designations referenced in this document are the property of their respective owners.

### **Table of Contents**

Tal	Table of Contents	
1.	Introduction	3
2.	Migration Overview	3
3.	Contact	4
4.	Document Version Information	5

#### 1. Introduction

Over their lifetime, Skywire® modems may incur several hardware and firmware updates provided by cellular module manufacturers. These updates improve communication, fix bugs, and add features to the module and resulting modem functionality. NimbeLink will stay current with the latest supplier releases. It is recommended that customers also test and apply these new versions when they become available.

The NL-SW-LTE-QBG95-B Skywire modem, which has firmware version BG95M3LAR02A03\_01.009.01.009, is being replaced by the NL-SW-LTE-QBG95-C Skywire modem which includes both hardware and firmware updates.

The hardware update adds suppliers to Quectel's approved vendors list for subcomponents within the cellular module. These components Do not materialy impact the functionality of the module or the resulting Skywire Modem.

The new firmware version is: BG95M3LAR02A03\_01.014.01.014. This new firmware is aligned to all future version of the NL-SW-Lte-QBG95-C modems

NimbeLink recommends that customers begin testing and plan to transition to the NL-SW-LTE-QBG95-C part number. The NL-SW-LTE-QBG95-B will still be available on a limited basis. The NL-SW-LTE-QBG95-C is now the recommended modem for long-term production.

#### 2. Migration Overview

All new orders should use part number NL-SW-LTE-QBG95-C which is specific to the newest version of firmware, BG95M3LAR02A03\_01.014.01.014.

Updated documentation for firmware version BG95M3LAR02A03\_01.014.01.014 can be found on the product page here:

https://nimbelink.com/products/quectel-bg95-4g-lte-m-embedded-modem/

Customers with existing NL-SW-LTE-QBG95 and NL-SW-LTE-QBG95-B parts can upgrade to the NL-SW-LTE-QBG95-C firmware using the firmware update procedure outlined in the Firmware Update application notes here:

NL-SW-LTE-QBG95 Windows Firmware Update Guide

NL-SW-LTE-QBG95 FOTA Guide

Customers can use the new FW on the older HW versions of the BG95.

All New orders should be placed on the NL-SW-LTE-QBG95-C for deliveries starting in H2 of 2022.

#### 3. Contact

For further information please contact NimbeLink at:

sales@nimbelink.com

## 4. Document Version Information

Revision	Description	Date
1	- Initial document release.	03/29/2022
2	- Fixed formatting errors.	4/15/2022
3	<ul> <li>Updated information regarding flashing new firmware onto old hardware revisions. New firmware can be updated onto old hardware.</li> </ul>	4/18/2022