
## B.T.W. Dive Service 2828 Cochran St #121 Simi Vallley CA,93065





info@btwdive.com www.btwdive.com



Robert Murray Vcd23 2111 Calaveras Drive Camarillo, CA 93010 \* Hull Cleaning \* Corrosion Control

\* Problem Recognition

lı	nvoice Date	Payment Enclosed	Invoice #
(	06/30/2014	\$	36493

Please detach here & return with payment.

Date	Invoice#	Terms	Account#
06/30/2014	36493	Due On Receipt	RMUR01

#	Description	List Price	Total	
	Location Vessel Name Paint Condition Select Location V/H Blindfaith Poor (needs Painting) Vim B44			
	Zinc/Anode Change and Replacement interval shown in Months 2014-06-01 Discount 10.00%			
	(Zinc Replaced on 06/01/2014)			
	1-3/4`` Shaft Collar Zinc & Installation(Prior Replacement 11/22/2013=7months)		38.15	34.34
	1-3/4` Shaft Collar Zinc & Installation(Prior Replacement 11/22/2013=7months)  Trim Tabs Clam. Medium Full Zinc + Installation - :  Trim Tabs Clam. Medium Full Zinc + Installation - :  New 2014 Promotion - Refer a friend - \$1.00 / foot credit to your account. You may	Total Credit Ba	38.15 31.40 31.40	34.34 28.26 28.26
			alance ling Balance	0.00 0.00
	Discourse with the growth rate from the device clear anywords. Deschadule also with	Balance Due		125.20
	Please monitor the growth rate from the day we clean, onwards. Reschedule cleaning before planned trips or hauling. Zinc replacement is usually billed the following month.	We A	We Accept Major Credit Cards	
	Your invoice is attached. Total Balance is due on receipt. Major credit cards accepted at www.btwdive.com/online-pay.html			Business