## B.T.W. Dive Service 2828 Cochran St #121 Simi Vallley CA,93065



info@btwdive.com www.btwdive.com



\* Hull Cleaning

- \* Corrosion Control
- \* Problem Recognition

Jeff Hyland 250 North Canon Dr. Beverly Hills,CA 90210

| Invoice Date | Payment Enclosed | Invoice # |
|--------------|------------------|-----------|
| 07/01/2014   | \$               | 36262     |

Please detach here & return with payment.

| Date       | Invoice# | Terms          | Account# |
|------------|----------|----------------|----------|
| 07/01/2014 | 36262    | Due On Receipt | JHYA01   |

|   |  | Description  |                          | List Price   | Total    |
|---|--|--|--------------------------|--------------|----------|
| Location  | Vessel Name                                    | Paint Condition  |                          |              |          |
| Basin F 2520  | Mdr Augusea                                    | Good (good Paint)  |                          |              |          |
| Hull Clean  |  | 05/21/2014   |                          |              |          |
| _   | Dates(April 1st-Oct 31s<br>Summer Hard Growth) | tt): 2 Week Half Clean: Metal/hardware/intakes/ Wat  | erline                   | 49.00        | 49.00    |
| Hull Clean  |  | 05/21/2014   |                          |              |          |
| Summer Cleaning   | Dates(April 1st-Oct 31s                        | t): Cleaning Of Dinghy   |                          | 10.00        | 10.00    |
| Zinc/Anode Char   | ge and Replacement i                           | nterval shown in Months 05/21/2014   |                          |              |          |
|   |  | (Zinc Replaced on 05/21/2014)  |                          |              |          |
| 2`` Limited Cleara  | nce Zinc & Installation                        | (Prior Replacement 06/08/2013=12months   | )                        | 38.42        | 38.42    |
| 2`` Limited Clearance Zinc & Installation(Prior Replacement 06/08/2013=12months)  |  |  | 38.42                    | 38.42        |          |
| Large Taiwan Plat   | e Zinc + Installation                          | (Prior Replacement 11/26/2013=6months)   |                          | 69.75        | 69.75    |
| Large Taiwan Plat   | e Zinc + Installation                          | (Prior Replacement 11/26/2013=6months)   |                          | 69.75        | 69.75    |
| Outboard Mounted 06/05/2011=37mc  |  | + Installation(Prior Replacement   |                          | 34.99        | 34.99    |
| 50Mm Shaft Colla  | ics - Center 1 Of 3 Is Ina                     | active. Check Bonding. Large Ref Zinc At The Bow Thrus They Were Corroding. 1 Trim Tab Removed To Stop r Side 120310 - 4 |                          |              |          |
| New 2014 Promotion - Refer a friend - \$1.00 / foot credit to your account. You may never have to pay for service again! Let us know ASAP so we can issue your credit  Credit Bal             |  |  |                          | 310.33       |          |
|   |  |  | lance                    | 0.00         |          |
| certificate. Outstand   |  | ing Balance  | 59.00                    |              |          |
| Please monitor the growth rate from the day we clean, onwards. Reschedule cleaning before planned trips or hauling. Zinc replacement is usually billed the following month.  Balance I  We Ad |  |  | Due                      | 369.3        |          |
|   |  |  | ccept Major Credit Cards |              |          |
|   | attached. Total Balanc<br>om/online-pay.html   | e is due on receipt. Major credit cards accepted at  | Thank \                  | You For Your | Business |