B.T.W. Dive Service 2828 Cochran St #121 Simi Vallley CA,93065





info@btwdive.com www.btwdive.com



Bill Durrell Vcd06 28832 Oak Spring Canyon Road Canyon Country,CA 91387 * Hull Cleaning * Corrosion Control

* Problem Recognition

Invoice Date	Payment Enclosed	Invoice #
07/01/2014	\$	36356

Please detach here & return with payment.

07/01/2014 36356 Due On Receipt BDUR01	Date	Invoice#	Terms	Account#
	07/01/2014	36356	Due On Receipt	BDUR01

#	Description		List Price	Total	
	Location Vessel Name Paint Condition Select Location V/H Melody Ann Excellent (new Paint) Vwm2 F11				
	Zinc/Anode Change and Replacement interval shown in Months 05/19/2014				
	(Zinc Replaced on 05/19/2014)				
	Sail Drive Yanmar (#196440-02660) 2 Part Zinc + Installation:	89.50	89.50		
	Sail Drive Yanmar (#196440-02660) 2 Part Zinc + Installation:	89.50	89.50		
Г	New 2014 Promotion - Refer a friend - \$1.00 / foot credit to your account. You may	Total		179.00	
	never have to pay for service again! Let us know ASAP so we can issue your credit	Credit Balance		0.00	
	certificate.		Outstanding Balance		
	Please monitor the growth rate from the day we clean, onwards. Reschedule cleaning	Balance Due 179.0		179.00	
	before planned trips or hauling. Zinc replacement is usually billed the following month.		We Accept Major Credit Cards		
	Your invoice is attached. Total Balance is due on receipt. Major credit cards accepted at www.btwdive.com/online-pay.html	Thank	ank You For Your Business		