
B.T.W. Dive Service 2828 Cochran St #121 Simi Vallley CA,93065



.

info@btwdive.com www.btwdive.com



Tony Smith 1007 N. Federal Highway Unit 164 Fort Lauderdale,FL 33304

- * Hull Cleaning
- * Corrosion Control
- * Problem Recognition

Invoice Date	Payment Enclosed	Invoice #
07/01/2014	\$	36276

Please detach here & return with payment.

Date	Invoice#	Terms	Account#
07/01/2014	36276	Due On Receipt	TSMI01

#	Description				List Price	Total
Ĭ	Location Vessel Name	Paint Co				
	Basin C 1907 Mdr Destiny 1	Excellen	t (new Paint)			
	Hull Clean					
						25.00
	Zinc/Anode Change and Replacement i	nterval shown in Months	05/21/2014			
	1-3/8`` Shaft Collar Zinc & Installation					29.35
	1-3/8`` Shaft Collar Zinc & Installation					29.35
	1-3/8`` Shaft Collar Zinc & Installation				29.35	29.35
	1-3/8`` Shaft Collar Zinc & Installation				29.35	29.35
	6 X12`` X 3/8 Slots - Plate Zinc + Installation(Prior Replacement 11/26/2013=6months)				69.85	69.85
	Comments Section: Rapid Burning Of Shaft Zincs					
	never to pay for service again! Let us know ASAP so we can issue your credit		Total		212.25	
			Credit Balance		0.00	
			Outstanding Balance		0.00	
	Discourage the growth rate from the day we also a covered. Deschadule also rive			Balance Due		212.25
	Please monitor the growth rate from the day we clean, onwards. Reschedule cleaning before planned trips or hauling. Zinc replacement is usually billed the following month.			We Accept Major Credit Cards		
	Your invoice is attached. Total Balance www.btwdive.com/online-pay.html	e is due on receipt. Major cre	dit cards accepted at	Thank You For Your Business		