
B.T.W. Dive Service 2828 Cochran St #121 Simi Vallley CA,93065



iı

info@btwdive.com www.btwdive.com



* Hull Cleaning

- * Corrosion Control
- * Problem Recognition

Robert Missirian 13029 A Victory Blvd. #525 N. Hollywood, CA 91606

Invoice Da	ate Payr	ment Enclosed	Invoice #
06/30/20	14 \$		35626

Please detach here & return with payment.

Date	Invoice#	Terms	Account#
06/30/2014	35626	Due On Receipt	RMIS01

#	Description					List Price	Total	
	Location Basin A 1112							
	Zinc/Anode Chang	e and Replacement in						
	60mm Shaft Collar 2	11/23/2013=4months)		65.17	65.17			
	60mm Shaft Collar 2	Zinc + Installation:	(Prior Replacement	11/23/2013=4months)		65.17	65.17	
	Trim Tab 4x6 Plate 2	Zinc + Installation	(Prior Replacement	10/06/2013=6months)		40.42	40.42	
	Trim Tab 4x6 Plate 2	Zinc + Installation	(Prior Replacement	10/06/2013=6months)		40.42	40.42	
	Comments Section Small Amount Of Wi		Light Fitting And Jelly Emitti	ing From The Glass Seal	(11/01/09)			
	never have to pay for service again! Let us know ASAP so we can issue your credit Credit to your account. For may Credit to your a					Total		
						Credit Balance		
	certificate.				Outstanding Balance		0.00	
	Please monitor the growth rate from the day we clean, onwards. Reschedule cleaning before planned trips or hauling. Zinc replacement is usually billed the following month. Your invoice is attached. Total Balance is due on receipt. Major credit cards accepted at					Balance Due		
						We Accept Major Credit Cards		
						Thank You For Your Business		