B.T.W. Dive Service

2828 Cochran St #121 Simi Vallley CA,93065

> Raymond J Fisher 13080 Mindanao Way #98 Marina Del Rey,CA 90292



- * Hull Cleaning
- * Zinc/Anode Replacement
- * Recoveries
- * Corrosion Control
- * Underwater Photography
- * Surveys

_	Invoiced Date	Payment Enclosed	Invoice #	
	2014-05-02	\$	35617	

Please detach here & return with payment.

Date	Invoice#	Terms	Account#
2014-05-02	35617	Due On Receipt	RFIS01

#		List Price	Total		
	Location	Vessel Name	Paint Condition		
	Basin F 400	Mdr Texas Dinghy - Thriller	Good(Healthy Paint)		
	Zinc/Anode Change and Repla	acement interval shown in Months	2014-03-23		
	Rudder Large Ref Cell Zinc + Ins	41.78	41.78		
	Rudder Large Ref Cell Zinc + Ins	41.78	41.78		
	Large Taiwan Plate Zinc + Instal	69.75	69.75		
	Large Taiwan Plate Zinc + Instal	69.75	69.75		
	TRIM TABS - EXTRA LARGE C	39.00	39.00		
	TRIM TABS - EXTRA LARGE C	39.00	39.00		
	3`` Shaft Collar Zinc & Installatio	on		84.75	84.75
	3`` Shaft Collar Zinc & Installatio	84.75	84.75		
	2`` LC Trim Tab Ram Zinc & Inst	38.42	38.42		
	2`` LC Trim Tab Ram Zinc & Inst	tallation(Prior Replacement 201	3-01-05=15months)	38.42	38.42
	Comments Section: Trim Ram Zinc - Trim Tab Zinc A	And Rudder Zinc All Very Low To 0% - 01.	/19/12.		
	N 0044B " B (Total	547.40
	New 2014 Promotion - Refer a fr again! Let us know ASAP so we	Credit Balance	0.00		
	again! Let us know ASAP so we	can issue your credit certificate.		Outstanding Balance	98.00
	Please monitor the growth rate for	ule cleaning before planned trips or hauling.	Balance Due	645.40	
	Zinc replacement is usually billed the following month.			We Accept Major Credit Cards	
	Your invoice is attached. Total B pay.html	Thank your for your business			