
## B.T.W. Dive Service 2828 Cochran St #121 Simi Vallley CA,93065



(P)310.918.5631





\* Hull Cleaning

- \* Corrosion Control
- \* Problem Recognition

Jay Becker 3100 Donald Douglas Loop N. Santa Monica,CA 90405

Invoice Date	Payment Enclosed	Invoice #	
07/01/2014	\$	36269	

Please detach here & return with payment.

Date	Invoice#	Terms	Account#
07/01/2014	36269	Due On Receipt	JBEC01

#	Description			List Price	Total	
		nt Condition (think About Painting)				
	Hull Clean				20.20	
	Zinc/Anode Change and Replacement interval shown in Month (Zinc Replaced o	Anode Change and Replacement interval shown in Months  (Zinc Replaced on 05/21/2014)				
	Bow Thruster - Imtra Side Power: 201180: Zinc + Installation Bow Thruster - Imtra Side Power: 201180: Zinc + Installation	46.81 46.81	46.81 46.81			
	Rudder - Taiwan Plate Zinc + Installation(Prior Replacement 06/23/2013=12months)				45.42	
	Rudder - Taiwan Plate Zinc + Installation(Prior Replacement 06/23/2013=12months)				45.42	
	<b>Comments Section:</b> New Swim Platform Anodes Are Not Submerged In The Water Eno Mostly Out Of The Water.					
	New 2014 Promotion - Refer a friend - \$1.00 / foot credit to your account. You may		Total		204.66	
	never have to pay for service again! Let us know ASAP so we can issue your credit Cred			Credit Balance		
	certificate.		Outstanding Balance		0.00	
	Please monitor the growth rate from the day we clean, onward before planned trips or hauling. Zinc replacement is usually bit	_	Balance Due 204.66  We Accept Major Credit Cards		204.66 dit Cards	
	Your invoice is attached. Total Balance is due on receipt. Majwww.btwdive.com/online-pay.html	or credit cards accepted at	Thank \	Business		