B.T.W. Dive Service 2828 Cochran St #121 Simi Vallley CA,93065

Below The Waterline Diving Service

(P)310.918.5631



info@btwdive.com www.btwdive.com



- * Hull Cleaning
- * Corrosion Control
- * Problem Recognition

Michael Chang

,

Invoice Date	Payment Enclosed	Invoice #
07/01/2014	\$	36300

Please detach here & return with payment.

Г	Date	Invoice#	Terms	Account#
	07/01/2014	36300	Due On Receipt	MCHA01

#		Description				List Price	Total	
	Location Basin C 2107	Vessel Name Mdr No Ties	Paint Condi	tion				
	Zinc/Anode Change and Replacement interval shown in Months 05/21/2014							
	(Zinc Replaced on 05/21/2014)							
	1-1/4`` Shaft Collar + Installation					24.85	24.85	
	1-1/4`` Shaft Collar + Installation					24.85	24.85	
	6 X12`` X 3/8 Slots	(12`` X 3/8 Slots - Plate Zinc + Installation m Tabs - Clam. Small Full Zinc & Installation				69.85	69.85	
	Trim Tabs - Clam.					25.89	25.89	
	Trim Tabs - Clam. Small Full Zinc & Installation					25.89	25.89	
	New 2014 Promotion - Refer a friend - \$1.00 / foot credit to your account. You may						171.33	
	never have to pay for service again! Let us know ASAP so we can issue your credit certificate.				Credit Balance		0.00	
					Outstanding Balance		0.00	
	Please monitor the growth rate from the day we clean, onwards. Reschedule cleaning				Balance Due		171.33	
	before planned trips or hauling. Zinc replacement is usually billed the following month.			We Accept Major Credit Cards				
		attached. Total Balance is dom/online-pay.html	ce is due on receipt. Major credit cards accepted at			Thank You For Your Business		