Call instructions

ACALL (Absolute call)
LCALL (Long call)



DJNZ R0, back
↳ main 001 – FF
main 255 counts
to count 266 start from 00h
∴ 00h → FF ← 00
∴ total 256 counts.

* When call is then
PC contain is ~~there~~ copied to stack
and then sub routine is executed and the
return statement ~~###~~ load the PC with
stack value.

LEFO Fation is helpfull in case of nested loop.

* All ISR are subroutines but all subroutines can't be ISR

0 1 0 1
1 0 1 0





6) * Write a program to toggel all the bits of port 1 by sending the values 55 H and AAH continuously put a time delay b/w each values send to point.

```
MOV  P1, 55

HERE: XRL  P1, #FFh
      SJMP HERE
back: MOV  R0, #20h
      DJNZ R0, back
      DJNZ 2 HERE


MOV  P1, #55h
* MOV  a, #FFh
  XRL  P1, a
```

```
ORG 00H
back : MOV P1, #55h
       LCALL DELAY
       MOV P1, #0AAh
       LCALL DELAY
       SJMP BACK

Delay : MOV R1, #255
Here : DJNZ R1, Here
       RET
       END
```

Assembler directive → for the assembler to understand

EQU directive

```
Count EQU 25
MOV R0, #Count        R0 = 25
ORG 500H → from where to start decoding
```

500H Data1 : DB 28d

501H Data 2 : DB 11011101B

502H Data 0 : DB 20h

503H Data 4 : DB "3132"

504H Data 5 : DB 'I' → not 16 bit

31 → 1 ASCII

32 → 2

∴ 12 8 bits.

505H Data 6 : DB "All the best".

506H 507H 508H space (509H)

8051 ALP Factorial of a no (upto 8T)

```
MOV R0, #25h

    MOV A, R0
    Dec R0
back: MOV b, R0
back: MUL AB
    MOV @R1, A
    DEC R0
    DJNZ R0, back
    MOV 26h, A
```

Fibonacci series till 12

```
MOV 12H, #1
MOV 13H, #1
MOV R1, #0Ah
MOV A, 12H
back: ADD A, 13h
MOV 13h, A
MOV A, R0
DJNZ R0, back
```

```
MOV R0, #20H
MOV R1, #10
Back: MOV A, @R0
INC R0
ADD A, @R0
INC R0
MOV @R0, A
DEC R0
DJNZ R1, Back
```

Date
Page

* ADD two 32 bit number

12, 13, 14, 15 | 16, 17, 18, 19 | 1A, 1B, 1C, 1D

```
    MOV R0, 04h
    MOV R1, #12h
    MOV R2, #16h
    MOV R3, #1Ah
    CLR C
back: MOV A, @R1
    ADDC A, @R2
    MOV @R3, A
    INC R1
    INC R2
    INC R3
    DJNZ R0, back
```

* WAP to find the address of 1st internal ram location b/w 20h to 80h which contains consecutive number.

```
    MOV R1, #20h
    MOV R0, #41h
back: MOV A, @R1
    INC R1
    SUBB A, R1
    CJNE R0, #00, last
last: DJNZ R0, back
    MOV A, R1
    MOV R2, A
    Dec R1
    MOV A, R1
    MOV R3, A
```

MOV R0, A
CJNE R0, #00, last

xch a,r1



Date
Page

ORG 00h ⇐ LCM of two no

```
mov r0, 20h
mov r1, 21h
mov r2, #01h
mov a, r0
mov b, r1
subb a, r1
jc next
back: mov a, r0
mov b, r2
mul ab
mov r3, a
mov b, r1
div ab
inc r2
xch a, b
cjne a, #00h, back
sjmp last
next: mov a, r0
xch a, r1
mov r0, a
sjmp back
last: mov 22h, r3
sjmp $
END
```

c) To check nibble wise pallindrom

```
MOV R2,#00h
MOV R3,#00h
MOV a,25h
MOV r0,a
SWAP a
MOV r1,a
CLR
MOV a,r0
SUBB a,r1
CJNE a,#00,NP
INC R2
SJMP NEXT
NP: INC R3
NEXT: SJMP $
END
```

d) Cube of no

```
MOV a,#0FFh
MOV b,#0FFh
MOV r0,#0FFh
MUL AB
MOV R1,B
MOV B,R0
MUL AB
MOV 50H,A
MOV R5,50h
MOV R2,B
```

{ a = FF, b = FF }
r = FF

R1 = MB
B = FF

FF x FF
FE01
B A

```
MOV A, R1
MOV B, R0
MUL AB
ADD A, R2
JNC skip
MOV R3, #004
INC R3
SKIP: MOV 51H, A
MOV R6, 51H
MOV A, B
ADD A, R3
MOV 52H, A
MOV R7, 52H
```

F F
F F

8) To check bitwise palindrom

```
MOV A, #1Fh
```

1	0	0	0	0	0	0	1

(4) Use of a number using push and pop

```
MOV  R0, #20h
MOV  A, @R0
MOV  R1, A
MOV  B, A
INC  R0
MOV  A, @R0
MUL  AB
PUSH 0F0H
MOV  B, A
MOV  A, R1
MUL  AB
INC  R0
MOV  @R0, A
MOV  A, B
MOV  R2, A
POP  0F0H
MOV  A, R1
MUL  AB
ADD  A, R2
INC  R0
MOV  @R0, A
MOV  A, B
ADDC A, #00h
INC  R0
MOV  @R0, A
MOV  A, B
ADDC A, #00h
INC  R0
MOV  @R0, A
```

MOV SP, #30h

Page

a) To implement DAA operation without using DAA.

b) To multiply 16 bits number.

c) To check given character is a character wise palindrom. (using DB)

d) To find HCF of a number.

delay

Software delay program

12 clock pulses are required to execute 1 instruction



$$T = \frac{\text{Osc freq}}{12}$$

a) Find the time period required to execute 1 machine cycle in each case.

(1) 11.0592 MHz $\Rightarrow$ $\left(\frac{11.0592}{12}\right)^{-1} = (0.9216)^{-1}$

$= 1.085\ \mu s$

(2) 16 MHz $\Rightarrow$ $0.75\ \mu s$

(3) 20 MHz $\Rightarrow$ $0.6\ \mu s$

(4) 22 MHz $\Rightarrow$ $0.54\ \mu s$

b) Find the size of the delay in the following program if crystal freq is 11.0592 MHz

```
        MOV  A, #55h
Again:  MOV  P1, A
        ACALL Delay
```

Date
Page

CPL A
SJMP AGAIN

Delay : MOV R3, #200 — 1
Here : DJNZ R3, Here — 2 × 200
RET — 2

} × 1.085 μs

= 437 μs

loop delay

Q) Find the delay program for the following sub program (not give f = 11.0592)

MOV R3, #250 — 1
NOP — 1 × 250
NOP — 1 × 250
NOP — 1 × 250
NOP — 1 × 250
~~NOP — 1 × 250~~
Here : DJNZ R3, Here — 2 × 250
RET — 2

} × 1.085 μs

= 1630.75 μs

Q) If crystal freq is 92 MHz generate a delay of 5 ms

(1) $5 \times 10^{-3} = 0.54 \times n \times 10^{-6}$

$n = \frac{5 \times 10^{-3}}{0.54 \times 10^{-6}}$

(2) $n = \frac{5 \times 10^{-3}}{0.54 \times 10^{-6}}$

= 9259 cycles

3) DJNZ - 2MC $\quad \frac{9259}{2} = 4630$ cycle

4) $\frac{4630}{258} = 18$ count

$\underbrace{(256}_{R1} \times \underbrace{18)}_{R2} = 4630$

MOV R2, #18 — 1 ×
Here1: MOV R1, #255 — 1 × 18
Here: DJNZ R1, Here — 2 × 256 × 18
DJNZ R2, Here 1 — 2 × 18
} × 0.54

This is extra

= 5.006 ms ≈ 5ms

check this way

Q) WAP to toggel all the bits of port 1 every 200 ms. Crystal freq 11.0592

$200 \times 10^{-3} = n \times 1.085 \times 10^{-6}$

$n = \frac{200 \times 10^3}{1.085}$

$= 184331.7$

$= 184332$ cycles

DJNZ - 2 → $\frac{184332}{2} =$ 92166 cycle

$\frac{92166}{256} = \frac{360}{256} = 1.4$ $\quad \frac{360}{180} = 2$

256 × 360 $\quad$ 38 256 ✗ $\quad$ divide by 180

256 × 180 × 2

DELAY: MOV R3, #[illegible] ×1 ×[illegible]

Here 2: MOV R2, #[illegible]180 ×1 ×[illegible]/180 2

Here 1: MOV DJNZ R1, #255 - 1 ×[illegible] ×255/180

Here: DJNZ R1, Here - 2 ×256×255

DJNZ R2, Here 1 - 2 ×[illegible]/180

DJNZ R3, Here 2 - 2 ×1×2

RET — 2

≈ 20.1 ms

AGAIN: MOV A, #55h

MOV P1, A

ACALL DELAY

CPL A

SJMP AGAIN

Q) WAP to generate a square wave of frequency 1 KHz assume crystal frequency of is 11.092 MHz

MHz

⇒ TON = TOFF Tim = 1 ms sq wave for 1 cycle

TON = TOFF = 0.5 ms

$0.5 \times 10^{-3} = n \times 1.085 \times 10^{-6}$

$n = 460.8$

$= 460$ cycles

DJNZ → $\frac{460}{2} = 230$ cycles

delay: MOV R0, #230

Here: DJNZ R0, Here

RET

* RESET → is non maskable

other are maskable

Date
Page

5 interrupts — Vector address

- $\overline{INT0}$ [ext H/w interrupts] 0003H
- $\overline{INT1}$ [ext H/w interrupts] 0013H
- T0 [Timer 0 interrupt] [TF0] 000BH
- T1 [Timer 1 interrupt] [TF1] 001BH
- Serial com^n [TI & RI flags] 0023H
  - TI — Transmission
  - RI — Recieve
  - if 1 then 1 byte of data have been transferred
- RESET 0000H

(global interrupts)

this is also considered some time.

When we press reset the BIOS program should run.

Reset → 0000H LJMP L1 L1: BIOS Prgm.

1 byte + 2 byte

total 3 byte is required.

* IE reg [bit addressable reg] — interrupt enable

EA	–	ET2	ES	ET1	EX1	ET0	EX0

EA = 0 – disable all interrupts (all interrupt is masked)

EA = 1 – enable interrupts and are serviced if particular interrupt bit is 1

a) So the instru to do the following

a) enable serial interrup
b) " To. "
c) " Ex1

a) SetB IE.4

b) SetB IE.1

c) SetB IE.2

d) clr IE.1

e) clr IE.7

d) Disable or mask Tiner 0 interru
e) to disable all the interrupt

Mann

for 1st three (a,b,c) → MOV IE, #10010110B

96H

Date
Page

IP Reg (Interrupt priority Reg
bit addressable)

-	-	PT2	PS	PT1	PX1	PT0	PX0

lowest ← → Highest

default

If PX1 is set 1 in IP Reg then 1st PX1 is serviced after that the priority order is followed.

(1) Discuss what happens if interrupt INT0, TF0, ~~TF0~~, INT1 are activated ~~at~~

INT0
TF0
INT1

a) To assign highest priority of Timer 1 interrupt TF1. discuss what happen if INT0 & INT1 & TF0 are activated at the same time.

a) SETB IP.3 or MOV IP, #08h

b) TF1
INT0
TF0
INT1

a) Discuss the seq

MOV IP, #0000 1100 B