

Test_Facility_Robot_UK



Executive Summary

BeaconMedaes Service Technician Robot_UK Tester tested the Medical Gas Pipeline System indicated by this report in accordance with HTM - Part B section (Maintenance) and/or accordance with the facilities own specification (where requested) and other applicable standards or agencies. The tests performed on this system were found to be within test specifications unless otherwise noted. The results, dates and locations of the tests performed and specific data on each test can be found on the Test Summary pages.

The testing of this system may include all or part of the tests offered by BeaconMedaes. Only the tests indicated by the summary and data pages were performed on the dates indicated. The results of the tests reported represent BeaconMedaes findings on the dates and locations indicated by the report forms only. System components include:

1. Air System : 1 pcs

Inspection Report

Test Date:

Air System: Oil Lub Screw: Medical: 7.5 Hp / 5.5 KW: Triplex: BeaconMedaes:

: mA

HTM - AC GA5 dMED , s/n MNL_

Location: Building 1 : Floor 1

General

Data Point	Result
Plant Room Condition	Pass
Plant access	Pass
Plant fixing and bonding	Pass
Compressor manufacturer	Atlas Copco
Dryer manufacturer	BeaconMedaes
Relevant staff advised of system test and likely alarms	Pass
ERM is online and able to supply air to the MGPS	Pass
Safety valve(s) in date	Pass
Receiver(s) condition is good	Pass
Dryer condition is good and operates correctly	Pass
Dryer line pressure (bar)	0. 0
Gauge(s) operate correctly	Pass
Condition of electrical components are acceptable	Pass
Isolate each compressor and check running conditions are acceptable	Pass
Compressor(s) are free from oil leaks	Pass
Alarms and indications operate correctly	Pass
Plant run hours	0. 0
Pressure switch fault level (bar)	0. 0
Backup pressure switch operates correctly	Pass
Filters are clean and in date	Pass
Filter auto drains are operating correctly	Pass
Equipment status is online	Pass
Atmospheric dew point level	0. 0

1 Compressor 1

Data Point	Result
Compressor run hours	0. 0
Cut in pressure (bar)	0. 0
Cut out pressure (bar)	0. 0
Running current loaded (A)	0. 0
Running current unloaded (A)	0. 0
Oil level check	Pass
Oil temperature	0. 0

2 Compressor 2

Data Point	Result
Compressor run hours	0. 0
Cut in pressure (bar)	0. 0
Cut out pressure (bar)	0. 0
Running current loaded (A)	0. 0
Running current unloaded (A)	0. 0

Oil level check	Pass
Oil temperature	0. 0

.3 Compressor 3

Data Point	Result
Compressor run hours	0. 0
Cut in pressure (bar)	0. 0
Cut out pressure (bar)	0. 0
Running current loaded (A)	0. 0
Running current unloaded (A)	0. 0
Oil level check	Pass
Oil temperature	0. 0

Dynamic Risk Assessment



Data Point	Result
Risk Assessment	I am OK to commence works



Device Notes

Device Notes



Image	Asset	Comments
	Air System: Oil Lub Screw: Medical: 7.5 Hp / 5.5 KW: Triplex: BeaconMedaes: : mAIR-GTF4- 2 HTM - AC GA5 dMED , s/n MNL_	Image Show_2.png uploaded
	Air System: Oil Lub Screw: Medical: 7.5 Hp / 5.5 KW: Triplex: BeaconMedaes: : mAIR-GTF4- 2 HTM - AC GA5 dMED , s/n MNL_	Image Show_1.png uploaded

Authorization to carry out work with/without an order number.

Notes: Customer will agree to supply Test Automatic UK with a valid order number or payment for non-account holders for the actual time spend, traveling and parts used during the breakdown intervention by next working day.

Customer Confirmation

Service Engineer Confirmation

Signed by Robot_UK
(Being duly authorized to sign on behalf of the customer)

Signed by Robot UK Tester



Test_Facility_Robot_UK

