BUDGE BUDGE INSTITUTE OF TECHNOLOGY



Name: - Sudip Basu

Stream:- Computer Science and

Technology (CST)

Year:- 2nd

Sem:- 4th

Subject:- Computer Network Lab

Roll No:- 16

Regestration No:- D181902025

- Name Of the Equipment:- Prepare and test using CAT5e untwisted pair cable and crimping tool.
- Tools Required:- 1) RJ45 Connector,
 2)Crimping Tool,
 3)Cat 5e UTP Cable,

4)Scissor.



Procedure:-

Step 1:= Start by stripping off about two inches of plastic jacket off the both ends of the cable,

Step 2:= Spread the wires appart but be sure to hold on to the base of the jacket with your other hand.


Step 3:= Untwist the wires and make it as Straight as possible and cut the head of the wires equally wish the blade Section of crimping tool.

Step 4:= Arrange the wire according to the colour combination and stuf the wire, into the connector, making sure the wires stay line up and wire should reach the evtreme end of the connector.

Step 5:= Now insert the cable into the crimping tool and crimped it .

Step 6:= Use a cable tester to check for proper connection.

 Diagram for combination of and Cross over



colour Straight cable.

