

## Janis Fridge Simulation Updates Sep 27, Fri


- Summary
  - o Physically measured (Roughly) the fridge
  - o The fridge has been debugged, with several possibly necessary details to add
  - New 4K shield and IVC has been updated
- · Physical measurement
  - Just a profile
  - o It tells us that there are no OBVIOUS difference between reality and drawings...

0







- Debugging
  - Possible fatal problems
    - ► The only found dimension error












► Slots



- Minor problems
  - · Close screws with different material
  - Cables and lots of complex structures








Model them?

• Should the sample chamber be full?



- Questions
  - Typical cross section?
  - O Another bug?

G4double can\_77k\_outer\_posZ = (can\_vacuum\_outer\_Dz - can\_77k\_outer\_Dz)/2.0;

