

Report: Ipswich - Furniture

Suburb / Node	Key Risk Category	Compliance Checklist / Metric	Requirements
Ipswich CBD	Solid Timber Waste & Stockpile Fire Risk	Timber Waste Skip Clearance Frequency & Dust Extraction Silo Spark Detection Log	Clear sawdust silos before reaching 80% capacity and separate treated vs. untreated timber scraps
Redbank	Solid Timber Waste & Stockpile Fire Risk	Timber Waste Skip Clearance Frequency & Dust Extraction Silo Spark Detection Log	Clear sawdust silos before reaching 80% capacity and separate treated vs. untreated timber scraps
Rosewood	Solid Timber Waste & Stockpile Fire Risk	Timber Waste Skip Clearance Frequency & Dust Extraction Silo Spark Detection Log	Clear sawdust silos before reaching 80% capacity and separate treated vs. untreated timber scraps
Springfield	Solid Timber Waste & Stockpile Fire Risk	Timber Waste Skip Clearance Frequency & Dust Extraction Silo Spark Detection Log	Clear sawdust silos before reaching 80% capacity and separate treated vs. untreated timber scraps
Springfield Central	Solid Timber Waste & Stockpile Fire Risk	Timber Waste Skip Clearance Frequency & Dust Extraction Silo Spark Detection Log	Clear sawdust silos before reaching 80% capacity and separate treated vs. untreated timber scraps
Wacol	Solid Timber Waste & Stockpile Fire Risk	Timber Waste Skip Clearance Frequency & Dust Extraction Silo Spark Detection Log	Clear sawdust silos before reaching 80% capacity and separate treated vs. untreated timber scraps