

Report: Moreton Bay - Furniture

Suburb / Node	Key Risk Category	Compliance Checklist / Metric	Requirements
Burpengary	Surface Coating & Hazardous Chemical Vapor Risk	Spray Booth Airflow Velocity Log & VOC Emission Check	Comply with AS/NZS 4114 for spray painting booths and maintain active charcoal filters
Caboolture	Surface Coating & Hazardous Chemical Vapor Risk	Spray Booth Airflow Velocity Log & VOC Emission Check	Comply with AS/NZS 4114 for spray painting booths and maintain active charcoal filters
Dakabin	Surface Coating & Hazardous Chemical Vapor Risk	Spray Booth Airflow Velocity Log & VOC Emission Check	Comply with AS/NZS 4114 for spray painting booths and maintain active charcoal filters
Kallangur	Surface Coating & Hazardous Chemical Vapor Risk	Spray Booth Airflow Velocity Log & VOC Emission Check	Comply with AS/NZS 4114 for spray painting booths and maintain active charcoal filters
Kippa-Ring	Surface Coating & Hazardous Chemical Vapor Risk	Spray Booth Airflow Velocity Log & VOC Emission Check	Comply with AS/NZS 4114 for spray painting booths and maintain active charcoal filters
Mango Hill	Surface Coating & Hazardous Chemical Vapor Risk	Spray Booth Airflow Velocity Log & VOC Emission Check	Comply with AS/NZS 4114 for spray painting booths and maintain active charcoal filters
Mango Hill East	Surface Coating & Hazardous Chemical Vapor Risk	Spray Booth Airflow Velocity Log & VOC Emission Check	Comply with AS/NZS 4114 for spray painting booths and maintain active charcoal filters

Suburb / Node	Key Risk Category	Compliance Checklist / Metric	Requirements
Morayfield	Surface Coating & Hazardous Chemical Vapor Risk	Spray Booth Airflow Velocity Log & VOC Emission Check	Comply with AS/NZS 4114 for spray painting booths and maintain active charcoal filters
Murrumba Downs	Surface Coating & Hazardous Chemical Vapor Risk	Spray Booth Airflow Velocity Log & VOC Emission Check	Comply with AS/NZS 4114 for spray painting booths and maintain active charcoal filters
Narangba	Surface Coating & Hazardous Chemical Vapor Risk	Spray Booth Airflow Velocity Log & VOC Emission Check	Comply with AS/NZS 4114 for spray painting booths and maintain active charcoal filters
Petrie	Surface Coating & Hazardous Chemical Vapor Risk	Spray Booth Airflow Velocity Log & VOC Emission Check	Comply with AS/NZS 4114 for spray painting booths and maintain active charcoal filters
Rothwell	Surface Coating & Hazardous Chemical Vapor Risk	Spray Booth Airflow Velocity Log & VOC Emission Check	Comply with AS/NZS 4114 for spray painting booths and maintain active charcoal filters