Construct CUSUM charts for hospital performance

Lena Hubig		
2019-10-02		

Overview

This vignette describes CUSUM charts based on a simulated false-signal-probability for hospital performance data in the R package **cusum**. This is a practical guide to constructing and evaluating non-risk-adjusted and risk-adjusted CUSUM charts following Steiner et al. (Biostatistics 1.4 (2000), pp. 441-52).

The **cusum** packages takes different factors into account that influence the signal rate of CUSUM charts. Some are given by the process to be monitored; these factors are:

- number of patients: How many observations do we expect in a monitoring period (e.g. a month/a year)?
- risk-adjustment: Is risk adjustment available? Can we allocate different risks to different observations?
 - o if yes:
 - patient risks: What are these risks and how are they distributed?
 - o if no:
 - o accepted failure probability: What kind of failure rate do we expect on average?

The primary control input when constructing a CUSUM chart is the control limit. The control limit signals performance deterioration once crossed by the cumulated sum.

The control limit depends on a number of variables:

- the desired target odds multiplier associated to an out-of-control process
- the false signal probability accepted
- number of simulations

Motivating example

To illustrate how **cusum** can be used for monitoring, we employ a simple and artificial data set generated to closely follow the performance data of German hospitals for one non-risk-adjusted performance indicator and one risk-adjusted performance indicator in 2016 and 2017.

risk-adj.	Indicator Description	Further explanation (in German)
NO	Ratio of observed to expected cases of severe stroke or death under open carotid stenosis surgery	<u>pdf (p4)</u>
YES	Preoperative stay more than 24 hours for patients with proximal femur fracture	<u>pdf (p23)</u>

Non-risk-adjusted performance indicator

Risk-adjusted performance indicator

First, CUSUM charts are constructed on performance data from 2016 (Phase I), and then applied and evaluated on performance data from 2017 (Phase II).

```
cusum_example_p1 <- cusum_example_data[cusum_example_data$year == 2016, ]
cusum_example_p2 <- cusum_example_data[cusum_example_data$year == 2017, ]
racusum_example_p1 <- racusum_example_data[racusum_example_data$year == 2016, ]
racusum_example_p2 <- racusum_example_data[racusum_example_data$year == 2017, ]</pre>
```

Non-risk-adjusted CUSUM chart

Simulation of CUSUM Control Limits

We get the control limit of our CUSUM chart by simulating for a false signal probability depending on sample size and accepted failure probability.

We can estimate the accepted failure probability by taking the average of Phase I. Alternatively, we could also define an accepted failure probability politically

```
failure_probability <- mean(cusum_example_p1$y)
n_patients <- nrow(cusum_example_p1)</pre>
```

Then, control limits can be simulated using *cusum_limit_sim*.

```
cusum_limit <- cusum_limit_sim(failure_probability,</pre>
```


```
n_patients,
odds_multiplier = 2,
n_simulation = 1000,
alpha = 0.05,
seed = 2046)

print(cusum_limit)
#> [1] 6.498476
```


Applying CUSUM Charts

Monitoring via CUSUM charts is applied on performance data from 2017 (Phase II) and the control limit *cusum_limit*. It can be calculated using *cusum*.

```
patient_outcomes <- cusum_example_p2$y</pre>
cusum_cs <- cusum(failure_probability,</pre>
                patient_outcomes,
                limit = cusum_limit,
                odds_multiplier = 2,
                reset = FALSE)
head(cusum_cs)
#> t failure_probability ct signal
                                     Limit
                 0.216 0
#> 1 1
                            0 6.498476
#> 2 2
                   0.216 0
                              0 6.498476
#> 3 3
                  0.216 0 0 6.498476
#> 4 4
                 0.216 0
                              0 6.498476
#> 5 5
                  0.216 0
                              0 6.498476
#> 6 6
                   0.216 0 0 6.498476
plot(cusum_cs)
```



Performance is as expected during the first half of monitoring, and then deteriorates. We get a signal at t=547. If reset==TRUE, the CUSUM resets after each signal.



Evaluating CUSUM charts

The false signal probability of a CUSUM chart can be simulated using *cusum_alpha_sim* given a predefined control limit.

We see that cusum_alpha equals our previously defined false signal probability of 0.05.

Risk-adjusted CUSUM chart


Simulation of RA-CUSUM Control Limits

Control limits of RA-CUSUM charts are simulated for a false signal probability depending on sample size and risk distribution.


RA-CUSUM Control limits can be simulated using racusum_limit_alpha.

Applying RA-CUSUM charts

Monitoring via RA-CUSUM chart is applied on performance data from 2017 (Phase II) and the control limit *racusum_limit*. It can be calculated using *racusum*.



Performance is as expected during the first half of monitoring, and then deteriorates. We get a signal at t=865. If reset==TRUE, the CUSUM resets after each signal.



Evaluating RA-CUSUM charts

The false signal probability of a CUSUM chart can be simulated using cusum_alpha_sim.

We see that $racusum_alpha$ is similar to our previously defined false signal probability of 0.05. Deviation is possible due to a slight change in risk population.

CUSUM Chart for process improvement

CUSUM charts for detecting process improvements can be constructed similarly, but the CUSUM statistic is restricted to non-positive values.

```
n_simulation = 1000,
alpha = 0.5,seed = 2046)
```

plot(cusum_cs_improve)

