ASSIGNMENT-2

Name: SUJAL SRIVASTAVA

Reg. No.: 20BME0699

Ex No: - 2

Title: - Flange Coupling

Aim: To construct the flange coupling with the help of fusion 360.

Procedure:

Flange Coupling:

1. Name the component name as 'Flange' and after this unhide the origin. Take the right plane.

2. Draw four concentric circles.

a.)45mm

b.)90mm

c.)140mm

d.)190mm

3. Draw one more circle on third circle of d=12 mm

4. Go to create —> circular pattern window appears—-> select the small circle(12mm) and for centre point of all the circles. Give the number of circles as 4.

5. Delete the 140 mm diameter circle. Finish the sketch

6. Go to the extrusion and give diameter= 20 mm

7. Unhide the sketch 8. Select the front plane and go for sketch

9. Extrude the recent sketch Extrude —-> symmetric —> full —> 14 mm —> cut

10. Make a fillet for three edges and give r=2 mm

Shaft:

11. Repeat the step 1. Take the right plane and go to sketch

12. Make a circle of 45 mm d.

13. Extruded circle as 150 mm

14. Take the front clean and go to sketch.

15. Extrude the above portion and give symmetric.

16. Repeat the step 1. Select the right plane.

17. Take the 'line' icon. Extrude this profile symmetric—> fold—> 14mm. Key is over.

Bolt:

18. Repeat the step 1 take the front plane.

19. Create a circle of 12 mm diameter.

20. Go to create—> polygon—>circumference polygon. Give the length of 21/2. Finish the sketch.
21. Go to extrude.

22. Go to create—> thread—> length—>18mm. Take modelled. Thread is formed. Bolt is completed.

Nut:

23. Select the front plane.

24. Repeat step 19 and 20

25. Select the inner surface of the both.

Results:

Figure:



Link: https://a360.co/3cxEHFg