

<i>TPD level</i>	<i>TPD Range</i>	<i>Indicative Workforce</i>	<i>Infra & Equipment Benchmarks</i>	<i>Note/ Scaling Guidance</i>
Small	<5 TPD	6–10 workers (4–6 sorters, 1 helper, 1 supervisor)	Manual sorting tables No forklift Basic storage zones	Lean operations with minimal role differentiation. A supervisor can also manage basic record-keeping. Forklift is typically not required. Deploy multi-skilled workers who can flex across loading, sorting, and basic admin tasks.
Small-mid	5-10 TPD	10–16 workers (6–10 sorters, 1–2 helpers, 1 supervisor)	Sorting tables + optional basic conveyor Manual handling still dominant	Begin planning for process streamlining. If feedstock is largely mixed, evaluate introducing a basic or semi-mechanised conveyor to improve sorting efficiency and reduce labour strain.
Mid	10-50 TPD	16–40 workers (12–30 sorters, 2–4 machine operators, 1–2 supervisors)	Conveyor belts essential Baling machine Basic mechanisation (trommel optional)	Conveyor-based sorting becomes increasingly valuable. Start structuring teams by function (sorting, machine operation, supervision). Collection workforce should be planned based on catchment characteristics, rather than TPD alone.
Large	>50 TPD	40–80+ workers (does not scale linearly with TPD)	Semi/full mechanisation Multiple conveyors Baling + advanced machinery	Strongly consider semi- to fully mechanised systems. Manual sorting alone does not scale efficiently beyond this level. Optimise sorter deployment alongside conveyors and mechanised processes to

				maintain throughput and consistency.
--	--	--	--	--------------------------------------