Joints	Angle (Degrees)	Rotation Axis	Link Length (m)
Joint 1	-180	Z-axis	0.03
Joint 2	-30	Y-axis	0.25
Joint 3	-30	Y-axis	0.28
Joint 4	-30	Y-axis	0.28
Joint 5	-30	Y-axis	0.15

Table 1: Joint Angles, Rotation Directions, Axes, and Link Lengths from the graph