Fire Safety Compliance Report

Automated compliance red-flag assessment (Fire Safety)

Document ID: 28181e97-97a2-4e2e-afd1-704ca7307352
Uploaded file: Sample Report Fire Safety.pdf
Analysis Date: 11/03/2026, 00:45:14

Prepared by:
Fire Safety Compliance Engine

Total rules	FAIL	UNKNOWN	PASS
281	2	157	122

Executive Summary

Overall compliance score

76/100

Risk rating: Moderate Risk

Moderate Risk

Status distribution

FAIL: 2

UNKNOWN: 157

PASS: 122

Top red flags

B5-FIREMAIN-OUTLET-01

High Score: 85

Review landing valve locations and surrounding obstructions (walls, door swings, cupboards

B5-FIREMAIN-INLET-SIGN-01

Medium Score: 65

Install durable, compliant signage identifying fire main inlet connections.

Family Overview

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

Family	FAIL	UNKNOWN	PASS	TOTAL
Other	2	151	118	271
Roof Spread	0	3	0	3
External Wall / Reg 7	0	2	2	4
Unprotected Areas	0	1	0	1
Vehicle Access	0	0	2	2

Compliance Results Overview

Automated compliance red-flag assessment (Fire Safety)

Grouped view of evaluated rules by status and rule family.

Red Flags

Other

2 item(s) • FAIL

B5-FIREMAIN-OUTLET-01

FAIL High Score: 85

Landing valve clearance

Part: B5 • Family: Other • Severity: high

Landing valve clearance issue reported (obstruction/restricted access for hose connection).

Mitigation

• Review landing valve locations and surrounding obstructions (walls, door swings, cupboards, services).

• Relocate the landing valve or adjust adjacent construction to achieve unobstructed hose connection and operation.

• Confirm installation matches BS 9990 guidance and record evidence in the fire strategy / commissioning pack.

References

• Vol 2, Section 17 — Fire mains should be arranged so landing valves are accessible and usable for firefighters.

• BS 9990 — Landing valves should have adequate clearance from obstructions to allow hose connection and operation.

B5-FIREMAIN-INLET-SIGN-01

FAIL Medium Score: 65

Dry riser inlet signage and visibility

Part: B5 • Family: Other • Severity: medium

Fire main inlet signage inadequate or missing

Mitigation

• Install durable, compliant signage identifying fire main inlet connections.

• Ensure inlet positions are clearly visible from appliance hardstanding.

• Improve visibility through additional signage, lighting, or relocation if obstructed.

• Ensure signage complies with BS 3251 and BS 9990 identification standards.

References

• Vol 2, Section 15, paras 15.4–15.5 — Fire main inlets should be clearly indicated and accessible to fire service.

• BS 3251 — Specification for fire service inlet breeching.

• BS 9990 — Fire mains installation and identification requirements.

Green Flags

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

External Wall / Reg 7

2 item(s) • PASS

B4-EXTWALL-REG7-01

PASS Low Score: 0

External wall relevant-building combustibility compliance

Part: B4 • Family: External Wall / Reg 7 • Severity: critical

Building is not evidenced as a relevant building for the Reg 7 route.

Compliance

No mitigation required (PASS).

References

• Regulation 7(2) and 7(3) — Relevant buildings generally require specified materials in the external wall and attached specified attachments, subject to limited exemptions.

• Vol 2, B4 — External wall combustibility and relevant-building rules should be evidenced through acceptable classification or exemption logic.

B4-NONRES-EXTWALL-BR135-01

PASS Low Score: 0

Non-residential external wall system test-route check (BR 135 / equivalent)

Part: B4 • Family: External Wall / Reg 7 • Severity: high

No non-residential BR 135 / system-test route is indicated.

Compliance

No mitigation required (PASS).

References

• Vol 2, B4 / system test route — Certain external wall systems may rely on an evidenced system-test route such as BR 135 / BS 8414 type evidence where applicable.

Other

118 item(s) • PASS

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-ALARM-CATEGORY-SLEEPING-01

PASS Low Score: 0

Automatic fire detection and alarms for sleeping accommodation (purpose groups 2(a)/2(b))

Part: B1 • Family: Other • Severity: critical

No sleeping accommodation (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 1, para 1.4 (p.198) — Sleeping uses (2(a)/2(b)) should have automatic fire detection and alarms.

• Vol 2, Section 1, paras 1.7–1.9 (p.198) — Category guidance via BS 5839-1; electrically operated systems should comply with BS 5839-1.

B1-DW-ESC-HOUSE-GROUND-01

PASS Low Score: 0

Escape from ground storey of dwellinghouses

Part: B1 • Family: Other • Severity: critical

Not applicable: room not habitable or not on ground storey

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 2, para 2.1 — Ground storey habitable rooms must open onto a hall leading to a final exit or have an emergency escape window/door.

B1-FLAT-ALARM-01

PASS Low Score: 0

Alarm provision within each flat

Part: B1 • Family: Other • Severity: critical

Not a self-contained flat (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 1, paras 1.10–1.13 — Each flat should have a domestic fire detection and alarm system to BS 5839-6; a common alarm is usually not required.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-COMP-FLOOR-RES-SEP-01

PASS Low Score: 0

Retail / residential compartment floor (separating commercial below from residential above)

Part: B3 • Family: Other • Severity: critical

Not a commercial-below / residential-above arrangement (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 8, paras 8.11–8.13; Table B4 (p.132) — Floors separating commercial uses from residential above should achieve the required compartment floor fire resistance (typically 60 or 90 minutes depending on height).

B3-FIRESTOP-SERVICES-WALL-01

PASS Low Score: 0

Service penetrations in compartment walls

Part: B3 • Family: Other • Severity: critical

Element is not a compartment wall/floor (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 10, paras 10.2–10.5, 10.24–10.29 (p.113) — Service penetrations through compartment walls/floors must be sealed with tested fire-stopping systems providing equivalent integrity and insulation.

B3-FIRESTOP-BASEMENT-PLANT-01

PASS Low Score: 0

Basement plant room compartmentation

Part: B3 • Family: Other • Severity: critical

Rule not applicable (not a basement plant room).

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 8, para 8.7 (p.89) — Plant rooms in basements should be enclosed in fire-resisting construction.

• Vol 2, Section 10 (p.112) — Service penetrations must be sealed to maintain compartmentation.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-COMP-WALL-CONTINUITY-01

PASS Low Score: 0

Compartment wall continuity and head detail

Part: B3 • Family: Other • Severity: critical

Rule not applicable (not a compartment wall).

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 8, paras 8.18–8.24 (p.94) — Compartment walls must form a continuous barrier and maintain fire resistance.

• Vol 2, Section 8, Diagram 8.3 (p.95) — Deflection head and junction details must preserve compartment integrity.

B5-FIREMAIN-PROVISION-01

PASS Low Score: 0

Fire main provision by building height

Part: B5 • Family: Other • Severity: critical

Building height (18 m) does not exceed 18 m; fire main provision not required.

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 16 — Fire mains should be provided in buildings with storeys over 18 m above fire service access level.

• Vol 2, Section 17; BS 9990 — Wet or dry rising mains should be installed depending on building height and firefighting shaft provision.

B1-ACCESS-CONTROL-ESCAPE-01

PASS Low Score: 0

Access control and electric locks on escape doors

Part: B1 • Family: Other • Severity: critical

Door is not on escape route (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 5, paras 5.7–5.8 — Escape doors must be openable without key and without delay.

• Vol 2, Section 2, para 2.8 — Escape doors must allow immediate escape without special knowledge.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-FLAT-SPRINKLERS-11M-01

PASS Low Score: 0

Sprinklers in blocks of flats with top storey over 11 m

Part: B3 • Family: Other • Severity: critical

Not a block of flats (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 7, para 7.4 (2020 amendments) (p.69)
• Vol 1, Appendix E (sprinklers) (p.69)
• Diagram D6 (sprinklers for flats > 11 m) (p.69)

B2-LININGS-CLASS-CIRCULATION-01

PASS Low Score: 0

Wall and ceiling linings classification for circulation spaces

Part: B2 • Family: Other • Severity: critical

Circulation space: wall and ceiling linings meet at least B-s3,d2

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 6, Table 6.1 (p.55) — Circulation spaces: wall and ceiling linings should be at least B-s3,d2 (unless a specific allowance applies).
• Vol 2, Section 6, para 6.1 (p.55) — Surface linings of walls and ceilings should meet Table 6.1 classifications.
• Vol 2, Section 6, para 6.4 (p.55) — Circulation spaces are sensitive because linings can provide a main route for fire spread and can rapidly compromise escape.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-STRUCT-FLOORS-01

PASS Low Score: 0

Fire resistance of floors supporting escape routes

Part: B3 • Family: Other • Severity: critical

No escape route flagged (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 7, para 7.5 — Floors forming part of the means of escape (supporting escape routes) should have appropriate fire resistance.

• Vol 2, Appendix B, Table B4 — Minimum periods of fire resistance (minutes) by use/height/sprinklers; used as the baseline required period.

B3-STRUCT-LOADBEARING-01

PASS Low Score: 0

Fire resistance of loadbearing elements

Part: B3 • Family: Other • Severity: critical

Not marked as loadbearing (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 7, para 7.3 — Loadbearing walls, columns and beams should maintain stability for the required fire resistance period.

• Vol 2, Appendix B, Table B4 — Minimum periods of fire resistance (minutes) by use/height/sprinklers; used as baseline required period.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-COMP-WALLS-HEIGHT-01

PASS Low Score: 0

Fire resistance of compartment walls by building height

Part: B3 • Family: Other • Severity: critical

No compartment wall flagged (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 7, Table 7.1 — Compartment wall fire resistance depends on building height and use (and related assumptions). Use the table/project fire strategy requirement to set the required minutes.

• Vol 2, Section B3, paras 7.5–7.6 (compartment walls/floors general provisions) — Compartment walls/floors should form a complete barrier and have appropriate fire resistance per the relevant tables/assumptions.

B3-COMP-FLOORS-HEIGHT-01

PASS Low Score: 0

Fire resistance of compartment floors

Part: B3 • Family: Other • Severity: critical

No compartment floor flagged (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 7, Table 7.1 — Compartment floors' minimum fire resistance depends on building height/use (and related assumptions). Use Table 7.1 / fire strategy requirement to set required minutes.

• Vol 2, Section B3, paras 7.5–7.6 (compartment walls/floors general provisions) — Compartment floors should provide a complete barrier and have appropriate fire resistance consistent with the building's compartmentation strategy.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-COMP-MIXED-USE-01

PASS Low Score: 0

Compartmentation between different uses

Part: B3 • Family: Other • Severity: critical

Not mixed-use (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 7, para 7.10 — Different purpose groups/uses within a building should be separated by compartment walls and floors (appropriate compartmentation strategy).

B3-SHAFT-PROTECTION-01

PASS Low Score: 0

Protection of lift shafts

Part: B3 • Family: Other • Severity: critical

No lift shaft flagged (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 7, paras 7.14–7.17 — Lift shafts should be enclosed in fire-resisting construction to prevent vertical fire spread; protection should match the relevant compartmentation requirement.

• Vol 2, Section B3, Table 7.1 — Compartmentation fire resistance periods by height/use (used to set required minutes for shaft enclosure where applicable).

B3-SHAFT-SERVICE-RISER-01

PASS Low Score: 0

Protection of service risers and vertical shafts

Part: B3 • Family: Other • Severity: critical

No service riser/vertical shaft flagged (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section B3, para 7.18 — Service risers/vertical service shafts should be enclosed in fire-resisting construction to limit fire spread between storeys; where they pass through compartment floors/walls, enclosure should maintain compartmentation.

• Vol 2, Section 7, Table 7.1 — Compartmentation fire resistance periods by height/use (used to set required minutes where risers cross compartments).

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-SHAFT-OPENINGS-01

PASS Low Score: 0

Protection of openings into protected shafts

Part: B3 • Family: Other • Severity: critical

No openings into protected shafts flagged (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 7, para 7.19 — Openings into protected shafts must not reduce the fire resistance of the shaft enclosure. Doors/hatches/access panels should provide equivalent fire resistance and be appropriately protected.

B3-PENETRATION-FIRESTOP-01

PASS Low Score: 0

Fire stopping of service penetrations

Part: B3 • Family: Other • Severity: critical

No service penetrations flagged (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 7, para 7.20 — Service penetrations through fire-resisting elements (e.g., compartment walls/floors) should be fire-stopped to maintain performance (integrity/insulation as applicable).

B3-PENETRATION-DUCTS-01

PASS Low Score: 0

Fire dampers in ducts penetrating compartments

Part: B3 • Family: Other • Severity: critical

No duct penetrations flagged (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 7, para 7.21 — Where ducts pass through compartment boundaries, they should be fitted with fire dampers (or appropriate tested/assessed protection) so compartment integrity is maintained.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-CAVITY-OPENINGS-LIMIT-01

PASS Low Score: 0

Openings through cavity barriers must be limited to permitted types and protected

Part: B3 • Family: Other • Severity: critical

No openings through cavity barriers flagged (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 9, para 9.17 — Openings through cavity barriers should be limited to permitted items and suitably protected (e.g., appropriately fire-rated doorsets; protected ducts with dampers; pipes/cables handled with suitable fire-stopping per relevant guidance).

B3-FIRESTOP-GENERAL-01

PASS Low Score: 0

All joints, imperfect fits, and service openings through fire-separating elements must be fire-stopped

Part: B3 • Family: Other • Severity: critical

No fire-separating element flagged (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 10, para 10.1 — Joints, imperfect fits and service openings in fire-separating elements should be sealed with suitable fire-stopping so the fire resistance is not impaired.

B5-FIRE-MAINS-HEIGHT-01

PASS Low Score: 0

Requirement for fire mains by building height (dry/wet rising mains)

Part: B5 • Family: Other • Severity: critical

Building height does not trigger fire main requirement under this rule

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 16, paras 16.1–16.6 (p.116) — Fire mains may be dry or wet; buildings with a storey more than 50m above fire service vehicle access level should be provided with wet fire mains.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B5-FIREFIGHTING-SHAFT-01

PASS Low Score: 0

Firefighting shafts required in tall buildings (shaft, protected lobby, rising main, lift where required)

Part: B5 • Family: Other • Severity: critical

Building height does not trigger firefighting shaft requirement under this rule

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 15, paras 15.1–15.12 (p.112) — Buildings above applicable height/complexity thresholds require firefighting shafts to support firefighting operations; shafts include protected stair and lobby and may require a firefighting lift and rising main.

B5-EVAC-ALERT-SYSTEM-18M-01

PASS Low Score: 0

Evacuation alert system (EAS) for blocks over 18m

Part: B5 • Family: Other • Severity: critical

No storey exceeds 18m (EAS not triggered)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 15, para 15.17 + 2022 amendments (evacuation alert systems) (p.113) — Blocks with storeys over 18m should provide an evacuation alert system (EAS) to enable fire and rescue service directed evacuation, typically to BS 8629.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-V1-FLATS-STRUCT-FR-APPB-01

PASS Low Score: 0

Flats: elements of structure must meet Appendix B fire resistance (Tables B3/B4)

Part: B3 • Family: Other • Severity: critical

Building is not a block of flats (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 6, para 6.1 (p.57) — Elements of structure (frames, beams, columns, loadbearing walls, floors, gallery structures) should have at least the fire resistance given in Appendix B, Table B3; supporting elements should have at least the same fire resistance as the element supported.

• Vol 1, Section 6, para 6.2 (p.57) — Defines exclusions from 'element of structure' (e.g., roof-only structures unless roof functions as a floor/escape, etc.).

• Vol 1, Appendix B, Table B3 (p.126) — Table B3 sets element categories and refers to Table B4 for the minimum period (minutes).

B3-V1-FLATS-COMP-REQUIRED-LIST-01

PASS Low Score: 0

Flats: key compartment walls/floors required (between flats/other parts; floors between flats; refuse store; walls common to buildings)

Part: B3 • Family: Other • Severity: critical

No flats indicated (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 7, para 7.1(a)–(d) (p.59) — Lists what must be compartment walls/floors in blocks of flats and requires minimum fire resistance to Appendix B Table B3.

• Vol 1, Appendix B, Table B3 (p.126) — Minimum fire resistance for compartment walls/floors is given by Table B3 (periods via Table B4).

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-V1-FLATS-SPRINKLERS-11M-01

PASS Low Score: 0

Blocks of flats: sprinklers required when top storey > 11m above ground level

Part: B3 • Family: Other • Severity: critical

No flats indicated (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 7, para 7.4 (p.59) — Blocks of flats with a top storey more than 11m above ground should be fitted with sprinklers throughout in accordance with Appendix E.

• Vol 1, Appendix E (Sprinklers), paras E1–E4 (p.147) — Appendix E sets out sprinkler design/installation approach and references BS 9251 / BS EN 12845.

B4-V1-GARAGE-SEPARATION-01

PASS Low Score: 0

Fire separation between attached/integral garage and dwelling

Part: B3 • Family: Other • Severity: critical

No attached or integral garage present

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 5, para 5.6 — Walls and floors between an attached/integral garage and dwelling should achieve minimum REI 30 fire resistance (from garage side).

• Vol 1, Diagram 5.1 — Illustrates fire-resisting separation between dwelling and garage.

B1-ALARM-LARGE-DW-3PLUSSTOREY-GRADEA-LD2-01

PASS Low Score: 0

Large dwellinghouse (3+ storeys): Grade A, LD2 (BS 5839-6)

Part: B1 • Family: Other • Severity: critical

Not a dwelling/flat (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 1, para 1.7 — Large dwellinghouses of three or more storeys (excluding basements) should be fitted with a Grade A, Category LD2 system (BS 5839-6).

• BS 5839-6 — Grade A (panel + detectors) with LD2 coverage for the specified dwelling scenario.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-DW-ESC-UPPER-LE4_5-01

PASS Low Score: 0

Dwellinghouse: upper storeys ≤4.5m (single stair) need escape window/door or protected stair access

Part: B1 • Family: Other • Severity: critical

Not a dwellinghouse (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 2, para 2.2 — Where served by only one stair, upper storey habitable rooms (excluding kitchens) should have an emergency escape window/external door or direct access to a protected stairway.

• Vol 1, Section 2, para 2.10 — Emergency escape window/door criteria (where used).

• Vol 1, Section 2, para 2.5(a) — Related provisions for single-stair situations and escape arrangements.

B1-DW-PROTECTED-STAIR-REI30-01

PASS Low Score: 0

Dwellinghouse >4.5m: protected stairway (minimum REI 30) and associated provisions

Part: B1 • Family: Other • Severity: critical

Not a dwellinghouse (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 2, para 2.5 — Where a dwellinghouse has a storey more than 4.5m above ground and only one internal stair, provide a protected stairway (min REI 30) extending to a final exit or to two separated final exits.

• Vol 1, Section 2, Diagram 2.2 — Illustrates protected stairway and final exit arrangements.

• Vol 1, Section 2, Diagram 2.3 — Illustrates separation/arrangements for final exits and protected stairway.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-DW-GT7_5M-ALTROUTE-OR-SPRINKLER-01

PASS Low Score: 0

Dwellinghouse with 2+ storeys >4.5m: alternative escape route above 7.5m or sprinklers

Part: B1 • Family: Other • Severity: critical

Not a dwellinghouse (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 2, para 2.6 — Where a dwellinghouse has two or more storeys more than 4.5m above ground, provide an alternative escape route from each storey more than 7.5m above ground level, or provide sprinklers throughout to BS 9251.

• Vol 1, Section 2, Diagram 2.4 — Illustrates the 7.5m threshold and escape/sprinkler options.

• BS 9251 — Residential and domestic sprinkler systems standard.

B1-FLATS-MIN-STAIRS-BY-HEIGHT-01

PASS Low Score: 0

Flats: minimum number of stairways required based on building height and escape strategy

Part: B1 • Family: Other • Severity: critical

Building is not a block of flats (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 3 (Blocks of flats – common escape routes) — Number/arrangement of stairs depends on building height and whether a single stair is acceptable; higher buildings require more robust arrangements.

B1-FLATS-SINGLE-STAIR-HEIGHT-LIMIT-01

PASS Low Score: 0

Flats: single common stair is only permitted where top storey height is within the allowed limit

Part: B1 • Family: Other • Severity: critical

Building is not flats (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 3, para 3.28(a) — Small single-stair buildings: the top storey height must not exceed the single-stair limit (commonly 11m) for the single-stair approach to be acceptable.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-V2-PROTECTED-AREA-INDEPENDENT-ESCAPE-01

PASS Low Score: 0

Care homes (PHE): fire in one protected area must not prevent other protected areas reaching a final exit

Part: B1 • Family: Other • Severity: critical

Not a care home (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 2, para 2.38 (p.215) — A fire in one protected area should not prevent occupants of other areas from reaching a final exit; escape routes should not pass through ancillary accommodation listed in para 2.44.

• Vol 2, Section 2, Diagram 2.11 (p.215) — Illustrates progressive horizontal evacuation arrangement and routing to adjacent compartments/storey exit/final exit.

B1-V1-MIXED-USE-SEPARATE-ESCAPE-01

PASS Low Score: 0

Mixed-use building: separate means of escape between different uses

Part: B1 • Family: Other • Severity: critical

Not a mixed-use building (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 3, para 3.5 — Where a building contains more than one use (e.g., flats over shops), escape routes for one use should not pass through another use; separation and independent escape arrangements are required.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B4-V2-SOLAR-SHADING-REG7-2-01

PASS Low Score: 0

Solar shading devices: curtain/slats must be A1 or A2-s1,d0; 4.5m height exception; curtain cannot be treated as a membrane

Part: B4 • Family: Other • Severity: critical

Not a relevant building for Regulation 7(2) (rule not applicable)

Compliance

No mitigation required (PASS).

References

• Vol 2, Section 12, paras 12.19–12.20 (p.287) — Curtain/slats of solar shading devices in relevant buildings must be class A1 or A2-s1,d0; curtain cannot be classified as a membrane; devices up to 4.5m above ground are not required to meet Reg 7(2).

• Regulation 7(2)–7(4) (p.281) — Reg 7(2) requires A2-s1,d0 or A1 for materials in external walls/ specified attachments of relevant buildings; Reg 7(4) defines relevant buildings; Reg 7(3) exemptions exist but do not allow treating the solar shading curtain as a membrane.

B4-V2-WINDOW-SPANDREL-INFILL-COMPLIANCE-01

PASS Low Score: 0

Window spandrel panels and infill panels must comply with Regulation 7(2) (frames/glass are exempt)

Part: B4 • Family: Other • Severity: critical

Not a relevant building for Regulation 7(2) (rule not applicable)

Compliance

No mitigation required (PASS).

References

• Vol 2, Section 12, para 12.22(d) (p.98) — Window frames and glass (including laminated glass) are exempt from Reg 7(2); window spandrel panels and infill panels must comply with Reg 7(2).

• Vol 1, Section 10, para 10.14–10.16 (p.92) — Reg 7(2) requires materials forming part of external walls/ specified attachments in relevant buildings to be class A2-s1,d0 or A1 (except Reg 7(3) exemptions).

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-ALARM-CATEGORY-COMPLEX-01

PASS Low Score: 0

Voice alarm / staged alarm support for complex or managed evacuations

Part: B1 • Family: Other • Severity: high

No complex/managed evacuation indicators (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 1, para 1.11 (p.199) — Voice alarm (BS 5839-8) may be considered for slow response/ unfamiliar occupants.

• Vol 2, Section 1, para 1.13 (p.199) — Simultaneous evacuation -> warning from all sounders; phased evacuation -> staged alarm appropriate.

B1-CORRIDOR-PROTECTED-01

PASS Low Score: 0

Protected corridor required for bedrooms, extended dead-ends, or mixed occupancy

Part: B1 • Family: Other • Severity: high

No protected-corridor trigger indicated (not serving bedrooms, not mixed occupancy, no extended dead-end identified)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 2, para 2.24 — Corridors serving certain risks should be protected.

• Vol 2, Section 5.2 — Guidance on protected corridors / fire-resisting construction.

B1-DW-ESC-LOFT-01

PASS Low Score: 0

Loft conversion: protect escape route + fire doors/partitions (or sprinkler alternative)

Part: B1 • Family: Other • Severity: high

Not a dwellinghouse (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 2, paras 2.21–2.23 (Loft conversions) — If a new storey is created above 4.5m, address the full escape route; provide E20 doors + REI30 partitions, incl. upgrades. Alternative: sprinklers + REI30/ E20 separation + cooking separated.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-DW-ESC-BSMT-01

PASS Low Score: 0

Escape from basements with habitable rooms (houses)

Part: B1 • Family: Other • Severity: high

Not a dwellinghouse (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 2, para 2.16 — Basements with habitable rooms need escape window/external door OR protected stairway to final exit.

B1-FLAT-INT-PLANNING-01

PASS Low Score: 0

Internal planning of flats above 4.5 m

Part: B1 • Family: Other • Severity: high

Not a self-contained flat (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 3, paras 3.18–3.22; Diagrams 3.2–3.6 — Flats with storeys > 4.5 m above ground need protected entrance halls and/or restricted travel distance or alternative exit arrangements.

B1-FLAT-COMMON-ESC-01

PASS Low Score: 0

Common escape routes in blocks of flats

Part: B1 • Family: Other • Severity: high

Not a block of flats (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 3, paras 3.25–3.38; Diagrams 3.7–3.9; Table 3.1 — Common corridors/lobbies/stairs must meet limits on travel distance, dead-ends, and single-stair conditions for stay-put and firefighter access.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B2-LININGS-BASEMENT-01

PASS Low Score: 0

Basement linings reaction-to-fire

Part: B2 • Family: Other • Severity: high

Not a basement area (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 6, Table 6.1; Vol 1, Section 4 — Basement storage/circulation linings should achieve at least Class C-s3,d2 (or national Class 1 / Class 0 equivalent). Exposed Class 3 / D-s3,d2 materials (e.g., polystyrene boards) are normally unacceptable.

B2-DW-LININGS-GENERAL-01

PASS Low Score: 0

Linings in dwellings (rooms, circulation, garages)

Part: B2 • Family: Other • Severity: high

Not a dwelling (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 4, para 4.1; Table 4.1 (p.43) — Walls/ceilings linings in dwellings must meet Table 4.1 classes (small rooms, garages, rooms, circulation).

B3-STRUCT-MEZZ-01

PASS Low Score: 0

Mezzanine floor fire resistance (retail/industrial)

Part: B3 • Family: Other • Severity: high

No mezzanine indicated (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 7, Table B4; Section 8 (p.131) — Use Table B4 periods; mezzanines forming structure/compartmentation should meet required REI for that storey.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-DOOR-RATING-01

PASS Low Score: 0

Fire door rating on compartment lines

Part: B3 • Family: Other • Severity: high

Rule not applicable (door not on compartment/protected route line).

Compliance
No mitigation required (PASS).

References
• Vol 2, Appendix C, Table C1 (p.203) — Doors in compartment walls/protected routes need appropriate fire resistance and smoke control.

B3-DOOR-SEALS-01

PASS Low Score: 0

Fire door intumescent and smoke seals

Part: B3 • Family: Other • Severity: high

Rule not applicable (door not on compartment/protected route line).

Compliance
No mitigation required (PASS).

References
• Vol 2, Appendix C, paras C10–C15 (p.204) — Intumescent/cold-smoke seals should be continuous, undamaged, and match the tested doorset configuration.

B3-COMP-WALL-SEPARATED-01

PASS Low Score: 0

Separated parts and walls between buildings

Part: B3 • Family: Other • Severity: high

Rule not applicable (not treated as separated part).

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 8, paras 8.18–8.21 (p.94) — Walls separating buildings or separated parts must form full-height compartment walls.

• Vol 2, Appendix A (separated part) (p.140) — Separated parts must be treated as independent buildings with full compartmentation.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-SPECIAL-HAZARD-ENCLOSURE-01

PASS Low Score: 0

Places of special fire hazard enclosure

Part: B3 • Family: Other • Severity: high

Rule not applicable (not a special fire hazard space).

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 8, para 8.7 (p.92) — Places of special fire hazard must be enclosed in fire-resisting construction.

• Vol 2, Appendix A (place of special fire hazard) (p.138) — Examples include boiler rooms, fuel stores, and electrical switch rooms.

B3-DW-GARAGE-SEPARATION-01

PASS Low Score: 0

Separation between integral/attached garages and dwellings

Part: B3 • Family: Other • Severity: high

Garage is not integral/attached (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 5, paras 5.6–5.7 — Attached/integral garages require fire-resisting separation and appropriate door performance.

• Vol 1, Section 5, Diagram 5.1 — Diagram shows separation/threshold/fall guidance to manage fuel spills.

B4-CAVITY-BARRIERS-01

PASS Low Score: 0

External wall cavity barriers

Part: B4 • Family: Other • Severity: high

No indication of an external wall cavity system (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 9, paras 9.3–9.4 — Cavity barriers to restrict unseen fire spread in concealed cavities.

• Vol 2, Section 12, para 12.9 — External wall cavities must be appropriately closed/subdivided at key locations.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B5-BASEMENT-SMOKE-VENT-01

PASS Low Score: 0

Basement smoke outlets for non-residential areas

Part: B5 • Family: Other • Severity: high

No basement (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 18, paras 18.1–18.4 (p.126) — Basements require smoke ventilation to assist firefighting and smoke clearance.

• Vol 2, Section 18, paras 18.5–18.10 (p.127) — Smoke outlets must provide sufficient free area or mechanical extract capacity.

B5-CARPARK-SMOKE-VENT-01

PASS Low Score: 0

Smoke ventilation in basement and enclosed car parks

Part: B5 • Family: Other • Severity: high

Car park is not enclosed/basement (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 11, paras 11.2–11.5 — Car park ventilation provisions (open-sided vs enclosed) and associated fire safety considerations.

• Vol 2, Section 18, paras 18.11–18.15 — Smoke ventilation expectations for basement/enclosed car parks (natural or mechanical).

B5-DW-ACCESS-01

PASS Low Score: 0

Fire appliance access to dwellinghouses

Part: B5 • Family: Other • Severity: high

Not a dwellinghouse (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 13, paras 13.1–13.2 — Fire and rescue service vehicle access/positioning and hose laying distance for dwellinghouses.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-OPEN-PLAN-FLOOR-OPENING-01

PASS Low Score: 0

Escape routes near internal floor openings

Part: B1 • Family: Other • Severity: high

No internal floor opening/void affecting escape route (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 2, para 2.13 — Escape routes passing close to internal floor openings/voids can be rapidly compromised.

• Vol 2, Section 2, Diagram 2.5 — If within 4.5 m of an internal opening, initial escape should be away or provide alternative route.

B1-MIXED-USE-FOOD-AREA-01

PASS Low Score: 0

Escape from food and drink areas in mixed-use storeys

Part: B1 • Family: Other • Severity: high

Not an ancillary food/drink area on the storey (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 2, para 2.16 (p.207) — Ancillary food/drink areas on a storey need 2 escape routes and must not rely on routes through kitchens/high hazard areas.

B1-MULTI-OCCUPANCY-CORRIDOR-01

PASS Low Score: 0

Common corridors between multiple occupancies

Part: B1 • Family: Other • Severity: high

Corridor not shared by multiple occupancies (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 2, para 2.17 (p.207) — If a storey is divided into occupancies, escape must not pass through other occupancies; common corridor shared by 2+ occupancies should be protected corridor or have suitable automatic detection.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-FIXED-LADDER-ESCAPE-01

PASS Low Score: 0

Use of fixed ladders as escape routes

Part: B1 • Family: Other • Severity: high

No fixed ladder used (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 3, para 3.85 (Fixed ladders) (p.48) — Fixed ladders are not acceptable for public escape; only where a conventional stair is impractical (e.g. plant rooms not normally occupied).

B1-ESCAPE-LIGHTING-SPECIFIC-01

PASS Low Score: 0

Escape lighting to specified high-risk spaces

Part: B1 • Family: Other • Severity: high

Space does not trigger AD B Table 5.1 escape lighting requirements

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 5, Table 5.1 (p.239) — Table 5.1 lists areas requiring escape lighting (e.g., underground/windowless, toilets ≥ 8 m², generator/electricity rooms, emergency control rooms).

• Vol 2, Section 5, paras 5.25–5.27 (p.240) — If mains fails, escape lighting should illuminate routes listed in Table 5.1 and conform to BS 5266-1.

B1-REFUSE-CHUTE-STORAGE-01

PASS Low Score: 0

Refuse chutes and storage near escape routes

Part: B1 • Family: Other • Severity: high

No refuse chute/storage indicated (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 5, paras 5.42–5.45; BS 5906 (p.52) — Refuse chutes/storage: fire separation, location away from protected stairs/lobbies, approach/ventilation, and siting of access openings.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B5-WAYFINDING-FLATS-11M-01

PASS Low Score: 0

Wayfinding signage in flats over 11 m

Part: B5 • Family: Other • Severity: high

Not a block of flats (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 15, paras 15.13–15.16 (2020 amendments)

B5-VEHICLE-ACCESS-PERIMETER-01

PASS Low Score: 0

Fire appliance access to building perimeter (Vol 2, Section 15; Table 15.1)

Part: B5 • Family: Other • Severity: high

Building fitted with fire mains (use fire-mains access rules; this rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 15, paras 15.1–15.3 (p.111) — Small buildings: 15% perimeter or within 45m of all points. Others: Table 15.1 perimeter % by floor area/height. Doors required on accessed elevations.

• Vol 2, Section 15, Table 15.1 (p.112) — Required perimeter access % depends on total floor area (excluding basements) and top storey height.

B5-FIRE-MAINS-PROVISION-01

PASS Low Score: 0

Provision of fire mains and type (dry/wet) (Vol 2, Section 16)

Part: B5 • Family: Other • Severity: high

Building height does not exceed 18m; fire main provision not required.

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 16, paras 16.2–16.7 — Where firefighting shafts are required or hose reach is excessive, provide internal fire mains (typically to BS 9990). Where any storey is >50m above access level, mains should be wet rather than dry.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

R38-V1-HANDOVER-COMPLEX-01

PASS Low Score: 0

R38 handover: additional strategy record for complex buildings

Part: R38 • Family: Other • Severity: high

Building not marked as complex (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 17, para 17.5 (p.113) — For complex buildings, provide a detailed record of the fire safety strategy and operating/maintenance procedures including an outline cause-and-effect matrix.

• Vol 1, Section 17, para 17.6 (p.113) — Records should include assumptions, risk assessments/analysis, management assumptions, escape/evacuation strategy details, and passive/active measures (as-built plan locations).

• BS 9999 clause 9 & Annex H — Further guidance on fire safety management documentation and records.

B2-LININGS-CLASS-OTHER-ROOMS-01

PASS Low Score: 0

Wall and ceiling linings classification for other rooms (including garages)

Part: B2 • Family: Other • Severity: high

Room qualifies as a 'small room' (use small-room linings rule instead)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 6, Table 6.1 (p.55) — Rooms other than small rooms (incl. garages): wall and ceiling linings should be at least C-s3,d2 (or better).

• Vol 2, Section 6, para 6.1 (p.55) — Surface linings of walls and ceilings should meet Table 6.1 classifications.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-COMP-CONTINUITY-01

PASS Low Score: 0

Continuity of compartment walls and floors

Part: B3 • Family: Other • Severity: high

Not a compartment junction (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 7, para 7.8 — Compartment walls and floors should be continuous and maintain fire resistance at junctions/through interfaces; fire resistance should not be reduced at junctions.

B3-COMP-VOID-CONTINUITY-01

PASS Low Score: 0

Compartment continuity through concealed spaces

Part: B3 • Family: Other • Severity: high

No concealed spaces flagged (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 7, para 7.11 — Compartment walls/floors should extend through concealed spaces so the compartment line is not bypassed (e.g., roof/ceiling voids, raised floors).

B3-PENETRATION-CONTINUITY-01

PASS Low Score: 0

Continuity of fire resistance at service penetrations

Part: B3 • Family: Other • Severity: high

No service penetrations flagged (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 7, para 7.22 — Fire resistance should be continuous around service penetrations; gaps/voids should be sealed to prevent fire/smoke spread.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-CAVITY-OPENINGS-BEDROOMS-EXCEPTION-01

PASS Low Score: 0

Bedroom partition cavity barrier openings: minimise openings and smoke-seal penetrations

Part: B3 • Family: Other • Severity: high

Bedroom partition cavity barrier exception not applicable

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 9, para 9.18 — Where cavity barriers are provided above/below certain non-fire-resisting bedroom partitions (PG 2(a)/2(b)), openings should be minimised and penetrations smoke-sealed to reduce smoke spread risk.

B3-CAVITY-FIRECEILING-EI30-01

PASS Low Score: 0

Fire-resisting ceiling option below cavity must be EI 30 and continuous

Part: B3 • Family: Other • Severity: high

Fire-resisting ceiling strategy not used (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 9, Diagram 9.3 (see para 9.5) — A continuous EI 30 ceiling may substitute for cavity barriers in certain situations, provided it is continuous, imperforate except for permitted openings, and maintains required fire performance.

B3-CAVITY-EXTENSIVE-DIMENSIONS-01

PASS Low Score: 0

Maximum dimensions for undivided cavities (purpose groups 2–7)

Part: B3 • Family: Other • Severity: high

Cavity dimension within permitted Table 9.1 limits

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 9, paras 9.9–9.10

• Vol 2, Table 9.1 — Maximum dimensions for undivided cavities vary by cavity location and surface class; typically 20m for roof/ceiling cavities and 20m or 10m for other cavities depending on lining class.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-FIRESTOP-PIPES-PROPRIETARY-01

PASS Low Score: 0

Pipes through fire-separating elements: proprietary tested seals are acceptable (any diameter)

Part: B3 • Family: Other • Severity: high

No pipe penetration flagged (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 10, paras 10.2–10.3 — Pipes penetrating fire-separating elements must not reduce fire resistance. Proprietary tested sealing systems may be used for any pipe diameter where performance is maintained.

B3-FIRESTOP-PIPES-DIAMETER-01

PASS Low Score: 0

Pipes through fire-separating elements: if no proprietary seal, diameter limits apply

Part: B3 • Family: Other • Severity: high

No pipe penetration flagged (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 10, para 10.4 — If proprietary tested seals are not used, pipes through fire-separating elements must be tightly fire-stopped with small openings and must not exceed Table 10.1 diameter limits (by situation and pipe material).

• Vol 2, Section 10, Table 10.1 — Max nominal internal diameters: Situation 1: 160/110/40; Situation 2: 160/40/40 (by material category).

• Vol 2, Section 10, Diagram 10.1 — Opening in fire-separating element should be as small as possible and fire-stopped around pipe; sleeve should be A1 rated where relevant.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B4-BALCONY-FIRE-SPREAD-01

PASS Low Score: 0

Balconies and external projections: limit external fire spread between storeys

Part: B4 • Family: Other • Severity: high

No balconies/external projections (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 10, para 10.9 (p.90) — Balconies and external projections should not promote rapid fire spread between storeys; materials and detailing should resist flame spread and fire penetration.

B4-EXT-JUNCTIONS-01

PASS Low Score: 0

Fire spread at external wall and roof junctions (cavity barriers and fire-stopping)

Part: B4 • Family: Other • Severity: high

No external wall/roof junction flagged (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 10, para 10.11 (p.90) — Junctions between external walls and roofs must limit concealed and surface fire spread; provide cavity barriers and fire-stopping at wall/roof junctions.

B2-LININGS-CLASSIFICATION-01

PASS Low Score: 0

Minimum wall/ceiling lining class by location (dwellings) – Table 4.1

Part: B2 • Family: Other • Severity: high

Lining classification "A1" meets minimum "C-s3,d2" for space type "CIRCULATION"

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 4 (Wall and ceiling linings), Table 4.1 (p.43) — Wall and ceiling surface linings should meet minimum reaction-to-fire classifications by location within dwellings.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B2-LININGS-ROOMS-01

PASS Low Score: 0

Rooms: lining classification (Table 4.1)

Part: B2 • Family: Other • Severity: high

Not a room (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 4 (Wall and ceiling linings), Table 4.1 (p.43) — Rooms generally permit less restrictive lining classifications than circulation spaces. Apply Table 4.1 based on room type and area.

B2-THERMOPLASTICS-CEILINGS-01

PASS Low Score: 0

Thermoplastic ceiling linings restrictions

Part: B2 • Family: Other • Severity: high

No thermoplastic ceiling lining proposed (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 4 (Thermoplastic materials) (p.44) — Thermoplastic materials on ceilings are subject to area and location limits, particularly in circulation spaces and protected escape routes.

B2-LININGS-LOWER-PERF-ALLOWANCE-01

PASS Low Score: 0

Limited areas of lower-performance wall linings in rooms

Part: B2 • Family: Other • Severity: high

Not a room (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 4, para 4.4 (p.42) — Limited areas of wall in rooms may be lower performance than Table 4.1, subject to minimum class and area limits.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B2-THERMOPLASTIC-ROOFLIGHTS-01

PASS Low Score: 0

Thermoplastic rooflights allowed except protected stairways; subject to TP class + Table 4.2 limits

Part: B2 • Family: Other • Severity: high

No thermoplastic rooflights indicated (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 4, para 4.14 (p.56) — Thermoplastic rooflights permitted in rooms/circulation spaces (not protected stairways) if lower surface is TP(a) rigid or TP(b) and size/location limits are met.

• Vol 1, Section 4, Table 4.2 (p.57) — Table 4.2 limits: TP(a) no limit (except not in protected stairways); TP(b) subject to max areas/percentages and separation distances.

B3-V1-FLATS-MIXED-USE-COMP-01

PASS Low Score: 0

Flats: separate different primary purposes by compartment walls/floors (unless ancillary)

Part: B3 • Family: Other • Severity: high

Not mixed-use (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 7, para 7.3 (p.59) — Parts of a building occupied mainly for different purposes should be separated by compartment walls/floors; not needed if one purpose is ancillary to the other.

• Vol 1, paragraphs 0.18–0.19 (p.9) — Explains mixed-use approach and ancillary use principle referenced by para 7.3.

B5-V1-HOSE-DISTANCE-01

PASS Low Score: 0

Maximum hose distance from fire appliance to dwelling entrance

Part: B5 • Family: Other • Severity: high

Appliance access not required for this dwelling

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 11, para 11.4 — Fire service appliances should be able to approach within 45m of all points within a dwellinghouse.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-ALARM-DWELLING-MIN-GRADED2-LD3-01

PASS Low Score: 0

Minimum fire detection and alarm standard for dwellings (min Grade D2, LD3; BS 5839-6)

Part: B1 • Family: Other • Severity: high

Not a dwelling/flat (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 1, paras 1.1–1.4 — Dwellings should be provided with appropriate fire detection and alarm systems.

• BS 5839-6 — Minimum Grade D2 and Category LD3 commonly referenced for dwellings (unless higher standard needed).

B1-ALARM-LARGE-DW-2STOREY-GRADEA-LD3-01

PASS Low Score: 0

Large dwellinghouse (2 storeys): Grade A, LD3 (BS 5839-6)

Part: B1 • Family: Other • Severity: high

Not a dwelling/flat (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 1, paras 1.5–1.6 — Large two-storey dwellinghouses (excluding basements) with a storey over 200m² should be fitted with a Grade A, Category LD3 system (BS 5839-6).

• BS 5839-6 — Grade A (panel + detectors) LD3 for specified dwelling scenarios.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-ALARM-EXTENSION-HABITABLE-ABOVE-BELOW-01

PASS Low Score: 0

Extensions/material alterations: alarm needed if new habitable room above/below ground storey

Part: B1 • Family: Other • Severity: high

No extension/material alteration creating a new habitable room above/below ground storey (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 1, para 1.8(a) (p.9) — Install a fire detection and alarm system where a new habitable room is provided above or below the ground storey.

• Vol 1, Section 1, para 1.9 (p.9) — Provide smoke alarms in circulation spaces in accordance with paras 1.1–1.4.

• Vol 1, Section 1, paras 1.1–1.4 (p.9) — Minimum Grade D2 Category LD3 system per BS 5839-6; mains-powered alarms: standby power.

B1-DW-PASSENGERLIFT-PROTECTED-01

PASS Low Score: 0

Dwellinghouse: passenger lift serving storey >4.5m must be within protected stair enclosure or REI30 shaft

Part: B1 • Family: Other • Severity: high

Not a dwellinghouse (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 2, para 2.7 — A passenger lift serving any storey more than 4.5m above ground should be within the protected stair enclosure or in a fire-resisting lift shaft (minimum REI 30).

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-DW-AIR-CIRCULATION-PROTECTED-STAIR-01

PASS Low Score: 0

Dwellinghouse >4.5m: air circulation precautions to protect stair enclosure

Part: B1 • Family: Other • Severity: high

Not a dwellinghouse (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 2, paras 2.8–2.9 — Air circulation systems should not compromise protected stair enclosures (e.g., no transfer grilles; ducts through stair enclosure to be rigid steel and fire-stopped; appropriate zoning/shutdown).

B1-DW-INNER-INNER-ROOMS-01

PASS Low Score: 0

Dwellinghouse: inner rooms and inner-inner rooms must have appropriate escape provisions

Part: B1 • Family: Other • Severity: high

Not a dwellinghouse (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 2 (Inner rooms guidance) — Inner rooms and inner-inner rooms require additional safeguards (e.g., escape windows/doors or detection/vision panels) to ensure occupants can escape if the access room is affected by fire.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-V1-FLATS-ACCESS-THROUGH-ROOM-REI30-01

PASS Low Score: 0

Flats: if habitable room access passes through another room, provide alternative exit + REI30 separation + E20 doors

Part: B1 • Family: Other • Severity: high

Not flats (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 3, para 3.19 (p.23) — Where access from any habitable room to the entrance hall/flat entrance is impossible without passing through another room, conditions (a) bedrooms separated by REI30 + E20 doorsets and (b) alternative exit in bedroom part should be met.

• Vol 1, Section 3, Diagram 3.4 (p.23) — Flat with alternative exit where habitable rooms have no direct access to entrance hall; shows REI30 separation and alternative exit located in bedroom part.

B1-V1-MAISONETTE-NO-GROUND-ENTRANCE-APPROACH-01

PASS Low Score: 0

Multi-storey flat without own external entrance at ground level: adopt Approach 1, 2, 3, or 4

Part: B1 • Family: Other • Severity: high

Not flats/maisonette (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 3, para 3.21 (p.24) — Where multi-storey flats do not have their own external entrance at ground level, adopt Approach 1, 2, 3 or 4 (alternative exits by room, alternative exits by storey with protected landing, protected stair + sprinklers, or protected stair + additional alarms/heat alarm where vertical distance ≤7.5m).

• Vol 1, Section 3, Diagrams 3.5 and 3.6 (p.24) — Diagrams illustrating Approach 1 (alternative exits from each habitable room not on entrance storey) and Approach 2 (alternative exit from each non-entrance storey with protected landing).

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-V1-FLATS-SINGLE-ROUTE-FLAT-ENTRANCE-01

PASS Low Score: 0

Common parts (flats): single escape route from flat entrance door only acceptable in defined cases

Part: B1 • Family: Other • Severity: high

Not flats (rule not applicable).

Compliance

No mitigation required (PASS).

References

• Vol 1, Section 3, para 3.27 — From the flat entrance door, a single escape route is acceptable only if (a) single common stair with protected lobby/protected corridor separation and one-direction travel distance not exceeded, OR (b) dead-end of common corridor served by 2+ stairs and one-direction travel distance not exceeded.

• Vol 1, Section 3, Table 3.1 — Maximum travel distance from flat entrance to common stair or stair lobby: escape in one direction 7.5m (reduced to 4.5m for small single stair building).

B4-V2-REG7-3-EXEMPTIONS-01

PASS Low Score: 0

Regulation 7(3) exemptions to the Regulation 7(2) combustibles ban (external walls & specified attachments)

Part: B4 • Family: Other • Severity: high

Not a relevant building for Regulation 7(2) (rule not applicable)

Compliance

No mitigation required (PASS).

References

• Regulation 7(2)–7(4) (p.281) — Reg 7(2) requires A2-s1,d0 or A1 materials in external walls/specified attachments of relevant buildings; Reg 7(3) lists exempt components.

• Vol 2, Section 12, paras 12.14–12.17 (p.286) — Explains Regulation 7(2) and states Reg 7(3) provides exemptions for certain components in external walls and specified attachments.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-REG38-INFORMATION-01

PASS Low Score: 0

Provision of fire safety information (Regulation 38)

Part: B1 • Family: Other • Severity: medium

Regulation 38 fire safety information provided (or not assessed)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 19 (Regulation 38) — Fire safety information must be handed over on completion/first occupation for relevant buildings.

B2-LININGS-SMALLROOM-01

PASS Low Score: 0

Small room linings

Part: B2 • Family: Other • Severity: medium

Circulation space (use circulation-linings rule instead)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 6, para 6.1; Table 6.1 (p.55) — Small rooms (≤4m² residential or ≤30m² non-residential): linings should be at least Class D-s3,d2.

B2-THERMO-ROOFLIGHT-01

PASS Low Score: 0

Thermoplastic rooflights and diffusers

Part: B2 • Family: Other • Severity: medium

Not a rooflight or diffuser (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 6, paras 6.13–6.18 (p.60) — Thermoplastic rooflights/diffusers must meet TP(a) rigid or TP(b) classifications.

• Vol 2, Section 6, Tables 6.2 and 4.2 (p.61) — Limits on area, spacing, and use above escape routes or protected stairways.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B2-DW-THERMO-ROOFLIGHT-01

PASS Low Score: 0

Thermoplastic rooflights/diffusers in dwellings

Part: B2 • Family: Other • Severity: medium

Not a dwelling (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 4, paras 4.17; Tables 4.2 and 12.2–12.3 (p.49) — Thermoplastic rooflights/diffusers have size & spacing limits; restrictions over protected stairways / escape routes.

B3-CORRIDOR-SUBDIVISION-01

PASS Low Score: 0

Sub-division of long escape corridors

Part: B3 • Family: Other • Severity: medium

Rule applies only to corridors.

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 2, paras 2.26–2.28 — Long corridors connecting multiple exits or with dead ends require fire-resisting subdivision to limit smoke spread.

• Vol 2, Section 2, Diagrams 2.9–2.10 — Diagram guidance for sub-division arrangement.

B1-CORRIDOR-RECESS-DEPTH-01

PASS Low Score: 0

Deep recesses off escape corridors

Part: B1 • Family: Other • Severity: medium

No corridor recesses reported (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 2, para 2.24; Diagrams 2.7–2.8 (p.207) — Recesses/extensions off escape corridors deeper than 2m should be treated as dead-end portions for travel distance/corridor protection purposes.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-HEADROOM-ESCAPE-01

PASS Low Score: 0

Headroom on escape routes (minimum 2.0 m)

Part: B1 • Family: Other • Severity: medium

Not an escape-route segment (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 5, para 5.16 (p.239) — Escape routes need 2.0 m clear headroom; only door frames may project below this.

B1-RAMPS-SLOPE-01

PASS Low Score: 0

Ramp and sloping floor gradients on escape routes

Part: B1 • Family: Other • Severity: medium

No ramp or sloping floor/tier identified on escape route (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 5, para 5.18 (p.238) — Ramp on escape route should meet Approved Document M; any sloping floor/tier pitch ≤ 35°.

B1-SPIRAL-STAIR-TYPE-01

PASS Low Score: 0

Helical and spiral stairs on escape routes

Part: B1 • Family: Other • Severity: medium

No spiral/helical stair present (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 3, para 3.86 (p.48) — Spiral/helical stairs must comply with BS 5395-2 and be appropriate for escape use.

• BS 5395-2 — Type E required where stair serves public escape routes.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-ELECTRIC-METERS-STAIR-01

PASS Low Score: 0

Electricity meters and cupboards in protected stairways

Part: B1 • Family: Other • Severity: medium

No electricity meters located within protected stairway (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 3, para 3.79 (p.47) — In single-stair buildings, electricity meters in protected stairs should be in securely locked cupboards separated from the escape route by fire-resisting construction.

B1-EXIT-SIGNAGE-01

PASS Low Score: 0

Exit signage on escape routes

Part: B1 • Family: Other • Severity: medium

Exit signage rule not applicable (door not part of escape route or is main entrance)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 5, para 5.28 (p.241) — Every doorway or exit providing access to a means of escape should be marked with appropriate escape route signage.

• BS ISO 3864-1 / BS 5499 — Escape route signs must comply with recognised graphical symbol standards.

B2-LININGS-CLASS-SMALL-ROOMS-01

PASS Low Score: 0

Wall and ceiling linings classification for small rooms threshold

Part: B2 • Family: Other • Severity: medium

Qualifying small room: wall and ceiling linings meet at least D-s3,d2

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 6, Table 6.1 (p.55) — Small rooms: max internal floor area 4m² (residential) or 30m² (non-residential) may use D-s3,d2 linings.

• Vol 2, Section 6, para 6.1 (p.55) — Surface linings of walls and ceilings should meet Table 6.1 classifications.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B2-LININGS-LOWER-PERFORMANCE-AREA-LIMITS-01

PASS Low Score: 0

Limited areas of lower-performance wall linings in rooms – area limits

Part: B2 • Family: Other • Severity: medium

Circulation space (use circulation-linings rule instead; not applicable here)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 6, para 6.4 (p.55) — Parts of walls in rooms may be lower than Table 6.1 but no worse than D-s3,d2; total area < 0.5 × room floor area, capped at 20m² (res) or 60m² (non-res).

B2-LININGS-LOWER-PERFORMANCE-CLASS-FLOOR-01

PASS Low Score: 0

Lower-performance wall lining allowance – minimum class floor

Part: B2 • Family: Other • Severity: medium

Lower-performance allowance not applied (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 6, para 6.4 (p.55) — Where a portion of wall lining is below the Table 6.1 class, the lower-performance lining must be no worse than D-s3,d2 and must comply with the area limits in para 6.4.

B3-CAVITY-EXTENSIVE-EXCEPTIONS-01

PASS Low Score: 0

Cavity barrier dimension table exceptions must be satisfied if relied upon

Part: B3 • Family: Other • Severity: medium

No cavity dimension exception claimed (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 9, para 9.10 (a–d) — Certain cavities may be excluded from Table 9.1 limits only where specific construction/usage conditions are satisfied.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-CAVITY-ROOF-SHEET-01

PASS Low Score: 0

Double-skinned insulated profiled roof sheeting: cavity barriers depend on insulation contact

Part: B3 • Family: Other • Severity: medium

Roof type not double-skinned insulated profiled sheeting (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 9, Diagram 9.4 (see para 9.8) — In double-skinned insulated profiled roof sheeting, concealed cavities may require cavity barriers unless insulation fully closes the void by contacting both skins.

B5-V1-ACCESS-WIDTH-01

PASS Low Score: 0

Access route width, clearance and turning for fire appliances

Part: B5 • Family: Other • Severity: medium

Appliance access not required

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 11, paras 11.5–11.7 — Access routes for fire appliances must meet minimum width, turning and clearance requirements.

B1-V1-FLATS-BS9991-MODIFICATION-01

PASS Low Score: 0

Flats (common escape routes): para 3.27 may be modified using BS 9991 clause 7.3

Part: B1 • Family: Other • Severity: medium

Not flats (rule not applicable).

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 3, para 3.29 — Paragraph 3.27 may be modified using the guidance in clause 7.3 of BS 9991.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B2-LININGS-WALL-DEFINITION-GLAZING-SLOPES-01

PASS Low Score: 0

Definition of wall linings includes glazing and steep ceiling slopes

Part: B2 • Family: Other • Severity: low

No glazing (wall surfaces) or steep ceiling slopes detected (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 6, para 6.2 (p.55) — For lining classification purposes, a 'wall' includes internal/external glazing (except glazing in doors) and any part of a ceiling sloping >70° from horizontal.

B2-LININGS-WALL-EXCLUSIONS-TRIMS-01

PASS Low Score: 0

Items excluded from wall lining classification (doors, frames, trims, furniture)

Part: B2 • Family: Other • Severity: low

Element is not in the excluded-items list (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 6, para 6.3 (p.55) — For B2 lining classification, 'walls' do not include doors/door frames, window frames/frames holding glazing, architraves/cover moulds/picture rails/skirtings and similar narrow members, or fitted furniture.

B2-LININGS-CEILING-DEFINITION-GLAZED-01

PASS Low Score: 0

Definition of ceiling linings includes glazed surfaces

Part: B2 • Family: Other • Severity: low

No glazed ceiling surfaces detected (rule not applicable)

Compliance
No mitigation required (PASS).

References
• Vol 2, Section 6, para 6.5 (p.55) — For B2 lining classification purposes, a ceiling includes glazed surfaces; assess glazed ceiling areas as part of ceiling lining classification.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-V1-FLATS-STRUCT-EXCLUSIONS-LOWEST-PLATFORM-CURTAIN-01

PASS Low Score: 0

Flats: exclusions from 'element of structure' (lowest floor, platform floors, non-load-transmitting external walls)

Part: B3 • Family: Other • Severity: low

Building is not flats (rule not applicable)

Compliance

No mitigation required (PASS).

References

• Vol 1, Section 6, para 6.2(b) (p.57) — The lowest floor of the building is excluded from the definition of 'element of structure'.

• Vol 1, Section 6, para 6.2(c) (p.57) — A platform floor is excluded from the definition of 'element of structure'.

• Vol 1, Section 6, para 6.2(d) (p.57) — External walls (e.g., curtain walls/cladding) that transmit only self-weight and wind loads (not floor loads) are excluded from 'element of structure'.

Vehicle Access

2 item(s) • PASS

B5-VEHICLE-ACCESS-01

PASS Low Score: 0

Fire service vehicle access route compliance

Part: B5 • Family: Vehicle Access • Severity: high

Fire service vehicle access route appears adequate based on available width, turning, hardstanding and obstruction information.

Compliance

No mitigation required (PASS).

References

• Vol 2, Section 15 — Fire and rescue service vehicle access, including route width, turning, hardstanding and obstruction.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B5-V1-VEHICLE-ACCESS-01

PASS Low Score: 0

Fire service vehicle access to dwellinghouses

Part: B5 • Family: Vehicle Access • Severity: high

Appliance access not required for this dwelling

Compliance
No mitigation required (PASS).

References
• Vol 1, Section 11, paras 11.2–11.7 — Dwellinghouses should be accessible to fire appliances where necessary; hose distance typically limited to 45m.

• Vol 1, Table 11.2 — Access route width, turning and hardstanding requirements.

Missing Information

External Wall / Reg 7

2 item(s) • UNKNOWN

B4-EXTWALL-ACM-01

UNKNOWN Medium Score: 55

ACM cladding risk check for external wall systems

Part: B4 • Family: External Wall / Reg 7 • Severity: critical

ACM is indicated, but non-combustible classification evidence is also indicated and should be checked carefully.

Missing info / action
• Confirm whether ACM is present in the external wall system.

• Remove or replace ACM components where non-compliant.

• Provide clear non-combustible classification evidence if relied upon.

• Submit a clearer wall-system specification and material breakdown.

References
• Vol 2, B4 / Reg 7 route — ACM in external wall systems is a high-risk facade condition and should be clearly evidenced as compliant or non-compliant.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B4-EXTWALL-HPL-01

UNKNOWN Medium Score: 55

HPL cladding risk check for external wall systems

Part: B4 • Family: External Wall / Reg 7 • Severity: critical

HPL is indicated, but non-combustible classification evidence is also indicated and should be checked carefully.

Missing info / action

- Confirm whether HPL is present in the external wall system.
- Remove or replace HPL components where non-compliant.
- Provide clear non-combustible classification evidence if relied upon.
- Submit a clearer wall-system specification and material breakdown.

References

- Vol 2, B4 / Reg 7 route — HPL in external wall systems is a high-risk facade condition and should be clearly evidenced as compliant or non-compliant.

Other

151 item(s) • UNKNOWN

B1-TRAVEL-DIST-SINGLE-DIR-01

UNKNOWN Medium Score: 55

Maximum travel distance where escape is initially in one direction

Part: B1 • Family: Other • Severity: critical

Missing twoDirectionsAvailableFlag

Missing info / action

- Confirm whether escape is initially only possible in one direction (before a point of choice).
- Measure the travel distance to the first point where two directions of escape become available.
- Check the applicable Table 2.1 limit based on purpose group and hazard level.
- If distance exceeds the limit, reconfigure layout, add an additional exit, or provide an alternative route so the point of choice occurs earlier.

References

- Vol 2, Section 2, Table 2.1 — Limits travel distance where escape is initially in one direction (purpose group + hazard level dependent).
- Vol 2, Section 2, paras 2.3–2.7 — Travel distance limits guidance and application to routes/points of choice.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-SINGLE-STAIR-ACCEPTABLE-01

UNKNOWN Medium Score: 55

Acceptability of relying on a single escape stair (height/area/use exceptions)

Part: B1 • Family: Other • Severity: critical

Missing numberOfStaircases

Missing info / action

• Confirm the number of independent escape stairs serving the building/part.

• If relying on a single stair, check Section 3 exceptions against top storey height, largest storey area and purpose group.

• If outside the exceptions, provide an additional independent escape stair OR commission a robust fire engineering assessment to justify the arrangement.

• Document assumptions, calculations and justification in the fire strategy pack.

References

• Vol 2, Section 3, para 3.3 — Single escape stair only acceptable within stated limits for height/storey size/use

B1-DW-ALARM-MIN-01

UNKNOWN Medium Score: 55

Domestic alarm provision in dwellings

Part: B1 • Family: Other • Severity: critical

Missing dwellingType (cannot assess domestic alarm requirement)

Missing info / action

• Confirm building is classified as dwelling (house or flat).

• Install Grade D2 (or better) alarm system with mains power and standby supply.

• Provide at least Category LD3 coverage (escape routes minimum).

• Ensure system is designed, installed and commissioned per BS 5839-6.

References

• Vol 1, Section 1, paras 1.1–1.4 — Dwellings should have Grade D2 LD3 fire alarm systems with mains power and standby supply.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-STRUCT-GLOBAL-01

UNKNOWN Medium Score: 55

Primary structure fire resistance (Table B4)

Part: B3 • Family: Other • Severity: critical

elementFrMinutes missing

Missing info / action

• Confirm purpose group classification and top storey height used for Table B4 selection.

• If unsprinklered option is 'Not permitted' for the height band, add sprinklers or change height/ compartmentation strategy.

• Upgrade fire protection to primary elements (tested boards/spray/encasement) to meet the required minutes.

• Record structural fire strategy assumptions and evidence in the fire strategy pack.

References

• Vol 2, Section 7, Table B4 (p.131) — Minimum periods of fire resistance by purpose group, height and sprinkler provision

B3-DW-PARTY-WALL-01

UNKNOWN Medium Score: 55

Compartment walls between dwellinghouses (party walls)

Part: B3 • Family: Other • Severity: critical

partyWallPresentFlag missing.

Missing info / action

• Confirm party wall locations between attached dwellings (terrace/semi).

• Ensure the party wall is continuous full height (foundation to underside of roof / through roof void where required).

• Provide correct roof junction detailing: fire-stopping at junctions or provide an upstand/parapet solution per AD B diagrams.

• Identify and seal any service penetrations through the party wall using tested fire-stopping systems.

References

• Vol 1, Section 5, paras 5.5, 5.10–5.15 — Walls separating dwellinghouses to act as compartment walls running full height and through roof space.

• Vol 1, Section 5, Diagram 5.2 — Typical party wall / roof junction detailing and continuity guidance.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B5-SHAFT-COVERAGE-01

UNKNOWN Medium Score: 55

Firefighting shaft coverage and hose distances

Part: B5 • Family: Other • Severity: critical

hoseDistanceMax_m missing

Missing info / action

- Review firefighting shaft and fire main outlet positions.
- Ensure hose laying distances do not exceed 45 m.
- Provide additional firefighting shafts where required.
- Reposition shafts or fire main outlets to improve coverage.

References

- Vol 2, Section 17, paras 17.2–17.8 — Firefighting shafts and fire mains must provide adequate hose coverage.

B1-GAS-IN-STAIR-01

UNKNOWN Medium Score: 55

Gas service and installation pipes in protected stairways

Part: B1 • Family: Other • Severity: critical

protectedStairFlag missing

Missing info / action

- Remove gas pipes from protected stairways wherever possible.
- Re-route gas services outside stair enclosures.
- Where unavoidable, provide enclosed, fire-protected and ventilated service shafts.
- Ensure installation complies with relevant gas and fire safety standards.

References

- Vol 2, Section 3, para 3.39 (p.49) — Gas services should not be located in protected stairways.
- Vol 2, Section 8, paras 8.36–8.38 (p.83) — Where unavoidable, strict fire protection and shaft separation required.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-DW-BASEMENT-HABITABLE-ESCAPE-01

UNKNOWN Medium Score: 55

Basement habitable rooms require direct escape or protected stair to final exit (Vol 1, para 2.16)

Part: B1 • Family: Other • Severity: critical

basementHabitableRoomsFlag missing

Missing info / action

• Provide an emergency escape window or external door directly from the basement (para 2.10).

• If using a stair route, enclose the stair as a protected stairway (para 2.5a) and ensure it leads to a final exit.

• Document the discharge arrangement and confirm the basement escape route is not dependent on non-protected circulation.

• Update the fire strategy and drawings to clearly show compliant basement escape.

References

• Vol 1, Section 2, para 2.16 (p.17) — Basement storeys with habitable rooms need either an escape window/external door (para 2.10) or a protected stairway (para 2.5a) to a final exit.

• Vol 1, Section 2, para 2.10 (p.15) — Emergency escape window / external door criteria.

B1-FLATS-COMMON-SINGLE-STAIR-11M-01

UNKNOWN Medium Score: 55

Small single-stair blocks of flats ≤11m (when permitted) (Vol 1, para 3.28; Diagram 3.9)

Part: B1 • Family: Other • Severity: critical

numberOfStaircases missing

Missing info / action

• If any criterion is not met, do not rely on a single common stair: provide a second independent escape stair or adopt a fire-engineered solution.

• If the stair connects to a covered car park, provide compliant separation or ensure the car park is open-sided as required.

• Provide compliant lobby smoke ventilation or mechanical smoke control to the stair/lobbies.

• Ensure any fire service ventilation provisions and remote operation arrangements meet the chosen strategy.

References

• Vol 1, Section 3, para 3.28 — Single common escape stair in blocks of flats only permitted for limited low-rise cases with additional smoke-venting/limitations.

• Vol 1, Section 3, Diagram 3.9 — Diagram 3.9 conditions for when a single common stair may be used.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-FLATS-COMMON-AOV-OMITTED-LOBBY-01

UNKNOWN Medium Score: 55

Small single-stair blocks: AOV required where lobby is omitted (Diagram 3.9 note 3)

Part: B1 • Family: Other • Severity: critical

numberOfStaircases missing

Missing info / action

• Provide an AOV at the head of the stair with geometric free area ≥1.0 m².

• Ensure the AOV is triggered by smoke detection within the stair at any storey.

• If AOV requirements cannot be met, reinstate a compliant lobby arrangement.

References

• Vol 1, Diagram 3.9 note 3 — Where lobby between stair and flats is omitted (Diagram 3.9(b)), provide AOV at head of stair with ≥1.0 m² geometric free area, triggered by smoke detection in stair at any storey.

B1-FLATS-COMMON-TRAVELDIST-TABLE3_1-01

UNKNOWN Medium Score: 55

Common escape routes from flats – travel distance compliance (Table 3.1; para 3.32; Diagrams 3.7–3.8)

Part: B1 • Family: Other • Severity: critical

commonEscapeTravelDistanceM missing

Missing info / action

• Reconfigure corridor geometry to reduce travel distance and dead-end lengths.

• Add corridor subdivision (cross-corridor) fire doors where required by the relevant diagram.

• Provide an additional common stair/alternative exit route if geometry cannot be brought within Table 3.1.

• Select and document the correct arrangement diagram and apply its constraints consistently.

References

• Vol 1, Section 3, para 3.32 — Travel distance from flat entrance doors to final exit via common routes must meet Table 3.1 limits.

• Vol 1, Table 3.1 — Sets common escape route travel distance limits (depends on arrangement and dead-end conditions).

• Vol 1, Diagrams 3.7–3.8 — Diagram constraints for common corridors/lobbies (dead ends, subdivision doors, arrangements).

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-FLATS-COMMON-CORRIDOR-PROTECTION-REI30_60-01

UNKNOWN Medium Score: 55

Common corridors as protected corridors + flat-to-corridor compartmentation (REI 30/60) (Vol 1, para 3.34)

Part: B1 • Family: Other • Severity: critical

commonCorridorPresent missing

Missing info / action

• Treat common corridor as a protected corridor: upgrade enclosure construction and openings/doorsets to a protected route standard.

• Upgrade flat-to-corridor wall construction to meet minimum compartment rating: REI 30 (≤5 m) or REI 60 (>5 m).

• Verify doorsets, seals, and penetrations maintain the required fire resistance.

References

• Vol 1, Section 3, para 3.34 — Common corridors serving flats must be protected; flat-to-corridor walls are compartment walls with minimum REI depending on top storey height.

B3-STRUCT-FRAME-HEIGHT-01

UNKNOWN Medium Score: 55

Minimum fire resistance of structural frame by building height

Part: B3 • Family: Other • Severity: critical

sprinklersProvided missing (needed for Table B4)

Missing info / action

• Confirm purpose group classification and whether sprinklers are provided (as assumed in the fire strategy).

• Confirm top floor height above ground (and basement depth if applicable) using Appendix D measurement conventions.

• Lookup the Table B4 minimum period and ensure the structural frame fire protection specification meets/exceeds it.

• If short, revise fire protection to achieve the required minutes (e.g., upgraded protection system or member protection strategy).

References

• Vol 2, Requirement B3 (Structure), Section 7, para 7.1 (p.63) — Loadbearing elements (including structural frame) should have minimum fire resistance per Appendix B (Tables B3/B4).

• Vol 2, Appendix B, Table B4 (p.146) — Minimum periods of fire resistance depend on purpose group, sprinklers, top floor height above ground, and basement depth.

• Vol 2, Appendix B, para B26 (application of Table B4) (p.148) — When applying Table B4, use the appropriate height/depth bands and apply the higher requirement where relevant (e.g., floor over basement note).

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B4-UNPROTECTED-AREAS-01

UNKNOWN Medium Score: 55

Limits on unprotected areas in external walls (openings)

Part: B4 • Family: Other • Severity: critical

boundaryDistance_mm missing/invalid

Missing info / action

• Confirm the relevant boundary location and whether a notional boundary is being applied.

• Calculate the wall face geometry/height and total unprotected opening area for the elevation.

• Use ADB Vol 2 Section B4 method/tables/diagrams to determine the maximum permitted unprotected area.

• If openings exceed the permitted limit: reduce opening area, increase boundary distance, or redesign façade layout.

References

• Vol 2, Section 10, paras 10.7–10.9 (p.90) — Openings in external walls must be limited to control fire spread to adjacent buildings or boundaries; maximum allowable unprotected area depends on distance, wall geometry and elevation characteristics

B5-FIREFIGHTING-LIFT-01

UNKNOWN Medium Score: 55

Firefighting lift provided where required (BS EN 81-72)

Part: B5 • Family: Other • Severity: critical

firefightingShaftRequired missing

Missing info / action

• Confirm whether firefighting shafts are required for the building configuration/height.

• Provide a firefighting lift where required and locate it within the firefighting shaft.

• Specify the lift to comply with BS EN 81-72 and retain evidence (specification, certificates).

• Ensure the lift is accessible from the protected lobby and coordinated with firefighting stair/shaft layout.

References

• Vol 2, Section 15, paras 15.10–15.12 (p.113) — Where firefighting shafts are required, a firefighting lift is typically required; lifts should meet BS EN 81-72 and be located within the firefighting shaft.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-V1-FLATS-CONV-4PLUS-FULLSTANDARD-01

UNKNOWN Medium Score: 55

Conversion to flats (≥4 storeys): full Appendix B fire resistance standard is necessary

Part: B3 • Family: Other • Severity: critical

isConversionToFlats missing

Missing info / action

• Confirm storey count is 4 or more (concession in para 6.6 no longer applies).

• Determine the required minimum period from Appendix B (Table B4) using height of top floor and sprinkler status.

• Upgrade structural fire protection to meet the Appendix B minimum periods across relevant elements of structure.

• Attach structural fire assessment and evidence (test/assessment reports, drawings) demonstrating compliance.

References

• Vol 1, Section 6, para 6.7 (p.58) — In a converted building with four or more storeys, the full standard of fire resistance given in Appendix B is necessary.

B3-V1-COMP-SEMI-DETACHED-TERRACE-SEPARATION-01

UNKNOWN Medium Score: 55

Semi-detached and terraced dwellinghouses: treat as separate buildings with a compartment wall between them

Part: B3 • Family: Other • Severity: critical

isSemiDetachedOrTerraced missing

Missing info / action

• Confirm the dwelling is semi-detached or terraced.

• Identify the separating/party wall(s) between dwellings.

• Specify/construct each separating wall as a compartment wall in line with paras 5.8–5.12.

• Keep evidence (details/spec, site photos, fire strategy statement).

References

• Vol 1, Section 5, para 5.5 (p.51) — Semi-detached/terraced dwellinghouses should be considered separate buildings; every separating wall should be a compartment wall (see paras 5.8–5.12).

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B4-V1-EXT-WALLS-01

UNKNOWN Medium Score: 55

External walls to dwellings resist fire spread

Part: B4 • Family: Other • Severity: critical

externalWallReactionToFireClass missing

Missing info / action

• Confirm building height/use and whether it is a 'relevant building' for external wall material restrictions.

• Specify an external wall build-up with appropriate reaction-to-fire performance for the building height and use.

• Reduce/avoid combustible materials and unmanaged cavities in the external wall system.

• Check proximity to boundaries and assess risk of fire spread to adjacent buildings; retain site plan evidence.

References

• Requirement B4(1) (p.76) — External walls should adequately resist fire spread over the walls and from one building to another, having regard to height, use and position.

• Vol 1, B4 Intention (Resisting fire spread over external walls) (p.78) — External envelope should not contribute to undue fire spread; extent depends on height and use.

• Vol 1, Section 10: Resisting fire spread over external walls (Introduction) (p.79) — External walls should

B4-V1-BOUNDARY-SEPARATION-01

UNKNOWN Medium Score: 55

Separation distance between dwelling and boundary (space separation)

Part: B4 • Family: Other • Severity: critical

Missing boundary distance, building height, or unprotected area

Missing info / action

• Increase separation distance to the relevant boundary (set back the elevation).

• Reduce unprotected area (reduce/relocate openings; add fire-resisting construction).

• Provide evidence: site plan, elevations, and openings schedule to support the space separation assessment.

References

• Requirement B4(1) — External walls must resist fire spread from one building to another, having regard to height, use and position.

• Vol 1, Section 10 – Space separation — Space separation guidance relates boundary distance to unprotected area and height (elevation-based assessment).

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-DW-ESC-GROUND-HABITABLE-01

UNKNOWN Medium Score: 55

Dwellinghouse: ground storey habitable rooms need hall-to-final-exit or emergency escape window/door

Part: B1 • Family: Other • Severity: critical

habitableRoomAtGroundStoreyFlag missing

Missing info / action

• Provide direct hall-to-final-exit arrangement for the room, OR

• Install compliant emergency escape window/door:

• - Minimum openable area ≥ 0.33m²

• - Minimum clear width and height ≥ 450mm

References

• Vol 1, Section 2, para 2.1 (p.22) — Ground storey habitable rooms should open onto a hall leading to a final exit.

• Vol 1, Section 2, para 2.10 (p.24) — Emergency escape windows/doors must meet minimum openable

B1-DW-ESCAPE-WINDOW-MIN-CRITERIA-01

UNKNOWN Medium Score: 55

Emergency escape windows/doors must meet minimum opening area, dimensions and sill height

Part: B1 • Family: Other • Severity: critical

emergencyEscapeWindowProvidedFlag / emergencyEscapeDoorProvidedFlag missing

Missing info / action

• Increase openable area to at least 0.33m² and ensure minimum 450mm clear height and width.

• Reduce sill height so the bottom of the openable area is not more than 1100mm above the floor.

• Confirm the escape route leads to a place of safety (e.g., safe external area/ground).

• Record dimensions and retain window/door evidence.

References

• Vol 1, Section 2, para 2.10 — Emergency escape windows should provide an unobstructed openable area ≥ 0.33m², with minimum 450mm height and width, and the bottom of openable area ≤ 1100mm above floor; escape should lead to a place of safety.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-MIN-EXITS-OCCUPANT-LOAD-01

UNKNOWN Medium Score: 55

Minimum number of exits required based on occupant load

Part: B1 • Family: Other • Severity: critical

occupantLoad missing

Missing info / action

• Confirm occupant load for the space/storey.

• Check if a single exit can safely accommodate the occupant load.

• If occupant load is high or single exit insufficient, provide at least two exits in alternative directions.

• Retain occupancy calculations and exit strategy documentation.

References

• Vol 2, Section 2 (Number of exits and occupant capacity guidance) — Where occupant numbers exceed the capacity of a single exit, additional exits must be provided so people can escape in alternative directions.

• Vol 2, Section 2, Table 2.3 — Exit widths determine the number of persons accommodated; multiple

B1-V2-PROTECTED-SHAFT-ENCLOSURE-PERFORMANCE-01

UNKNOWN Medium Score: 55

Protected shaft enclosure: fire-resisting construction per compartment wall/floor requirements

Part: B1 • Family: Other • Severity: critical

protectedShaftProvidedFlag missing

Missing info / action

• Confirm required compartment fire resistance rating for the building (based on height/use).

• Ensure shaft enclosure achieves at least the same fire resistance as compartment walls/floors.

• Maintain enclosure continuity through floors and at junctions.

• Provide tested fire-stopping systems to all service penetrations into the shaft.

References

• Vol 2, Section 7, para 7.23 (p.74) — Protected shafts should be enclosed with fire-resisting construction equivalent to the compartment wall/floor requirements for the building.

• Vol 2, Section 7, Diagram 7.2 (p.74) — Illustrates typical protected shaft enclosure arrangement.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-V2-CAVITY-BARRIERS-GENERAL-REQUIREMENT-01

UNKNOWN Medium Score: 55

Cavity barriers: general requirement to restrict smoke/flame spread in concealed spaces

Part: B1 • Family: Other • Severity: critical

concealedCavitiesPresentFlag missing

Missing info / action

• Identify all concealed cavities in walls, floors, roofs, and cladding systems.

• Provide cavity barriers to subdivide cavities at required locations (per Section 8).

• Ensure cavity barriers achieve required fire performance and are continuous.

• Retain construction details and fire test certification.

References

• Vol 2, Section 8, para 8.2 — Cavities in the construction should be subdivided with cavity barriers to prevent the unseen spread of fire and smoke

B1-V2-CAVITY-BARRIER-LOCATIONS-01

UNKNOWN Medium Score: 55

Cavity barriers: provide them at required locations to subdivide cavities and protect junctions/openings

Part: B1 • Family: Other • Severity: critical

concealedCavitiesPresentFlag missing

Missing info / action

• Identify cavity extents in walls/floors/roofs/cladding systems.

• Add cavity barriers at required locations (around openings, at compartment boundaries, at junctions/edges) per Section 8 diagrams and details.

• Ensure barriers are continuous and properly fixed/sealed.

• Retain layout drawings and construction details as evidence.

References

• Vol 2, Section 8, para 8.3 — Cavity barriers should be provided at key locations to subdivide cavities and close gaps (e.g., around openings, at compartment lines, and at junctions) in accordance with Section 8.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-V2-PROTECTED-ROUTE-CAVITY-BARRIER-01

UNKNOWN Medium Score: 55

Cavity barriers protecting a protected route (e.g., corridor/lobby/stair)

Part: B1 • Family: Other • Severity: critical

protectedRoutePresentFlag missing

Missing info / action

- Identify protected routes (stairs, corridors, lobbies).
- Check whether concealed cavities are adjacent to or form part of the enclosing construction.
- Install cavity barriers to prevent fire/smoke spread into the protected route.
- Ensure barriers are fire-resisting, continuous, and properly sealed.

References

- Vol 2, Section 8, para 8.5 — Where a protected escape route adjoins or is formed by construction containing cavities, cavity barriers should be provided to protect the route from unseen fire and smoke spread

B1-V2-PROTECTED-SHAFT-ENCLOSURE-PERFORMANCE-02

UNKNOWN Medium Score: 55

Protected shaft: doors and openings in enclosure must achieve required fire resistance and be self-closing where applicable

Part: B1 • Family: Other • Severity: critical

protectedShaftProvidedFlag missing

Missing info / action

- Identify all doors and openings in the protected shaft enclosure.
- Confirm required shaft fire resistance rating.
- Ensure doors achieve required fire resistance performance.
- Provide self-closing devices where required.

References

- Vol 2, Section 7 (Protected shafts – openings in enclosure) — Openings in protected shaft enclosures (e.g., doors, hatches) should maintain the required fire resistance of the shaft and generally be self-closing where required.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-V2-PIPES-FIRE-SEPARATING-ELEMENT-SEALING-01

UNKNOWN Medium Score: 55

Pipes passing through fire-separating elements must maintain fire resistance (sealing/collars/wraps as required)

Part: B1 • Family: Other • Severity: critical

pipePenetrationsThroughFireSeparatingElementFlag missing

Missing info / action

- Identify all pipe penetrations through fire-separating walls and floors.
- Provide tested fire-stopping systems or proprietary collars/wraps as appropriate.
- Ensure the system achieves at least the required fire resistance rating of the element.
- Retain product certification and installation evidence.

References

- Vol 2, Section 9 (Service penetrations through fire-separating elements) — Pipes passing through fire-separating walls and floors must be appropriately fire-stopped or fitted with suitable protection (e.g., collars/wraps) to maintain the fire resistance of the element.

B1-V2-FLUE-DUCT-WALL-FIRE-RESISTANCE-01

UNKNOWN Medium Score: 55

Flues and ducts in/through fire-separating elements must maintain required fire resistance

Part: B1 • Family: Other • Severity: critical

flueOrDuctThroughFireSeparatingElementFlag missing

Missing info / action

- Identify all flues and ducts passing through fire-separating walls and floors.
- Provide fire-resisting enclosure or proprietary fire-rated duct system achieving required rating.
- Fire-stop all penetrations to maintain integrity.
- Ensure tested performance equals or exceeds required fire resistance period.

References

- Vol 2, Section 9 (Flues and ducts passing through fire-separating elements) — Flues and ducts passing through fire-resisting walls and floors must not reduce the fire resistance of the element and should be appropriately protected or enclosed.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-V2-FLUE-DUCT-WALL-FIRE-RESISTANCE-02

UNKNOWN Medium Score: 55

Flue wall / duct containing flues: REI at least half the compartment wall/floor rating and class A1 construction

Part: B1 • Family: Other • Severity: critical

flueOrDuctContainingFluesPresentFlag missing

Missing info / action

• Confirm whether any flue/duct containing flues/appliance ventilation duct passes through or is built into a compartment wall/floor.

• Confirm the compartment wall/floor required fire resistance (minutes).

• Specify a flue/duct wall REI rating at least half that period.

• Ensure flue/duct wall is class A1 construction.

References

• Vol 2, Section 9, para 9.23 — Flue/duct wall fire resistance (REI) should be at least half of the compartment wall/floor it passes through or is built into; flue walls should be class A1 construction (Diagram 9.5).

• Vol 2, Section 9, Diagram 9.5 — Illustrates flues penetrating or built into compartment walls/floors and

B4-V2-MATERIAL-CHANGE-OF-USE-REG7-2-01

UNKNOWN Medium Score: 55

Material change of use: investigate external walls / specified attachments and upgrade to meet Regulation 7(2)

Part: B4 • Family: Other • Severity: critical

materialChangeOfUseFlag missing

Missing info / action

• Confirm the change of use is a ‘material change of use’ and that the building becomes a Reg 7(4) relevant building.

• Carry out and document an external wall / specified-attachments investigation (survey + materials identification + classifications).

• Where any non-exempt component is not A2-s1,d0 or A1, specify and complete remediation to achieve compliance.

• Retain evidence pack: survey report, product classifications, and remediation completion sign-off.

References

• Vol 2, Section 12, para 12.18 (p.287) — On material change of use so the building becomes a Reg 7(4) relevant building, external walls and specified attachments must be investigated and, where needed, works carried out to ensure only A2-s1,d0 or A1 materials except Reg 7(3) exemptions.

• Vol 2, Section 12, para 12.15 (p.287) — Explains when Regulation 7(2) applies (storey ≥18m + dwellings/institution/RRP) and requires A2-s1,d0 or A1 for materials forming external walls / specified attachments, except Reg 7(3) exemptions.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-ALARM-AUTODET-UNSUPERVISED-01

UNKNOWN Medium Score: 45

Automatic detection in unsupervised risk areas adjacent to escape routes

Part: B1 • Family: Other • Severity: high

staffPresencePattern missing

Missing info / action

• Identify unsupervised/rarely visited risk rooms (plant, storage, voids) in the fire strategy / space schedule.

• Confirm whether they are adjacent/near escape routes or could affect occupied areas.

• Where detection is absent, add appropriate smoke/heat detectors and link them to the main alarm system.

• Update cause-and-effect matrix and retain commissioning / design evidence.

References

• Vol 2, Section 1, paras 1.5–1.7 (p.198) — Unsupervised/rarely visited rooms that could threaten escape routes should have automatic detection

B1-TRAVEL-DIST-TWO-DIR-01

UNKNOWN Medium Score: 45

Maximum travel distance where two alternative directions of escape are available

Part: B1 • Family: Other • Severity: high

Missing twoDirectionsAvailableFlag

Missing info / action

• Confirm that two independent directions of escape are available from the relevant points.

• Measure travel distance to the nearest storey exit (or relevant exit point) per your method statement.

• Check the applicable Table 2.1 limit for 'escape in more than one direction' based on purpose group and hazard level.

• If distance exceeds the limit, provide additional exits or re-route/shorten travel so a compliant exit is reached within Table 2.1.

References

• Vol 2, Section 2, Table 2.1 — Limits travel distance where more than one direction of escape is available (purpose group + hazard level dependent).

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-OCCUPANCY-NUMBER-EXITS-01

UNKNOWN Medium Score: 45

Number of exits vs occupant load (Table 2.2)

Part: B1 • Family: Other • Severity: high

Missing spaceMaxOccupancy

Missing info / action

• Confirm the design occupant load for the room/tier/storey under fire conditions.

• Count independent exits available from that space (as defined in your fire strategy and drawings).

• If occupant load exceeds thresholds without sufficient exits, add exits/routes or reduce allowable occupancy with management controls.

• Document occupant load and exit provision in the fire strategy pack.

References

• Vol 2, Section 2, Table 2.2 — Number of exits increases with occupant load

B1-INNER-ROOM-GENERAL-01

UNKNOWN Medium Score: 45

Inner rooms: access room safeguards (no special hazard, vision or detection)

Part: B1 • Family: Other • Severity: high

Missing innerRoomFlag

Missing info / action

• Identify all inner room arrangements (escape via access room only).

• Confirm the access room is not a place of special fire hazard (e.g., higher-risk room).

• Provide either direct vision from inner room to access room (vision panels/open head) OR install automatic smoke detection in the access room linked to the alarm system.

• If still non-compliant, provide an independent escape route or reconfigure the layout to remove the inner-room condition.

References

• Vol 2, Section 2, paras 2.11–2.12 — Inner rooms need safeguards so a fire in the access room is quickly apparent and occupants are not trapped.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-DOOR-FASTENINGS-ESCAPE-01

UNKNOWN Medium Score: 45

Door fastenings on escape routes: openable without key; panic hardware where needed; powered locks fail-safe

Part: B1 • Family: Other • Severity: high

Missing onEscapeRouteFlag

Missing info / action

• Identify all doors on escape routes and confirm opening requirements from the escape side.

• Replace key/code-dependent fastenings with single-action escape fastenings as needed.

• Where large occupant flows are expected, specify suitable panic hardware (EN 1125) or EN 179 where users are trained/familiar (with justification).

• For electrically locked doors, ensure fail-safe release, local manual override, and compliant interface with the fire alarm system (e.g., BS 7273-4).

References

• Vol 2, Section 5, paras 5.7–5.10 — Escape doors should be readily openable; panic hardware and fail-safe electrical locking where appropriate.

• BS EN 1125 — Panic exit devices for doors used by the public / where panic is likely.

B1-ESCAPE-LIGHTING-01

UNKNOWN Medium Score: 45

Emergency escape lighting to escape routes and critical spaces (Table 5.1 / BS 5266-1)

Part: B1 • Family: Other • Severity: high

Missing emergencyLightingPresent

Missing info / action

• Confirm which spaces are escape routes and which are Table 5.1 listed critical spaces.

• For toilet accommodation, confirm floor area against the 8 m² threshold.

• Where emergency lighting is missing, install/upgrade emergency lighting in accordance with BS 5266-1.

• Include testing/maintenance regime evidence in the fire strategy/operations pack.

References

• Vol 2, Section 5, paras 5.25–5.27 — Emergency lighting for escape routes and specified rooms/spaces.

• Vol 2, Section 5, Table 5.1 — Spaces that typically require emergency escape lighting.

• BS 5266-1 — Emergency lighting code of practice.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-REFUGE-PROVISION-01

UNKNOWN Medium Score: 45

Refuge provision and EVC for disabled occupants

Part: B1 • Family: Other • Severity: high

Missing requiresRefugesFlag

Missing info / action

- Confirm whether refuge provision is required based on building height and use.
- Provide refuge space at each protected stair where required.
- Install emergency voice communication (EVC) at refuge locations.
- Ensure EVC complies with BS 5839-9.

References

- Vol 2, Section 3, paras 3.48–3.52 — Refuges should be provided where occupants cannot use stairs unaided.

B1-STAIR-WIDTH-MIN-01

UNKNOWN Medium Score: 45

Minimum escape stair width vs occupant load

Part: B1 • Family: Other • Severity: high

Missing stairWidthMm

Missing info / action

- Increase stair width to required minimum.
- Redistribute occupants across additional stairs.
- Provide additional stairs.
- Review evacuation strategy.

References

- Vol 2, Table 3.1 — Minimum stair width for simultaneous evacuation
- Vol 2, Table 3.2 — Minimum stair width for phased evacuation

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-EXTERNAL-STAIR-PROTECTION-01

UNKNOWN Medium Score: 45

Protection of external escape stairs

Part: B1 • Family: Other • Severity: high

Missing externalStairFlag

Missing info / action

- Provide fire-resisting construction adjacent to external stairs.
- Install self-closing fire doors.
- Relocate external stair away from openings.
- Provide protected stair enclosure.

References

- Vol 2, paras 3.31–3.33 — External stairs must be protected from fire spread.
- Vol 2, paras 3.65–3.69 — Fire-resisting separation required for openings near external stairs.

B1-DW-ALARM-LARGE-01

UNKNOWN Medium Score: 45

Alarm systems in large dwellinghouses

Part: B1 • Family: Other • Severity: high

Missing dwellingType (cannot assess large dwellinghouse alarm requirement)

Missing info / action

- Confirm whether the dwelling qualifies as a large dwellinghouse (>200 m² storey area).
- Upgrade fire alarm system to Grade A if currently Grade D.
- Provide central control equipment and enhanced detection coverage.
- Document system design and certification per BS 5839-6.

References

- Vol 1, Section 1, paras 1.5–1.7 — Large dwellinghouses require higher specification Grade A alarm systems.
- BS 5839-6 — Grade A fire detection and alarm systems for large dwellings.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-DW-ALARM-EXTENSION-01

UNKNOWN Medium Score: 45

Alarms for new habitable rooms in extensions

Part: B1 • Family: Other • Severity: high

Missing workType and newHabitableRoomFlag

Missing info / action

• Confirm scope of works (extension/alteration/loft/basement conversion) and whether a new habitable room is created.

• Extend/upgrade the alarm system to meet current minimum standard across the entire dwelling (not only the new room).

• Update alarm layout drawings and specification to reflect extended coverage.

• Commission the updated system and retain certification/evidence.

References

• Vol 1, Section 1, paras 1.8–1.9 — Where new habitable rooms are created by extension/alteration, alarms must be installed/extended to maintain compliance throughout the dwelling.

B4-SPACE-SEPARATION-01

UNKNOWN Medium Score: 45

Space separation: limit external fire spread by distance to relevant boundary and unprotected area

Part: B4 • Family: Other • Severity: high

distanceToRelevantBoundary_mm missing/invalid

Missing info / action

• Confirm the relevant boundary and measure distance from the elevation to the boundary on the site plan.

• Reduce unprotected area (openings/glazing) or redesign elevation to comply.

• Increase fire resistance of relevant external wall elements where required by the method.

• Document calculations and assumptions in the fire strategy / compliance pack.

References

• Vol 2, Section 13 — Space separation guidance for external fire spread (use correct table/paragraph references if you want exact citations).

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-DW-ESC-HOUSE-UP-LE4_5-01

UNKNOWN Medium Score: 45

Escape from upper storeys up to 4.5m (dwellinghouse, single stair)

Part: B1 • Family: Other • Severity: high

storeyheightm missing

Missing info / action

• Confirm the upper storey height is ≤ 4.5m and the storey is served by a single stair.

• For each habitable room (excluding kitchens), provide either a compliant emergency escape window/ external door or direct access to a protected stairway enclosure.

• If relying on escape windows/doors, ensure they meet the AD B emergency escape opening requirements and lead to a place of safety.

• Record the solution on plans and in the fire strategy, with window/door schedules as evidence.

References

• Vol 1, Section 2, para 2.2 (p.21) — Upper storeys ≤4.5m with a single stair: habitable rooms (excluding kitchens) need escape window/door OR direct access to protected stair.

• Vol 1, Section 2, para 2.3 (p.21) — Two rooms may share a single escape window subject to access

B3-FIRESTOP-CEILING-VOID-01

UNKNOWN Medium Score: 45

Ceiling void fire-stopping and cavity barriers

Part: B3 • Family: Other • Severity: high

voidContinuous missing; cannot determine ceiling void continuity.

Missing info / action

• Inspect ceiling voids above compartments and escape routes.

• Install cavity barriers at compartment lines and escape corridors.

• Provide continuous fire-resisting ceiling construction (minimum EI 30 where required).

• Ensure cavity barrier installation matches approved fire strategy drawings.

References

• Vol 2, Section 9, paras 9.3–9.6, 9.9–9.12 (p.102) — Ceiling voids must not allow fire to bypass compartment walls; cavity barriers or fire-resisting ceilings required.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-DW-CAVITY-BARRIERS-01

UNKNOWN Medium Score: 45

Cavity barriers in dwellinghouse construction

Part: B3 • Family: Other • Severity: high

Insufficient information to confirm cavity barrier locations/coverage.

Missing info / action

• Identify all concealed cavities (external walls, party walls/compartment lines, floors, roofs, eaves).

• Detail cavity barriers at cavity edges and at junctions with compartment walls/floors (per AD B Section 5).

• Provide cavity barriers around openings (windows/doors) where cavities would otherwise bypass fire separation.

• Ensure barriers are continuous, correctly fixed, and compatible with the external wall construction system.

References

• Vol 1, Section 5, paras 5.16–5.24 — Cavity barriers to close/subdivide concealed cavities to restrict fire spread.

B3-CARPARK-VENT-01

UNKNOWN Medium Score: 45

Car park ventilation and structural fire measures

Part: B3 • Family: Other • Severity: high

carParkFlag missing.

Missing info / action

• Confirm whether car park qualifies as open-sided per AD B Section 11.

• For enclosed car parks, provide permanent natural ventilation openings totaling ≥1/40 of floor area, or mechanical ventilation achieving compliant air changes.

• Ensure mechanical ventilation ductwork has appropriate fire resistance where penetrating compartment boundaries.

• Document ventilation calculations and include in fire strategy.

References

• Vol 2, Section 11, paras 11.2–11.5 — Car parks require adequate ventilation to control smoke and heat.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-FINAL-EXIT-WIDTH-01

UNKNOWN Medium Score: 45

Final exit width vs escape route width

Part: B1 • Family: Other • Severity: high

Final exit width missing.

Missing info / action

• Compare the clear width of final exits with upstream escape route widths.

• Where exits are narrower than escape routes, widen the exit doors.

• Alternatively, reduce upstream flow or provide additional exits.

References

• Vol 2, Section 5, para 5.20 (p.238) — Final exits should have a clear width not less than the minimum width of the escape route they serve.

B1-FINAL-EXIT-HAZARD-PROXIMITY-01

UNKNOWN Medium Score: 45

Final exits near smoke outlets and high-risk rooms

Part: B1 • Family: Other • Severity: high

final_exit_location missing

Missing info / action

• Map final exit discharge points against basement smoke outlet locations and discharge directions.

• Relocate smoke outlets or final exits so evacuees are not exposed to smoke/heat discharge.

• Where adjacency to high-risk rooms exists, provide fire-resisting separation and protected lobbies where appropriate.

• Document decisions in the fire strategy and coordinate with MEP smoke extract design.

References

• Vol 2, Section 5, para 5.24 (p.50) — Final exits should be sited so evacuees are not exposed to smoke/outlets or other hazards near discharge.

• Vol 2, Section 18, paras 18.1–18.10 (p.123) — Basement smoke outlets / extract arrangements and considerations for outlet locations.

• Vol 2, Section 18, paras 18.1–18.10 (p.124) — Outlet locations should not compromise firefighting/escape arrangements; coordinate final exit discharge locations.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-ESCAPE-STAIR-MATERIAL-01

UNKNOWN Medium Score: 45

Escape stair construction materials (reaction-to-fire class)

Part: B1 • Family: Other • Severity: high

escape_stair_present_flag missing.

Missing info / action

• Confirm whether the stair is the only stair and how many storeys it serves; confirm whether any part is in a basement and whether it provides basement access to the final exit.

• Obtain reaction-to-fire classification evidence (Euroclass) for stair flights/landings and any applied finishes.

• Where classification is below the required minimum, redesign/upgrade to compliant non-combustible construction/linings or replace finishes with compliant systems.

• Record the evidence and assumptions in the fire strategy / compliance pack.

References

• Vol 1, Section 3, paras 3.82–3.83 (p.47) — If the only stair serves >3 storeys, is in a basement, or building has a storey ≥18 m above ground: require minimum Euroclass; basement-related conditions tighten to A2-s1,d0

B1-PROTECTED-STAIR-USE-01

UNKNOWN Medium Score: 45

Use of space within protected stairways

Part: B1 • Family: Other • Severity: high

protectedStairFlag missing

Missing info / action

• Remove combustible storage, plant equipment, or inappropriate uses from protected stairways.

• Relocate gas services or other hazardous systems outside the protected stair enclosure.

• Ensure protected stairways remain dedicated to escape and firefighting access only.

• Review fire strategy drawings to confirm stair enclosure integrity.

References

• Vol 2, Section 3, paras 3.38–3.39 (p.49) — Protected stairs should remain fire-sterile and free from storage or plant.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-LOBBY-PROTECTION-STAIRS-01

UNKNOWN Medium Score: 45

Requirement for protected lobbies/corridors to escape stairs

Part: B1 • Family: Other • Severity: high

Lobby/protected corridor provision not stated for para 3.34 triggers

Missing info / action

• Confirm whether any para 3.34 triggers apply (single stair, >=18m, phased evacuation, firefighting stair, 3.15b option).

• If triggered: add protected lobby/protected corridor protection to the escape stair at all storeys above ground (except top storey).

• If only triggers (a)-(c) apply: consider compliant smoke control (per para 3.15a) as an alternative and document it in the fire strategy.

• Update plans/fire strategy to show lobby layouts, door/fire-resistance standards, and smoke control (if used).

References

• Vol 2, Section 3, para 3.34 (p.229) — Protected lobbies/protected corridors should be provided at all storeys above ground (except top storey) in specified trigger situations.

• Vol 2, Section 3, paras 3.15a–3.15b (p.228) — Smoke control alternative may be used for triggers (a)–

B1-SHOP-STORE-ROOM-01

UNKNOWN Medium Score: 45

Separation of walk-in shop store rooms (or detection/sprinklers)

Part: B1 • Family: Other • Severity: high

is_walk_in_store_flag missing

Missing info / action

• Confirm whether the walk-in store room negatively affects means of escape (layout, travel distances, smoke spread potential).

• If it does: provide REI 30 separation between the store room and retail area, or provide automatic fire detection and alarm, or provide sprinklers.

• Record supporting evidence (plans, FR construction details, detection category/spec, sprinkler design) in the fire strategy pack.

References

• Vol 2, Section 5, para 5.46 (p.241) — Fully enclosed walk-in shop store rooms: provide REI 30 separation if they negatively affect means of escape, unless AFD/alarm or sprinklers are provided.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B4-BALCONY-CONSTRUCTION-RES-11M-01

UNKNOWN Medium Score: 45

Balcony combustibility in residential-purpose buildings ≥11m (Vol 2, para 12.11)

Part: B4 • Family: Other • Severity: high

balconyPresent missing

Missing info / action

• Confirm purpose group (1 or 2) and whether any storey is ≥11m (per Diagram D6 method).

• For balconies, choose compliance Route A (A1/A2-s1,d0 materials with only permitted exceptions) or Route B (REI30 A2 imperforate soffit + 300mm A2 band at compartment boundary where needed).

• Audit balcony floor/soffit/edge build-ups, especially at compartment lines; update specifications and details to remove combustible layers or add compliant protection/bands.

• Where Reg 7(2) applies, verify compliance against Reg 7(2) material restrictions in addition to ADB guidance.

References

• Vol 2, Section 12, para 12.11 (p.97) — Residential-purpose buildings (purpose groups 1 and 2) with storey ≥11m: balconies must meet Route A (A1/A2-s1,d0 with limited exceptions) OR Route B (REI30 A2 soffit + 300mm A2 band at compartment boundary if B-s1,d0 or worse extends beyond). Reg 7(2) prevails where applicable

B3-CAVITY-BARRIERS-JUNCTIONS-01

UNKNOWN Medium Score: 45

Cavity barriers at junctions, edges, and protected route interfaces (Vol 2, Section 9)

Part: B3 • Family: Other • Severity: high

Need barriersAtEdgesAndOpeningsFlag and barriersAtCompartmentJunctionsFlag

Missing info / action

• Identify all concealed cavities in external walls, internal walls, floors and roofs, including around openings and service penetrations.

• Add cavity barriers at cavity edges/around openings and at junctions with all compartment floors/walls and fire-resisting barriers.

• Check protected escape route enclosures: if not continuous to full height/underside of roof, provide cavity barriers on the enclosure line or adopt an EI30 fire-resisting ceiling approach where applicable.

• Update the fire-stopping/cavity barrier schedule and record as-built evidence.

References

• Vol 2, Section 9, paras 9.3–9.6; Diagram 9.1 (p.77) — Provide cavity barriers at edges/around openings; at junctions of cavities with compartment floors/walls and fire-resisting barriers; address protected escape route enclosure interfaces.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-DW-INNER-ROOMS-01

UNKNOWN Medium Score: 45

Permitted inner rooms in dwellinghouses (Vol 1, para 2.11)

Part: B1 • Family: Other • Severity: high

innerRoomFlag missing

Missing info / action

• Avoid inner rooms for habitable rooms where possible; redesign for direct access to hall/stair.

• If relying on 2.11(e), confirm storey height ≤4.5m above ground and provide a compliant emergency escape window (para 2.10).

• If relying on the gallery route, confirm the gallery complies with para 2.15.

• Do not use bedrooms as inner rooms under dwellinghouse guidance.

References

• Vol 1, Section 2, para 2.11 (p.15) — Inner room permitted only if it is kitchen / laundry-utility / dressing / bathroom-WC-shower / room on storey ≤4.5m with emergency escape window (para 2.10) / gallery complying with para 2.15.

• Vol 1, Section 2, para 2.10 (p.15) — Emergency escape window criteria (used for 2.11(e)).

B1-DW-GALLERY-ESCAPE-01

UNKNOWN Medium Score: 45

Gallery escape provisions in dwellinghouses (Vol 1, para 2.15; Diagram 2.6)

Part: B1 • Family: Other • Severity: high

galleryPresentFlag missing

Missing info / action

• Provide an alternative protected exit from the gallery level.

• If relying on window route, confirm floor ≤4.5m above ground and window complies with para 2.10.

• If relying on Diagram 2.6, verify travel distance, visibility, open-plan and geometry limits.

• Avoid single-direction escape galleries without compensatory measures.

References

• Vol 1, Section 2, para 2.15 (p.16) — Gallery must have alternative exit, emergency escape window (≤4.5m above ground), or comply with Diagram 2.6.

• Vol 1, Section 2, Diagram 2.6 (p.17) — Sets travel distance, visibility and geometry limits for single escape via gallery.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-FLAT-EMERGENCY-ESCAPE-WINDOW-01

UNKNOWN Medium Score: 45

Emergency escape windows / external doors in flats (Vol 1, Section 3, para 3.6)

Part: B1 • Family: Other • Severity: high

emergencyEscapeWindowPresent missing

Missing info / action

• Increase openable area to at least 0.33 m² and confirm minimum 450 mm x 450 mm clear opening.

• Lower the sill so the bottom of the openable area is no more than 1100 mm above the floor.

• Confirm the escape route from the opening reaches a place free from danger (not an enclosed/ inaccessible yard).

• If a compliant window/door cannot be achieved, revise the flat layout to provide an alternative compliant means of escape.

References

• Vol 1, Section 3, para 3.6(a)(i–iii) (p.20) — Escape window openable area ≥0.33m²; min 450mm high and 450mm wide; bottom of openable area ≤1100mm above floor.

• Vol 1, Section 3, para 3.6(b–d) (p.20) — Escape should reach a place free from danger; locks/stays

B1-FLAT-INNER-ROOM-PERMITTED-01

UNKNOWN Medium Score: 45

Permitted inner rooms within flats (Vol 1, Section 3, para 3.7)

Part: B1 • Family: Other • Severity: high

innerRoomFlag missing

Missing info / action

• Redesign to remove the inner-room condition by providing direct access to the hall/escape route.

• If relying on the ≤4.5m exception, provide a compliant emergency escape window per para 3.6.

• If relying on gallery conditions, verify the gallery arrangement meets the required criteria and document it.

• Avoid inner rooms for bedrooms and principal habitable rooms unless explicitly permitted by the rule conditions.

References

• Vol 1, Section 3, para 3.7 (p.21) — Inner rooms in flats allowed only for kitchen/laundry-utility/dressing/ bathroom-WC-shower, or storey ≤4.5m with emergency escape window (per 3.6), or compliant gallery arrangement.

• Vol 1, Section 3, para 3.6 (p.20) — Emergency escape window criteria referenced by 3.7.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-FLAT-INNER-INNER-ROOM-CONDITIONS-01

UNKNOWN Medium Score: 45

Conditions for inner-inner rooms in flats (Vol 1, Section 3, para 3.8)

Part: B1 • Family: Other • Severity: high

innerInnerRoomFlag missing

Missing info / action

• Remove the inner-inner dependency by re-planning circulation to provide direct access to the escape route.

• Ensure the underlying inner-room arrangement is permitted under para 3.7.

• Provide smoke alarms in every access room serving the inner-inner room.

• Do not use kitchens as access rooms to inner-inner rooms.

References

• Vol 1, Section 3, para 3.8 (p.21) — Inner-inner rooms in flats only acceptable where the inner-room arrangement is permitted (3.7), each access room has a smoke alarm, and no access room is a kitchen.

B1-FLAT-BASEMENT-HABITABLE-ESCAPE-01

UNKNOWN Medium Score: 45

Habitable basement rooms in flats (Vol 1, Section 3, para 3.9)

Part: B1 • Family: Other • Severity: high

basementHabitableRoomsFlag missing

Missing info / action

• Provide a compliant emergency escape window/external door from the basement in accordance with para 3.6.

• Or construct/upgrade the basement stair to minimum REI 30 protected enclosure.

• Ensure the protected stair discharges to a final exit.

References

• Vol 1, Section 3, para 3.9 (p.22) — Basement storeys with habitable rooms require either compliant emergency escape or a protected stair to a final exit.

• Vol 1, Section 3, para 3.6 (p.20) — Dimensional requirements for emergency escape windows.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-FLAT-BALCONY-FLATROOF-ESCAPE-REI30-01

UNKNOWN Medium Score: 45

Balconies/flat roofs forming part of escape in flats (Vol 1, Section 3, paras 3.10–3.12)

Part: B1 • Family: Other • Severity: high

escapeRouteOverFlatRoofFlag missing

Missing info / action

• Confirm the balcony/flat roof escape route is within the same building and discharges to a storey exit or external escape route.

• Upgrade the roof/balcony escape-route zone (including supporting structure) to minimum REI 30.

• Upgrade protection to any opening within 3m of the escape route to minimum REI 30 (or equivalent fire-resisting construction).

• If REI 30 cannot be achieved, revise the escape strategy to avoid reliance on balcony/flat roof escape.

References

• Vol 1, Section 3, paras 3.10–3.12 — Where a balcony/flat roof forms part of escape in flats: route must be within same building and lead to storey exit or external escape route; route zone (incl supporting structure) and openings within 3m should provide minimum REI 30.

B1-FLAT-GALLERY-CONDITIONS-01

UNKNOWN Medium Score: 45

Gallery escape provisions within flats (Vol 1, para 3.13; Diagram 3.1)

Part: B1 • Family: Other • Severity: high

galleryPresent missing

Missing info / action

• Provide an alternative exit from the gallery level.

• If relying on an emergency escape window/door, ensure gallery floor ≤4.5m above ground and opening complies with para 3.6.

• If relying on Diagram 3.1, verify geometry/visibility/open-area constraints and avoid risky cooking arrangements.

• Redesign the gallery to eliminate dead-end conditions where compliance cannot be achieved.

References

• Vol 1, Section 3, para 3.13 — Gallery within a flat needs alternative exit, or emergency escape opening if ≤4.5m above ground, or compliance with Diagram 3.1 conditions.

• Vol 1, Section 3, Diagram 3.1 — Sets geometric/visibility/open-area and cooking constraints for galleries relying on single escape.

• Vol 1, Section 3, para 3.6 (p.20) — Emergency escape window/door criteria referenced by 3.13.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-FLAT-ESCAPE-GROUNDSTOREY-HABITABLE-01

UNKNOWN Medium Score: 45

Escape provisions for ground-storey habitable rooms in flats (Vol 1, para 3.15)

Part: B1 • Family: Other • Severity: high

storeyIsGroundFlag or habitableRoomFlag missing

Missing info / action

- Re-plan the room layout to open directly onto a hall leading to the final exit.
- Provide a compliant emergency escape window in accordance with para 3.6.
- Provide a compliant external escape door where feasible.

References

- Vol 1, Section 3, para 3.15 — Ground-storey habitable rooms in flats must open to a hall leading to a final exit or have an emergency escape opening.
- Vol 1, Section 3, para 3.6 (p.20) — Emergency escape window/door dimensional requirements

B1-FLAT-ESCAPE-UPPERSTOREY-LE4_5-01

UNKNOWN Medium Score: 45

Escape provisions for upper storeys ≤4.5m in flats (Vol 1, paras 3.16–3.17)

Part: B1 • Family: Other • Severity: high

storeyIsUpperFlag / storeyHeightAboveGroundM / habitableRoomFlag missing

Missing info / action

- Provide a compliant emergency escape window/door to the habitable room (para 3.6).
- Or provide/upgrade a protected internal stair (minimum REI 30) and ensure the room has direct access to it.
- Revise internal doors/partitions so escape does not rely on passing through the protected stair enclosure in a non-compliant way.
- If neither route is feasible, redesign the unit layout to remove upper-storey habitable rooms without compliant escape.

References

- Vol 1, Section 3, paras 3.16–3.17 — Upper storeys of flats ≤4.5m: habitable rooms (excl kitchens) need emergency escape opening (3.6) or protected internal stair arrangement in multi-storey flats.
- Vol 1, Section 3, para 3.6 (p.20) — Emergency escape opening requirements referenced by 3.16–3.17.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-FLATS-COMMON-LOBBY-TRAVELDIST-4_5M-01

UNKNOWN Medium Score: 45

Small single-stair blocks: lobby travel distance limit (Diagram 3.9 notes; Diagram 3.7 note)

Part: B1 • Family: Other • Severity: high

isLobbyProvided missing

Missing info / action

• Reduce lobby travel distance via layout changes to ≤4.5 m.

• If relying on the 7.5 m allowance, provide compliant lobby smoke control and document it in the fire strategy.

• If neither is feasible, redesign to avoid a single-stair dependency or adopt an engineered solution.

References

• Vol 1, Diagram 3.9 notes — Small single-stair blocks: lobby between flat and stair has a travel distance limit.

• Vol 1, Diagram 3.7 note (7.5 m with smoke control) — Lobby travel distance can be extended to 7.5 m where smoke control is provided.

B1-FLATS-COMMON-STAIR-LOBBY-SECURITY-FASTENINGS-01

UNKNOWN Medium Score: 45

Common stair to lobby doors – avoid security fastenings (small single-stair blocks)

Part: B1 • Family: Other • Severity: high

numberOfStaircases missing

Missing info / action

• Remove security fastenings from the stair-to-lobby door.

• Ensure the door is readily openable from the escape side without key, code or special knowledge.

• If access control is required, use a fail-safe, escape-compliant release mechanism.

References

• Vol 1, Diagram 3.9 note — Door between common stair and lobby should be free from security fastenings; readily openable from escape side.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-FLATS-COMMON-FLATROOF-ESCAPE-REI30-01

UNKNOWN Medium Score: 45

Common escape route over flat roof – REI 30 and guarding (Vol 1, para 3.30)

Part: B1 • Family: Other • Severity: high

escapeRouteUsesFlatRoof missing

Missing info / action

• Provide alternative escape route that avoids roof travel.

• Upgrade roof construction (including supporting structure) to minimum REI 30.

• Upgrade openings within 3 m of the route to achieve minimum 30-minute fire resistance.

• Provide guarding/barriers along the escape route.

References

• Vol 1, Section 3, para 3.30 — Escape route over flat roof (as one of multiple routes) must meet REI 30 and guarding conditions

B1-FLATS-COMMON-NO-STAIR-TO-STAIR-PASSAGE-01

UNKNOWN Medium Score: 45

Common escape route should not pass through one stair enclosure to reach another (Vol 1, para 3.33)

Part: B1 • Family: Other • Severity: high

routePassesThroughStairEnclosure missing

Missing info / action

• Replan circulation so stairs are independent (no stair-to-stair passage through enclosures).

• Where connection is unavoidable, provide a compliant protected lobby between stairs with minimum REI 30 and appropriate fire doors.

• Document the arrangement clearly in the fire strategy and drawings.

References

• Vol 1, Section 3, para 3.33 — Escape route should not pass through one stair enclosure to reach another; permitted via protected lobby (min REI 30).

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-FLATS-COMMON-REVOLVING-AUTOMATIC-DOORS-FAILSAFE-01

UNKNOWN Medium Score: 45

Revolving/automatic doors or turnstiles on escape routes – failsafe or adjacent swing door (Vol 1, para 3.98)

Part: B1 • Family: Other • Severity: high

hasRevolvingDoor missing

Missing info / action

• Provide compliant failsafe operation for powered doors/turnstiles on the escape route (fail-safe to allow free outward egress).

• Provide monitored fail-safe release where required by the chosen system design.

• Install an adjacent escape-compliant outward-opening swing door of the required width.

References

• Vol 1, Section 3, para 3.98 — Revolving/automatic doors and turnstiles on escape routes must not obstruct escape; provide compliant failsafe operation or an adjacent escape-compliant swing door.

B1-DW-EXT-STAIR-FR-01

UNKNOWN Medium Score: 45

Fire resistance around external escape stairs in dwellinghouses (Vol 1, para 2.17; Diagram 2.7)

Part: B1 • Family: Other • Severity: high

externalEscapeStairPresent missing

Missing info / action

• Assess external stair arrangement against AD B Vol 1 para 2.17 and Diagram 2.7.

• Upgrade doors/openings adjacent to the stair to suitable fire performance where required (e.g., E30 doorsets, fire-stopping).

• Provide RE30 protection to adjacent envelope where required by the arrangement and protect/limit unprotected glazing; use E30 integrity glazing fixed shut where applicable.

• Provide a protected zone where required, and ensure the stair foot discharges to a protected route or has an alternative escape route.

References

• Vol 1, Section 2, para 2.17 — External escape stairs require protected openings/envelope so a fire does not compromise the stair/escape path.

• Vol 1, Diagram 2.7 — Typical external stair protection arrangements and protected zone concept.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-DW-LIFT-SHAFT-01

UNKNOWN Medium Score: 45

Passenger lift protection where serving storeys above 4.5 m (Vol 1, para 2.7)

Part: B1 • Family: Other • Severity: high

passengerLiftPresent missing

Missing info / action

• Confirm the highest storey served by the passenger lift (height above ground).

• If > 4.5 m, place the lift within the protected stair enclosure OR provide a dedicated fire-resisting lift shaft to at least REI 30, including fire-stopping at penetrations.

• Record shaft construction, doors/landing arrangements, and fire-stopping details in the fire strategy package.

References

• Vol 1, Section 2, para 2.7 — Passenger lifts serving storeys above 4.5m should be within protected stair enclosure or within a fire-resisting lift shaft (min REI/RF 30 as applicable).

R38-V1-HANDOVER-ESSENTIAL-01

UNKNOWN Medium Score: 45

Reg 38 handover: essential fire safety information (Vol 1, Section 17, paras 17.1–17.4)

Part: B5 • Family: Other • Severity: high

relevantChangeOfUseFlag missing

Missing info / action

• Confirm whether the project is a relevant building and/or a relevant change of use for Reg 38 handover purposes.

• Compile a fire safety handover pack including annotated as-built drawings and schedules for passive measures (compartmentation, cavity barriers, doorsets) and active systems (alarms, smoke control, suppression where present).

• Include inspection/testing/maintenance instructions and commissioning/certification evidence.

• Deliver the pack to the responsible person at completion/first occupation and record the handover.

References

• Vol 1, Section 17 (Regulation 38), paras 17.1–17.4 — On completion (or first occupation), essential fire safety information should be given to the responsible person for safe occupation/management.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-CAVITY-FIXING-01

UNKNOWN Medium Score: 45

Cavity barriers must be fixed to remain effective during movement and fire

Part: B3 • Family: Other • Severity: high

cavityBarrierFixingSpecified missing (cannot confirm fixing method is defined)

Missing info / action

• Specify tested/appropriate cavity barrier fixing methods (type, spacing, substrate) suitable for the barrier product and cavity construction.

• Fix cavity barriers to rigid/appropriate construction so they remain in place under movement and fire exposure.

• Where services run in cavities, ensure services are independently supported so collapse does not dislodge barriers.

• Inspect installation and keep evidence (photos, checklists); rectify loose, incomplete, or poorly-fixed barriers.

References

• Vol 2, Section 9, para 9.16 — Cavity barriers should be detailed/fixed so their performance is not made ineffective by movement, service collapse, fixing failure, or failure of abutting construction.

B4-BOUNDARY-ANGLES-01

UNKNOWN Medium Score: 45

Angle of exposure to boundaries (effective distance adjustment)

Part: B4 • Family: Other • Severity: high

boundaryDistance_mm missing/invalid

Missing info / action

• Identify whether any elevation is angled to the boundary or forms a corner condition relevant to fire exposure.

• Apply the ADB angle-of-exposure method to compute effective distance to boundary.

• Use the effective distance when calculating permitted unprotected area and required space separation.

• Record the calculation and assumptions (angle, geometry, boundary line) in the fire strategy pack.

References

• Vol 2, Section 10, para 10.10 (p.90) — Angle of exposure: effective distance to boundary should account for angled walls/corners when assessing fire spread and allowable unprotected area/space separation.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B5-FIRE-MAINS-COVERAGE-01

UNKNOWN Medium Score: 45

Fire main outlet coverage (hose reach to all parts of the building)

Part: B5 • Family: Other • Severity: high

hoseCoverageAllAreas missing (requires hose coverage assessment result)

Missing info / action

• Provide fire main outlets positioned in protected lobbies/firefighting shafts as appropriate.

• Ensure outlets are provided on each storey where required by the fire strategy.

• Run a hose coverage assessment on each storey to confirm all areas are reachable within permitted hose distances.

• Adjust outlet locations/add outlets if coverage is insufficient; retain layout drawings and assessment evidence.

References

• Vol 2, Section 16 (Fire mains) – outlet positioning / coverage guidance (p.116) — Fire main outlets should be positioned (e.g., in protected lobbies/firefighting shafts) so hose reach provides adequate coverage to all parts of each storey without exceeding permitted hose distances.

B5-FIREFIGHTING-LOBBY-01

UNKNOWN Medium Score: 45

Protected firefighting lobby arrangement (fire resistance + smoke control)

Part: B5 • Family: Other • Severity: high

firefightingShaftProvided missing

Missing info / action

• Provide protected firefighting lobbies within firefighting shafts at each storey where required.

• Ensure lobby enclosure/doors achieve the required fire resistance and are coordinated with the fire resistance schedule.

• Provide smoke control appropriate to the shaft/lobby arrangement and commission the system.

• Record lobby arrangement, fire resistance and smoke control evidence in the fire strategy pack.

References

• Vol 2, Section 15, paras 15.3–15.9 (p.112) — Firefighting lobbies (within firefighting shafts) protect firefighters from smoke/heat and provide a staging area; they should be fire-resisting and smoke controlled as required.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B5-WAYFINDING-SIGNAGE-11M-01

UNKNOWN Medium Score: 45

Wayfinding signage for blocks over 11m (floor and flat identification signage)

Part: B5 • Family: Other • Severity: high

wayfindingSignageProvided missing

Missing info / action

• Confirm the maximum storey height above ground/access level and whether any storey exceeds 11m.

• Provide floor identification signage in common parts at each level as required (clear, durable, legible).

• Provide flat/dwelling indication/numbering signage at entrances/landings as required to aid fire service wayfinding.

• Maintain a signage schedule and installation evidence aligned to the fire strategy.

References

• Vol 2, Section 15, paras 15.13–15.16 (wayfinding signage) + 2020/2022 amendments (p.113) — Blocks with storeys over 11m should provide floor identification and flat/dwelling indication signage in common parts to support fire service wayfinding.

B2-ROOFLIGHTS-PLASTIC-01

UNKNOWN Medium Score: 45

Plastic rooflights: minimum class D-s3,d2 only if limitations observed

Part: B2 • Family: Other • Severity: high

elementType missing

Missing info / action

• Confirm whether the rooflight is plastic/thermoplastic.

• Check compliance with relevant limitation tables.

• If limitations are not met, upgrade rooflight to meet required Table 4.1 classification.

References

• Vol 1, Section 4, para 4.7 (p.42) — Plastic rooflights may be minimum D-s3,d2 only where limitation tables are satisfied.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B2-THERMOPLASTIC-WINDOWS-01

UNKNOWN Medium Score: 45

Thermoplastic glazing to external windows: allowed to rooms, not to circulation spaces

Part: B2 • Family: Other • Severity: high

isExternalWindow missing

Missing info / action

• Confirm whether glazing is rigid thermoplastic (e.g., TP(a)).

• If window serves circulation space (corridor/lobby/stair), replace with compliant non-thermoplastic glazing system.

• Restrict rigid thermoplastic glazing to external windows serving rooms only.

References

• Vol 1, Section 4, para 4.13 (p.44) — TP(a) rigid thermoplastic glazing may be used for external windows to rooms but not for external windows to circulation spaces.

B2-THERMOPLASTIC-CEILINGS-TPA-FLEX-01

UNKNOWN Medium Score: 45

TP(a) flexible suspended/stretched-skin ceilings: max panel area and supported on all sides

Part: B2 • Family: Other • Severity: high

ceilingThermoplasticClass missing

Missing info / action

• If TP(a) flexible panels exceed 5 m², redesign panelisation to keep each panel ≤ 5 m².

• Ensure panels are fully supported on all sides (all edges) by suitable framing/support system.

• Attach ceiling spec, manufacturer datasheet, and drawings confirming panel sizes and edge supports.

References

• Vol 1, Section 4, para 4.17 (p.56) — TP(a) flexible ceiling panels: max area 5 m²; supported on all sides.

• Vol 1, Section 4, Table 4.2 (note on TP(a) flexible) (p.57) — TP(a) flexible diffusers/ceilings: use only in panels of max 5 m²; see para 4.17.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-V1-FLATS-STRUCT-SUPPORT-SAME-01

UNKNOWN Medium Score: 45

Flats: supporting/stabilising element must match the supported element's fire resistance

Part: B3 • Family: Other • Severity: high

supportsOrStabilises missing (need to know if element supports/stabilises another)

Missing info / action

• Identify which elements are supporting/stabilising others (e.g., bracing, transfer beams, frames supporting fire-resisting walls/floors).

• Confirm the supported element's required/achieved fire resistance period (minutes).

• Upgrade the supporting element's fire protection so its fire resistance is at least equal to the supported element.

• Attach calculations/assessments and marked-up drawings showing both elements and their fire resistance periods.

References

• Vol 1, Section 6, para 6.1 NOTE (p.57) — If one element of structure supports or stabilises another, the supporting element should have the same fire resistance as the other element (minimum).

B3-V1-FLATS-CONV-REVIEW-TIMBERFLOORS-01

UNKNOWN Medium Score: 45

Conversion to flats: review existing construction; retained timber floors may prevent meeting fire resistance

Part: B3 • Family: Other • Severity: high

isConversionToFlats missing

Missing info / action

• Carry out and document a review of existing construction as part of the conversion fire strategy.

• If timber floors are retained, provide a fire assessment and upgraded build-up details demonstrating compliance with the relevant fire resistance provisions.

• Attach survey/report evidence, floor build-up details, and any test/assessment reports supporting the achieved fire resistance.

References

• Vol 1, Section 6, para 6.5 (p.58) — When converting to flats, review existing construction; retained timber floors may make it difficult to meet fire resistance provisions.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-V1-FLATS-SPECIAL-FIRE-HAZARD-REI30-01

UNKNOWN Medium Score: 45

Flats: enclosures to places of special fire hazard should achieve minimum REI 30

Part: B3 • Family: Other • Severity: high

specialFireHazardPresent missing

Missing info / action

• Identify any places of special fire hazard and confirm they are fully enclosed with fire resisting construction.

• Specify an enclosure achieving at least REI 30 and retain test/assessment evidence for the proposed build-up.

• Confirm penetrations/openings (doorsets, services) maintain the enclosure performance and are detailed in the fire strategy/specification.

References

• Vol 1, Appendix B, Table B3 (Item 15a) (p.129) — Fire resisting construction enclosing places of special fire hazard should achieve minimum REI 30 (each side separately).

B3-V1-STRUCT-SUPPORTING-ELEMENT-01

UNKNOWN Medium Score: 45

Supporting structural elements must match the fire resistance of elements they support

Part: B3 • Family: Other • Severity: high

elementSupportsOther missing

Missing info / action

• Identify all cases where an element supports or stabilises another structural element.

• Set the supporting element fire resistance to be at least equal to the supported element requirement.

• Provide a structural fire assessment or specification evidence confirming ratings for both elements.

References

• Vol 1, Section 5, para 5.2 (p.50) — If one element of structure supports or stabilises another, the supporting element should have at least the same fire resistance as the other.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-V1-STRUCT-ROOF-MEMBERS-ESSENTIAL-STABILITY-01

UNKNOWN Medium Score: 45

Roof structural members essential to stability must achieve relevant fire resistance

Part: B3 • Family: Other • Severity: high

roofMemberIsStructuralStabilitySystem missing

Missing info / action

• Confirm whether the roof member is part of the building's primary structural stability system (not just roof load support).

• Determine the required fire resistance for the building circumstances (Appendix B / fire strategy / structural fire design).

• Upgrade protection/specification so the roof stability member achieves at least the required minutes of fire resistance.

• Record the basis and evidence (assessment/test/certification) in the structural fire report and fire strategy pack.

References

• Vol 1, Section 5, paras 5.2–5.3 (note) (p.51) — If roof members are essential to the building's structural stability system, they must demonstrate the relevant fire resistance (not merely roof support).

B3-V1-STRUCT-LOFT-CONVERSION-FLOOR-REI30-01

UNKNOWN Medium Score: 45

Loft conversion: new floor and enclosure to escape circulation space should achieve REI 30

Part: B3 • Family: Other • Severity: high

isLoftConversion missing

Missing info / action

• Confirm loft conversion introduces a new storey.

• Upgrade new floor construction to achieve minimum REI 30.

• Ensure floor forming part of escape route enclosure achieves REI 30.

• Provide specification/test/assessment evidence confirming performance.

References

• Vol 1, Section 5, para 5.4 (p.51) — In loft conversions creating an additional storey, the new floor should achieve minimum REI 30; floors forming part of the enclosure to escape circulation space should also achieve REI 30.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-V1-COMP-ATTACHED-GARAGE-SEPARATION-REI30-01

UNKNOWN Medium Score: 45

Attached/integral garages must be separated from the dwelling by REI 30 fire-resisting construction

Part: B3 • Family: Other • Severity: high

hasAttachedOrIntegralGarage missing

Missing info / action

- Confirm whether the garage is attached to or integral with the dwellinghouse.
- Specify/construct the wall and any floor between garage and dwellinghouse to achieve minimum REI 30.
- Ensure the REI 30 rating is evidenced for exposure from the garage side (Diagram 5.1).
- Retain drawings/specs/test evidence/photos in the fire strategy pack.

References

- Vol 1, Section 5, para 5.6; Diagram 5.1 (p.51) — If a garage is attached to or integral with a dwellinghouse, separate it from the dwellinghouse by fire-resisting construction (minimum REI 30) from the garage side

B3-V1-COMP-GARAGE-DOOR-FIRE-RESISTANCE-01

UNKNOWN Medium Score: 45

Door between garage and dwelling must be E 30 Sa and self-closing

Part: B3 • Family: Other • Severity: high

hasDoorBetweenGarageAndDwelling missing

Missing info / action

- Specify door achieving minimum E 30 fire integrity.
- Ensure door includes Sa-rated smoke seals.
- Fit approved self-closing device.
- Retain certification and installation evidence.

References

- Vol 1, Section 5, para 5.7; Diagram 5.1 — Door between dwellinghouse and attached/integral garage should achieve minimum E 30 Sa and be self-closing.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-V1-CAVITIES-CAVITY-BARRIERS-REQUIRED-01

UNKNOWN Medium Score: 45

Cavity barriers should both divide cavities and close cavity edges

Part: B3 • Family: Other • Severity: high

hasCavities missing

Missing info / action

- Identify all cavity locations (walls, floors, ceilings, roof voids).
- Provide cavity barriers to subdivide cavities (limit concealed smoke/flame spread).
- Provide edge closure at cavity perimeters (eaves, around openings, junctions).
- Do not rely on service penetration fire-stopping as a substitute for cavity barriers.

References

- Vol 1, Section 5, para 5.17 (p.52) — Cavity barriers are needed to subdivide cavities and close the edges of cavities; they are distinct from fire-stopping around service penetrations.

B3-V1-CAVITIES-CAVITY-BARRIERS-LOCATIONS-01

UNKNOWN Medium Score: 45

Cavity barriers must be provided at cavity edges including around openings

Part: B3 • Family: Other • Severity: high

openingPresentInCavityEdge missing

Missing info / action

- Identify all openings located at cavity edges (windows, doors, vents, service penetrations).
- Install cavity barriers around each opening.
- Ensure continuity at junctions with compartment walls/floors.
- Verify installation via drawings and site inspection evidence.

References

- Vol 1, Section 5, para 5.18(a) — Cavity barriers should be provided at cavity edges and around openings.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-V1-COMP-WALL-ROOF-JUNCTION-FIRESTOP-01

UNKNOWN Medium Score: 45

Compartment wall junction with roof must be fire-stopped up to underside of roof covering and into eaves

Part: B3 • Family: Other • Severity: high

hasCompartmentWallToRoofJunction missing

Missing info / action

- Confirm compartment wall extends to roof level.
- Provide fire-stopping across full thickness of wall at junction.
- Extend fire-stopping to underside of roof covering/boarding/slab.
- Extend into eaves where present.

References

- Vol 1, Section 5, Diagram 5.2 — Compartment walls must be fully fire-stopped at roof junctions, extending to underside of roof covering and into any eaves

B3-V1-COMP-WALL-ROOF-JUNCTION-THERMOPLASTICS-01

UNKNOWN Medium Score: 45

Thermoplastic insulation should not be carried over a compartment wall at roof junction; provide A2-s3,d2 band for thermoplastic-core insulated roof sheeting

Part: B3 • Family: Other • Severity: high

hasCompartmentWallToRoofJunction missing

Missing info / action

- Avoid carrying thermoplastic insulation across the compartment wall line at roof level.
- Where thermoplastic-core insulated roof sheeting is used, install a non-combustible A2-s3,d2 band centred over the wall.
- Ensure the band width meets the minimum requirement and is continuous through the junction.
- Retain classification reports and junction drawings/photos.

References

- Vol 1, Section 5, Diagram 5.2 (p.52) — Avoid carrying thermoplastic insulation across compartment wall at roof junction; where thermoplastic-core insulated roof sheeting is used, provide non-combustible (A2-s3,d2) band centred over the wall.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-ALARM-EXTENSION-GROUND-NO-FINALEXIT-01

UNKNOWN Medium Score: 45

Extensions/material alterations: alarm needed if new ground storey habitable room has no final exit

Part: B1 • Family: Other • Severity: high

newHabitableRoomGroundStoreyFlag missing

Missing info / action

• Confirm the works are an extension/material alteration and that a new ground-storey habitable room is being created.

• Confirm the new habitable room does not have a final exit (this is the trigger condition).

• Install or upgrade the fire detection and alarm system to at least Grade D2, Category LD3 (or better) in line with BS 5839-6.

• Consider improving means of escape (providing a final exit) alongside the alarm upgrade.

References

• Vol 1, Section 1, para 1.8(b) (p.9) — Install a fire detection and alarm system where a new habitable room is provided at the ground storey without a final exit.

• Vol 1, Section 1, paras 1.1–1.4 (p.9) — Minimum Grade D2 Category LD3 system per BS 5839-6; mains-

B1-DW-EXTERNAL-ESCAPE-STAIR-ZONES-01

UNKNOWN Medium Score: 45

External escape stair: doors and adjacent envelope zones must meet required fire resistance

Part: B1 • Family: Other • Severity: high

externalEscapeStairProvidedFlag missing

Missing info / action

• Upgrade doors opening to external stair to minimum E30 where required.

• Provide RE30 fire-resisting construction in defined envelope zones adjacent to the stair.

• Ensure glazing within defined zones is fixed shut and minimum E30.

• Provide weather protection for external stairs exceeding 6m in height.

References

• Vol 1, Section 2, para 2.17 — External escape stairs require fire-resisting construction in defined zones; doors generally min E30; adjacent envelope min RE30; glazing fixed shut and min E30.

• Vol 1, Section 2, Diagram 2.7 — Shows defined zones adjacent to external escape stair requiring fire-resisting construction.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-EXISTING-DW-REPLACEMENT-WINDOW-ESCAPE-01

UNKNOWN Medium Score: 45

Replacement windows: escape capability must be maintained (and may need cavity barriers)

Part: B1 • Family: Other • Severity: high

replacementWindowsFlag missing

Missing info / action

• Specify replacement escape window with clear openable area at least equal to the existing escape window, OR meet minimum escape criteria (≥0.33m², ≥450mm min dims, sill ≤1100mm).

• Confirm replacement window dimensions via schedule/datasheet.

• Where a cavity is present, provide cavity barriers around the opening where required.

• Retain window schedules and cavity barrier details as evidence.

References

• Vol 1, Section 2, paras 2.18–2.20 — Where an existing window is relied upon as an escape window and is big enough, the replacement should provide at least the same escape potential (or meet minimum escape criteria). Replacement may require cavity barriers around the opening where a cavity is present.

B1-EXIST-DW-WINDOW-CAVITY-01

UNKNOWN Medium Score: 45

Existing dwelling: cavity barriers required around window/door openings where a cavity is present

Part: B1 • Family: Other • Severity: high

existingDwellingFlag missing

Missing info / action

• Confirm whether the wall build-up includes a cavity around the opening.

• Provide cavity barriers around the window/door opening, OR confirm the frame itself forms the cavity barrier where permitted (steel/timber of suitable thickness).

• Ensure cavity barriers are tightly fitted to rigid construction and mechanically fixed.

• Fire-stop any junctions where tight fit is not achievable.

References

• Vol 1, Section 5, paras 5.20–5.23 — Cavity barriers should provide minimum performance and be tightly fitted/fixed; cavity barriers around openings may be formed by the window/door frame if it is steel or timber of minimum thickness.

• Vol 1, Section 5, para 5.21 (Note) — Frame may form cavity barrier around openings where constructed of steel or timber of minimum thickness.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-EXIT-AGGREGATE-WIDTH-01

UNKNOWN Medium Score: 45

Multiple storey exits: discount the largest exit and aggregate remaining exit capacity

Part: B1 • Family: Other • Severity: high

occupantLoad missing

Missing info / action

• Confirm occupant load for the storey (use Appendix D methods if needed).

• Confirm all storey exit clear widths (mm).

• Discount the largest exit (assume it may be unavailable in fire).

• Increase widths or provide additional exits so remaining combined capacity meets occupant load.

References

• Vol 2, Section 2, para 2.21 — Where multiple storey exits are available, discount the largest exit when assessing remaining exit capacity.

• Vol 2, Section 2, para 2.22 — After discounting, add together the maximum numbers of people each remaining exit width can accommodate.

• Vol 2, Section 2, Table 2.3 — Exit/route widths relate to maximum number of people (60/110/220, and

B1-EXIT-DISTRIBUTION-ANGLE-01

UNKNOWN Medium Score: 45

Multiple exits: exits should be sufficiently separated (distribution angle / independent directions)

Part: B1 • Family: Other • Severity: high

exitCount missing

Missing info / action

• Confirm the number of exits required for the space/storey.

• Check exit locations provide genuinely alternative directions of travel (use distribution angle or plan geometry).

• If exits are not sufficiently separated, relocate an exit or add an additional exit to create independent escape options.

• Retain plan evidence showing exit separation.

References

• Vol 2, Section 2 (Exit distribution guidance) — Where more than one exit is required, exits should be located so people can travel in alternative directions (i.e., they are not effectively the same route).

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-EXIT-MIN-WIDTH-BY-OCCUPANCY-01

UNKNOWN Medium Score: 45

Escape route / exit minimum clear width based on occupant capacity (Table 2.3)

Part: B1 • Family: Other • Severity: high

occupantLoad missing

Missing info / action

• Confirm occupant load for the space/storey/route.

• Measure/confirm clear escape route or exit width (mm).

• Increase width or provide additional exits so the minimum Table 2.3 width is met.

References

• Vol 2, Section 2, para 2.18 — Escape route and exit widths should meet Table 2.3.

• Vol 2, Section 2, Table 2.3 — Minimum widths for up to 60/110/220 persons and >220 persons (5mm per person above 220, with base 1050mm at 220)

B1-MIN-EXITS-FLOORS-01

UNKNOWN Medium Score: 45

Minimum number of storey exits required based on floors/storeys served

Part: B1 • Family: Other • Severity: high

storeysAboveGroundCount missing

Missing info / action

• Confirm number of storeys above ground and storey exit count.

• If 3+ storeys and only 1 exit is provided, add an additional exit/stair or redesign escape strategy to provide alternative direction of escape.

• Retain plans and fire strategy evidence for the exit provision.

References

• Vol 2, Section 2 (Number of exits guidance) — Where more than one exit is required, provide at least two exits from storeys/spaces depending on size, occupancy and escape strategy; higher floors/complexity increase the need for more than one exit.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-V2-CORRIDOR-CAVITY-SMOKE-BYPASS-01

UNKNOWN Medium Score: 45

Non-dwellings: restrict smoke bypass where a cavity exists above corridor enclosures

Part: B1 • Family: Other • Severity: high

corridorEnclosurePresentFlag missing

Missing info / action

• Confirm whether corridor enclosures stop short of full storey height / roof underside and whether a cavity exists above.

• If a cavity exists, implement Method 1 cavity barriers on the line of the corridor enclosure(s) and across the corridor, or implement Method 2 fire-resisting subdivision through the corridor line plus a fire-resisting ceiling/cavity barrier arrangement.

• Ensure any doors that could allow smoke bypass are fitted with self-closing devices.

• Retain drawings/details for cavity barriers, ceiling construction, subdivisions, and doorsets.

References

• Vol 2, Section 2, para 2.27 (p.22) — If a cavity exists above corridor enclosures (enclosures not full height/roof underside), restrict smoke bypass using Method 1 (cavity barriers on enclosure line) or Method 2 (fire-resisting subdivision through corridor + fire-resisting ceiling).

• Vol 2, Section 2, Diagram 2.9 (p.22) — Illustrates Method 1 cavity barriers across corridor enclosure line and Method 2 fire-resisting subdivision and cavity barrier arrangement.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-V1-PROTECTED-STAIR-EXTERNAL-WALL-HEAT-01

UNKNOWN Medium Score: 45

Protected stair: if adjacent external wall configuration could expose stair wall to heat, keep 1800mm between unprotected areas

Part: B1 • Family: Other • Severity: high

protectedStairPresentFlag missing

Missing info / action

• Identify whether the protected stair is projecting, recessed, or located at an internal angle relative to the adjoining external wall.

• Measure the separation between unprotected areas of the building enclosure and the protected stair enclosure.

• If <1800mm, redesign façade geometry or upgrade openings/construction so the unprotected-area relationship no longer applies (or increase separation).

• Retain façade drawings/sections demonstrating the 1800mm minimum.

References

• Vol 1, Section 3, para 3.63 (p.34) — Certain external wall configurations (e.g., internal angle) can subject the external wall of a protected stairway to heat.

• Vol 1, Section 3, para 3.64 (p.34) — If protected stair projects beyond/is recessed from/is in an internal angle of adjoining external wall: minimum distance between unprotected areas of building enclosure and stair enclosure should be 1800mm.

• Vol 1, Section 3, Diagram 3.10 (p.34) — Shows configurations and 1800mm minimum separation between unprotected areas.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-V1-EXTERNAL-ESCAPE-STAIR-CONDITIONS-01

UNKNOWN Medium Score: 45

External escape stairs (flats): doors, fire-resisting zones, glazing, and weather protection conditions

Part: B1 • Family: Other • Severity: high

externalEscapeStairProvidedFlag missing

Missing info / action

• Set doors to stair as minimum E30 and self-closing; only use the top-landing exception where it strictly applies.

• Provide minimum RE30 fire-resisting construction to the envelope in the prescribed zones around flights/landings.

• If there is no alternative escape route from the stair foot, make the building parts (incl. doors) within 1800mm of the route to safety minimum RE30.

• Ensure glazing in the fire-resisting zones is fixed shut and minimum E30 (integrity).

References

• Vol 1, Section 3, para 3.68(a)-(e) (p.35) — External escape stair conditions: E30 self-closing doors (with a limited exception); RE30 building envelope in defined zones; RE30 within 1800mm of route from foot to place of safety (unless alternative routes); E30 fixed shut glazing; weather protection if stair >6m above ground.

B1-V1-ROOF-COMPARTMENT-STRIP-1500-01

UNKNOWN Medium Score: 45

Roof over compartment wall: provide 1500mm BROOF(t4) zone each side on A2-s3,d2 deck; no thermoplastic rooflights in zone

Part: B1 • Family: Other • Severity: high

compartmentWallMeetsRoofFlag missing

Missing info / action

• Confirm where compartment walls meet the roof/deck.

• Define and detail a 1500mm zone on both sides of the compartment wall.

• Specify roof covering as BROOF(t4) in the zone and ensure the deck/substrate is class A2-s3, d2 (or better).

• Remove/relocate thermoplastic rooflights from within the 1500mm zone.

References

• Vol 1, Section 5, para 5.12 (p.53) — To reduce fire spread over the roof between compartments, provide 1500mm zone each side of compartment wall with BROOF(t4) covering on A2-s3,d2 (or better) deck; thermoplastic rooflights are not suitable in that zone.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-V2-CEILING-DIFFUSER-THERMOPLASTIC-LIMITS-01

UNKNOWN Medium Score: 45

Thermoplastic lighting diffusers in ceilings: allowed in rooms/circulation (not protected stairs) if 6.1 surfaces comply and diffuser is TP(a) rigid or TP(b) within Table 6.2 limits

Part: B1 • Family: Other • Severity: high

lightingDiffusersProvidedFlag missing

Missing info / action

• Confirm the diffusers are thermoplastic and form part of the ceiling construction.

• If the space is a protected stairway: do not use thermoplastic diffusers there.

• Confirm the exposed wall/ceiling surfaces above the suspended ceiling comply with para 6.1 (except the upper surface of thermoplastic panels).

• If using TP(b) diffusers: demonstrate compliance with Table 6.2/Diagram 6.2 limits (area, percentage, separation/grouping).

References

• Vol 2, Section 6, para 6.17 (p.58) — Thermoplastic diffusers may be used in ceilings to rooms and circulation spaces, but not protected stairways, if (a) surfaces above the suspended ceiling comply with para 6.1 (except upper surfaces of the panels) and (b) diffusers are TP(a) rigid (no extent limits) or TP(b) (extent limited per Table 6.2/Diagram 6.2).

• Vol 2, Section 6, Table 6.2 (p.59) — Limits for TP(b)/class D-s3,d2 plastic diffusers and rooflights: max individual area, max total % of floor area, and minimum separation by space type.

• Vol 2, Section 6, Diagram 6.2 (p.59) — Layout restrictions / grouping and separation for TP(b) lighting

B1-V2-PROTECTED-SHAFT-GLAZED-SCREEN-CONDITIONS-01

UNKNOWN Medium Score: 45

Protected shaft: conditions where an uninsulated glazed screen may form part of enclosure

Part: B1 • Family: Other • Severity: high

protectedShaftProvidedFlag missing

Missing info / action

• Confirm glazing forms part of a protected shaft enclosure.

• Check required fire resistance for shaft enclosure.

• Ensure glazing achieves required fire resistance performance.

• If using uninsulated glazing (integrity only), verify all para 7.24 conditions are met and documented.

References

• Vol 2, Section 7, para 7.24 — An uninsulated glazed screen may form part of a protected shaft enclosure only where specific conditions are satisfied (e.g., limited location, appropriate fire resistance, and no undue risk of fire spread).

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-V2-ROOF-COMPARTMENT-STRIP-1500-01

UNKNOWN Medium Score: 45

Roof at compartment wall: provide 1500mm BROOF(t4) zone each side on A2-s3,d2 (or better) deck; protect members passing through wall

Part: B1 • Family: Other • Severity: high

compartmentWallMeetsOrPassesUnderRoofFlag missing

Missing info / action

• Confirm where compartment walls meet or pass under roof construction.

• Detail a 1500mm zone each side of the wall with BROOF(t4) roof covering on class A2-s3,d2 (or better) deck/substrate.

• Carry fire-stopping up to the underside of the roof covering/boarding/slab at the wall.

• If any roof support members pass through the wall, provide fire protection for 1500mm each side (as needed to delay distortion).

References

• Vol 2, Section 8, paras 8.26–8.29 (Diagram 8.2 notes) (p.71) — Roof covering for 1500mm each side of compartment wall should be BROOF(t4) on deck/substrate class A2-s3,d2 (or better). If roof support members pass through wall, fire protection for 1500mm each side may be needed to delay distortion; fire-stopping to underside of roof covering.

• Vol 2, Section 8, para 8.28 (p.71) — Double-skinned insulated roof sheeting should incorporate a band

B1-V2-SPACE-SEPARATION-CANOPY-MEASURE-01

UNKNOWN Medium Score: 45

Space separation: measure to canopy outer edge; classify canopy as open-sided or enclosed

Part: B1 • Family: Other • Severity: high

canopyProvidedFlag missing

Missing info / action

• Confirm whether canopy is open-sided or enclosed.

• Measure separation distance to the correct reference point (outer edge of canopy projection where applicable).

• Recalculate unprotected area and separation distance if canopy projects toward boundary.

• Update fire strategy and site plans accordingly.

References

• Vol 2, Section 12, paras 12.8–12.9 — For space separation, distance is measured to the outside face of the external wall including projections; canopies are included. Open-sided canopies are measured to the outer edge; enclosed canopies are treated as part of the building.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-V2-SHARED-SPACE-SEPARATION-LIMITS-01

UNKNOWN Medium Score: 45

Open connections: alternative escape route separation (4.5m rule)

Part: B1 • Family: Other • Severity: high

openConnectionPresent missing

Missing info / action

• Revise the escape layout so initial travel is away from the open connection (re-position exits/doors/screens).

• Provide separation so the alternative escape route does not pass within 4.5m of the opening (re-route corridor, add fire-resisting enclosure, or add lobby/doorsets).

• Confirm the 4.5m clearance on GA plans and in the fire strategy with a clearly dimensioned diagram.

References

• Vol 2, Section 2, paras 2.12–2.13 (p.207) — Open connections: travel direction away from opening; alternative escape route should not pass within 4.5m of the opening.

• Vol 2, Section 2, Diagram 2.5 (p.207) — Area within 4.5m of opening must not be on the alternative escape route

B1-V2-SPACE-SEPARATION-UNPROTECTED-AREA-CALC-01

UNKNOWN Medium Score: 45

Space separation: unprotected area calculation completed and within limits

Part: B1 • Family: Other • Severity: high

spaceSeparationAppliesFlag missing

Missing info / action

• Produce a space-separation / unprotected-area calculation using an accepted ADB Vol 2 method (method 1 or method 2 as applicable).

• Reduce unprotected area (e.g., smaller glazing/openings) or increase boundary distance to bring the design within limits.

• Increase fire resistance of the external wall/openings where required and document the final result on elevations and in the fire strategy.

References

• Vol 2, Section 13 – Unprotected areas and fire resistance (p.294) — Space separation: radiation/flame spread via unprotected areas; methods provided for calculating acceptable unprotected area.

• Vol 2, Section 13, paras 13.17–13.21 (p.294) — Methods for calculating acceptable unprotected area (method 1 / method 2) and constraints (e.g. height limits for method 2).

• Vol 2, Section 13, Table 13.1 (p.295) — Permitted unprotected area limits by purpose group and distance to relevant boundary (method 2).

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-V2-FRS-TURNING-DEAD-END-ACCESS-20M-01

UNKNOWN Medium Score: 45

Fire service access: dead-end routes >20m need turning facilities (max 20m reversing)

Part: B1 • Family: Other • Severity: high

deadEndAccessRouteFlag missing

Missing info / action

• Add a turning head/hammerhead/turning circle where dead-end access exceeds 20m.

• Reconfigure the access road so appliances do not need to reverse more than 20m.

• Provide swept-path/turning geometry on the access plan and reference it in the fire strategy.

References

• Vol 2, Section 15, para 15.10 (p.304) — Dead-end access routes longer than 20m require turning facilities.

• Vol 2, Section 15, Diagram 15.3 (p.304) — FRS vehicles should not have to reverse more than 20m from end of access road.

• Vol 1, Section 13, para 13.4 and Diagram 13.1 (p.108) — Same 20m dead-end turning guidance (Volume

B1-V2-DRY-FIRE-MAINS-CONDITIONS-01

UNKNOWN Medium Score: 45

Dry fire mains: inlet access within 18m, on building face, visible, and indicated

Part: B1 • Family: Other • Severity: high

dryFireMainProvidedFlag missing

Missing info / action

• Reconfigure access/parking so the pumping appliance can get within 18m of each dry fire main inlet.

• Relocate/confirm inlets are on the building face and visible from the appliance parking position.

• Provide conspicuous inlet indication/signage (plate) and document it on plans and in the fire strategy.

References

• Vol 2, Section 15, para 15.4 (p.302) — Dry fire mains: pumping appliance within 18m; inlets on building face; inlet visible from parking position; satisfy para 16.10.

• Vol 2, Section 16, para 16.10 (p.306) — Hydrant/inlet location should be clearly indicated by a plate in accordance with BS 3251.

• Vol 1, Section 13, para 13.5 (flats) (p.109) — Parallel guidance for flats fitted with dry fire mains (18m + visible).

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-V2-SHARED-SPACE-SEPARATION-LIMITS-02

UNKNOWN Medium Score: 45

Open connections: escape routes not within 4.5m unless exception applies (para 2.13)

Part: B1 • Family: Other • Severity: high

openingBetweenFloorsPresentFlag missing

Missing info / action

• Re-route escape paths so they do not run within 4.5m of openings between floors.

• Ensure the initial direction of travel is away from the opening, or redesign the alternative route to maintain ≥4.5m clearance.

• Show the 4.5m zone and direction-of-travel compliance clearly on GA / escape plans.

References

• Vol 2, Section 2, para 2.13 (p.206) — Escape routes should not be within 4.5m of openings between floors unless travel is away OR alternative route does not pass within 4.5m.

• Vol 2, Section 2, Diagram 2.5 (p.207) — Open connections: 4.5m zone and direction of travel examples

B1-V2-FIREFIGHTING-SHAFTS-OVER-18M-01

UNKNOWN Medium Score: 45

Firefighting shafts: storey >18m above FRS access level requires shaft(s) with firefighting lift

Part: B1 • Family: Other • Severity: high

maxStoreyAboveFRSAccessLevelM missing

Missing info / action

• Add at least one protected firefighting shaft where storeys exceed 18m above FRS access level.

• Include a compliant firefighting lift within the shaft.

• Document shaft/lift provision clearly on GA plans and in the fire strategy.

References

• Vol 2, Section 17, para 17.2 (p.308) — A building with a storey more than 18m above FRS vehicle access level should have one or more firefighting shafts containing a firefighting lift.

• Vol 2, Section 17, Diagram 17.1 (note 2) (p.307) — Firefighting lift required if building has a floor more than 18m above (or more than 10m below) access level.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-V2-HOSE-LAYING-DISTANCE-LIMITS-01

UNKNOWN Medium Score: 45

Hose laying distance limits: 60m (firefighting shaft) and 45m (protected shaft if no sprinklers)

Part: B1 • Family: Other • Severity: high

sprinklersProvidedFlag missing

Missing info / action

• Reposition firefighting shafts/outlets to reduce hose laying distance so all areas are within 60m from a firefighting shaft outlet.

• If sprinklers are not provided and a protected shaft outlet is relied on, reconfigure to achieve ≤45m coverage or provide sprinklers/alternate compliant arrangement.

• Provide a hose-distance plan showing measurement route(s); if layout unknown, use two-thirds of direct distance and state the basis.

References

• Vol 2, Section 17, paras 17.7–17.8 (p.309) — Hose laying distance measured from fire main outlet along suitable route; max 60m from outlet in firefighting shaft; additionally max 45m from outlet in protected shaft where sprinklers not provided.

• Vol 2, Section 17, Diagram 17.3 (notes) (p.310) — Measurement notes: route suitable for hose laying; if layout unknown, use two-thirds of direct distance

B1-V2-FIREFIGHTING-LOBBY-APPROACH-01

UNKNOWN Medium Score: 45

Firefighting shaft approach: firefighting stair and lift approached via firefighting lobby

Part: B1 • Family: Other • Severity: high

firefightingShaftProvidedFlag missing

Missing info / action

• Reconfigure the firefighting shaft so the accommodation enters a firefighting lobby before reaching the firefighting stair/lift.

• Remove any direct door from accommodation into the firefighting stair/lift landing that bypasses the lobby (unless justified by an alternative compliant solution).

• Show the lobby approach clearly on GA plans and in the fire strategy (label lobby, doors, and approach route).

References

• Vol 2, Section 17, para 17.9 (p.311) — Every firefighting stair and firefighting lift should be approached from the accommodation through a firefighting lobby.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B4-V2-MEMBRANES-MIN-CLASS-01

UNKNOWN Medium Score: 45

Membranes in external wall above ground: minimum reaction-to-fire class B-s3,d0 (additional consideration)

Part: B4 • Family: Other • Severity: high

membranePresentFlag missing

Missing info / action

• Confirm whether the membrane is part of the external wall construction above ground.

• Obtain BS EN 13501-1 reaction-to-fire classification for the membrane in its end-use application.

• If below B-s3,d0, re-specify to a membrane achieving B-s3,d0 or better (or redesign the build-up to eliminate the membrane).

• Document product classification evidence in the fire strategy / compliance pack.

References

• Vol 2, Section 12, para 12.22(a) (p.98) — Membranes used as part of the external wall construction above ground should achieve minimum class B-s3,d0. Roofing membranes do not need to achieve minimum class A2-s1,d0 when used as part of a roof connecting to an external wall.

B4-V2-THERMAL-BREAKS-CONSTRAINTS-01

UNKNOWN Medium Score: 45

Thermal breaks: must not span compartments; minimise size; principal insulation is not a thermal break

Part: B4 • Family: Other • Severity: high

thermalBreaksPresentFlag missing

Missing info / action

• Confirm which elements are being treated as thermal breaks (do not classify the principal insulation layer as a thermal break).

• Detail thermal breaks so they do not span compartment lines (align with compartmentation strategy).

• Minimise thermal break size to the minimum required to address thermal bridging, and document the reasoning.

• Retain detail drawings and Part L thermal-bridging justification in the compliance pack.

References

• Vol 2, Section 12, para 12.22(e) (p.99) — Thermal breaks: no minimum performance; should not span two compartments; limit size to minimum; principal insulation layer is not a thermal break.

• Regulation 7(3)(i) (p.281) — Thermal break materials are exempt from Reg 7(2) where necessary to meet Part L thermal bridging requirements (still subject to prudent constraints).

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-DOOR-SWING-DIRECTION-01

UNKNOWN Low Score: 30

Escape door swing direction: open in direction of escape for high occupancy or high-risk rooms

Part: B1 • Family: Other • Severity: medium

Missing onEscapeRouteFlag

Missing info / action

• Confirm the escape occupant load using this door and whether the served room is high fire-risk.

• If triggered, ensure the door opens in the direction of escape (typically outward from the room/space).

• Where not reasonably practicable, document the justification and apply alternative risk controls (e.g., manage occupant load, re-route flow, add exits).

• Update drawings/schedules and record the decision in the fire strategy pack.

References

• Vol 2, Section 5, para 5.11 — Doors used by large numbers of escaping occupants or from high fire-risk spaces should open in the direction of escape

B1-CORRIDOR-BEYOND-STAIR-01

UNKNOWN Low Score: 30

Corridor extension beyond protected stair

Part: B1 • Family: Other • Severity: medium

corridor_wraps_behind_stair_flag missing.

Missing info / action

• Measure any corridor run/extension beyond the protected stair; confirm whether it exceeds 2m.

• If >2m, treat as a dead-end corridor: provide protected corridor construction and/or sub-division with rated fire doors/screens as appropriate.

• Update escape strategy drawings and fire door schedule to reflect any added protection/sub-division.

References

• Vol 2, Section 2, para 2.24 (p.209) — Dead-end corridors should be protected; corridor extensions beyond a protected stair are limited (see Diagram 2.8).

• Vol 2, Section 2, Diagram 2.8 (p.210) — Extension of corridor beyond a protected stairway; 2m max shown.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-FLOOR-FINISH-SLIP-01

UNKNOWN Low Score: 30

Slippery finishes on escape stairs and routes

Part: B1 • Family: Other • Severity: medium

on_escape_route_flag missing

Missing info / action

• Identify escape-route segments (stairs, ramps, landings) and confirm finish types.

• Avoid highly smooth/polished finishes where surfaces can become wet.

• Specify and document slip-resistance performance suitable for wet conditions, especially on treads/ramps/landings.

• If already installed, apply anti-slip nosings/treatments or replace finishes and manage water ingress/drainage.

References

• Vol 2, Section 5, para 5.17 (p.238) — Escape route floor finishes should minimise slipperiness when wet (incl. steps, ramps, landings)

B1-SINGLE-STEP-MARKING-01

UNKNOWN Low Score: 30

Single steps on escape routes

Part: B1 • Family: Other • Severity: medium

Missing singleStepPresentFlag

Missing info / action

• Survey escape routes for isolated single steps.

• Ensure steps are clearly marked using high-contrast visual markings.

• Consider replacing single steps with compliant ramps where possible.

• Record compliance evidence in the fire strategy and safety documentation.

References

• Vol 2, Section 3, para 3.26 — Single steps should be clearly visible and marked to avoid trips on escape routes.

• Vol 2, Section 5, para 5.19 — Level changes on escape routes should be avoided or clearly marked and safe.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B5-SECURE-INFO-BOX-11M-01

UNKNOWN Low Score: 30

Secure information box in blocks of flats with top storey over 11m (FIA premises information box guidance)

Part: B5 • Family: Other • Severity: medium

secureInfoBoxProvided missing

Missing info / action

• Confirm the building is purpose group 1(a) and determine whether the top storey height is over 11m above ground.

• Install a secure information box in a location that firefighters can easily identify and access.

• Ensure the box is large enough for required information, secured against unauthorised access, readily accessible by firefighters, and protected from weather.

• Populate with current fire strategy / plans / key system information and maintain it up to date.

References

• Vol 1, Section 15, paras 15.18–15.21 (p.108) — Blocks of flats (1(a)) with top storey > 11m should have a secure information box; conditions given; FIA Code of Practice referenced

B5-PRIVATE-HYDRANTS-01

UNKNOWN Low Score: 30

Private hydrants for large or remote buildings (Vol 2, Section 16.8–16.11)

Part: B5 • Family: Other • Severity: medium

largestCompartmentAreaM2 missing

Missing info / action

• Confirm largest compartment size and measure distance to nearest public hydrant.

• If triggers met, design and install private hydrants within 90 m of fire main inlets or principal entrances.

• Ensure hydrants are spaced at no more than 90 m intervals around the building.

• Record hydrant positions and distances on the fire strategy and site plan.

References

• Vol 2, Section 16, paras 16.8–16.11 — If any compartment >280 m² and >100 m from public hydrant, provide private hydrants within 90 m of inlets/entrances and at 90 m spacing.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-ROOF-OVER-COMP-WALL-01

UNKNOWN Low Score: 30

Roof treatment where crossing compartment walls (Vol 2, Section 8; Diagram 8.2)

Part: B3 • Family: Other • Severity: medium

compartmentWallThroughRoofFlag missing

Missing info / action

• Confirm the compartment wall meets the underside of roof covering/deck and is fire-stopped; ensure continuity across eaves.

• Choose compliance route: (A) 1500mm BROOF(t4) zone each side on A2-s3,d2 deck; or (B) extend wall through roof as parapet/upstand to Diagram 8.2 heights.

• Check roof build-up details at the wall: avoid carrying thermoplastic insulation over the wall; address any insulated roof sheeting with the 300mm A2 band detail.

• Record roof covering classification and deck/substrate classification evidence and as-built fire-stopping confirmation.

References

• Vol 2, Section 8, paras 8.25–8.29 (p.71) — Compartment wall must fire-stop to underside of roof/deck and continue across eaves. Provide either 1500mm BROOF(t4) zone each side on A2 deck or extend wall through roof as upstand with minimum heights (Diagram 8.2).

• Vol 2, Diagram 8.2 (p.72) — Diagram shows 1500mm roof zones and upstand/parapet option; notes include restrictions on thermoplastic insulation carried over the wall and 300mm A2 band for insulated

B1-DW-FLATROOF-ESCAPE-01

UNKNOWN Low Score: 30

Flat roofs and balconies forming part of escape in dwellinghouses (Vol 1, paras 2.13–2.14)

Part: B1 • Family: Other • Severity: medium

escapeRouteOverFlatRoofFlag missing

Missing info / action

• Confirm the flat roof/balcony escape route is within the same building and discharges to a storey exit or an external escape route.

• Upgrade the roof route zone (including supporting structure) to minimum REI 30 where it forms part of the escape route.

• Ensure any opening within 3m of the escape route has minimum REI 30 protection (or equivalent fire-resisting construction).

• Provide guarding/edge protection to AD K requirements along the escape route.

References

• Vol 1, Section 2, para 2.13 (p.16) — Flat roof escape route must be part of same building; lead to storey exit/external escape; roof portion and any opening within 3m must be minimum REI 30.

• Vol 1, Section 2, para 2.14; AD K (p.16) — Balcony/flat roof used for escape must have guarding etc. per Approved Document K.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-DW-PASSENGER-LIFT-SHAFT-01

UNKNOWN Low Score: 30

Passenger lift protection in dwellinghouses above 4.5 m (Vol 1, para 2.7)

Part: B1 • Family: Other • Severity: medium

passengerLiftPresent missing

Missing info / action

• Confirm whether any storey served by the lift is more than 4.5m above ground.

• If yes, place the lift within the protected stair enclosure or provide a dedicated fire-resisting lift shaft (target REI 30).

• Ensure fire-stopping at penetrations and continuity of fire-resisting construction around the shaft.

• Record shaft rating and enclosure approach in the fire strategy and drawings.

References

• Vol 1, Section 2, para 2.7 — Where a dwellinghouse has storeys over 4.5m above ground and a passenger lift, the lift should be in protected construction: within protected stair enclosure or a fire-resisting lift shaft (typically REI 30)

B1-FLAT-PROTECTED-ENCLOSURE-AIR-CIRCULATION-01

UNKNOWN Low Score: 30

Air circulation systems and protected stairs/entrance halls in flats (Vol 1, para 3.23)

Part: B1 • Family: Other • Severity: medium

protectedStairOrEntranceHallPresent missing

Missing info / action

• Remove transfer grilles from protected stair/entrance hall enclosure boundaries.

• Upgrade ducts through enclosure to rigid steel construction and fire-stop all penetrations.

• Ensure enclosure ventilation does not serve other areas.

• Provide smoke-detection shutdown to any recirculating air system serving the flat.

References

• Vol 1, Section 3, para 3.23 — Transfer grilles and air systems must not compromise protected stair/entrance hall enclosures; duct penetrations require fire-stopping and recirculating systems need smoke-detection shutdown.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-FLAT-LIVEWORK-TRAVELDIST-18M-01

UNKNOWN Low Score: 30

Live/work units: travel distance and escape lighting (Vol 1, para 3.24)

Part: B1 • Family: Other • Severity: medium

liveWorkUnitFlag missing

Missing info / action

- Re-plan working area/escape routes to ensure travel distance ≤18m.
- Provide an alternative escape route if distance to entrance exceeds 18m.
- Provide compliant escape lighting in windowless working areas.
- Where >18m cannot be achieved, develop a bespoke fire strategy.

References

- Vol 1, Section 3, para 3.24 — Live/work flats: max 18m travel distance from working area to entrance door or alternative escape; provide escape lighting where areas are windowless.

B1-FLATS-COMMON-DOOR-RECESS-CORRIDOR-STAIR-01

UNKNOWN Low Score: 30

Doors opening onto corridors/stairs – recess to avoid encroachment (Vol 1, para 3.96)

Part: B1 • Family: Other • Severity: medium

doorOpensOntoCorridorOrStair missing

Missing info / action

- Recess the door into an alcove so the swing is clear of the corridor/stair landing effective width.
- Alternatively re-hang/reconfigure the door swing so it does not encroach on the escape route width.

References

- Vol 1, Section 3, para 3.96 — Doors opening towards corridors or stairs should be recessed so their swing does not reduce the effective width of the escape route.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-EXIST-DW-WINDOW-ESC-01

UNKNOWN Low Score: 30

Replacement windows must maintain emergency escape potential (Vol 1, paras 2.18–2.19; min dims per 2.10)

Part: B1 • Family: Other • Severity: medium

replacementWindowsFlag missing

Missing info / action

• Measure the existing clear openable area/dimensions of the escape window and record as baseline.

• Ensure the replacement provides at least the same clear openable area OR (if reducing) still meets para 2.10 minimums (0.33m², 450mm min height/width, sill ≤1100mm).

• Adjust window configuration (opening type, mullions, restrictors/stays) to maintain compliant escape potential.

References

• Vol 1, Section 2, paras 2.18–2.19 (p.27) — Replacement windows must not reduce emergency escape potential where an existing window would be an escape window.

• Vol 1, Section 2, para 2.10 (p.24) — Minimum escape window criteria: 0.33m²; 450mm min height/width; sill ≤1100mm.

B3-FIRESTOP-PIPES-SLEEVE-01

UNKNOWN Low Score: 30

Sleeving option for pipe penetrations through fire-separating elements (≤160mm, A1 sleeve, fire-stopped)

Part: B3 • Family: Other • Severity: medium

pipe_penetration_present missing

Missing info / action

• Confirm this penetration is through a fire-separating element and that the sleeving alternative is intended (not a proprietary seal system).

• Ensure pipe nominal internal diameter does not exceed 160mm for the sleeving option.

• Confirm pipe material is permitted; if uPVC, confirm compliance with BS 4514 or BS 5255.

• Use a high-melting-point metal sleeve (e.g., cast iron/copper/steel) that is class A1 rated, and ensure sleeve/pipe contact as per the diagram.

References

• Vol 2, Section 10, para 10.5 (p.272) — Sleeving alternative: pipe ≤160mm nominal internal diameter permitted with high melting point metal sleeve (A1) for specified pipe materials.

• Vol 2, Section 10, Diagram 10.1 (p.272) — Opening should be as small as possible; provide fire-stopping between pipe and fire-separating element; sleeve class A1; sleeve/pipe in contact.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B2-THERMOPLASTICS-LIGHT-DIFFUSERS-01

UNKNOWN Low Score: 30

Thermoplastic light diffusers in ceilings (area/location limits)

Part: B2 • Family: Other • Severity: medium

elementType missing

Missing info / action

• Avoid thermoplastic diffusers in protected escape routes where practicable.

• Limit total thermoplastic diffuser coverage within ceiling to permitted percentages (stricter in escape routes/circulation).

• Specify higher-performing materials and retain test evidence.

• Provide ceiling layout and lighting schedule showing diffuser areas and coverage.

References

• Vol 1, Section 4 (Thermoplastic materials) (p.44) — Thermoplastic light diffusers/lighting panels in ceilings may be limited by area and location, particularly in circulation/escape routes.

B2-LININGS-WALL-DEFINITION-01

UNKNOWN Low Score: 30

Wall definition includes glazing surfaces and steep ceilings

Part: B2 • Family: Other • Severity: medium

elementType missing

Missing info / action

• Confirm whether glazing is part of a door (exclude door glazing).

• Check ceiling slope angle from horizontal.

• Where glazing (not in doors) or ceilings >70° are present, apply B2 lining classification requirements.

References

• Vol 1, Section 4, para 4.2 (p.42) — For lining classification checks, the term 'wall' includes internal glazing (except door glazing) and ceilings sloping more than 70° from horizontal.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B2-CEILING-DEFINITION-01

UNKNOWN Low Score: 30

Ceiling definition includes glazed surfaces, shallow walls, galleries and roof undersides

Part: B2 • Family: Other • Severity: medium

elementType missing

Missing info / action

• Confirm geometry/angle of sloping surfaces relative to horizontal.

• Identify underside of galleries and roof undersides exposed to rooms below.

• Where these conditions apply, treat the surface as a ceiling lining for B2 classification checks.

References

• Vol 1, Section 4, para 4.5 (p.42) — For lining classification checks, 'ceiling' includes glazed surfaces, walls at 70° (boundary condition), underside of galleries, and underside of roofs exposed to the room below.

B2-THERMOPLASTIC-DIFFUSERS-01

UNKNOWN Low Score: 30

Thermoplastic lighting diffusers forming part of ceiling: permitted except protected stairways (TP class + conditions)

Part: B2 • Family: Other • Severity: medium

diffuserFormsPartOfCeiling missing (rule applies only to diffusers forming part of ceiling)

Missing info / action

• Do not use thermoplastic lighting diffusers forming part of ceilings in protected stairways.

• Confirm the diffuser is actually ‘forming part of the ceiling’ (if attached to soffit or suspended beneath, this rule does not apply).

• Ensure exposed wall/ceiling surfaces above the suspended ceiling comply with para 4.1 (except upper surfaces of thermoplastic panels).

• Specify TP(a) rigid diffusers (no extent limits) or, if TP(b), demonstrate compliance with Table 4.2 limits via layout and calculations.

References

• Vol 1, Section 4, para 4.15 (p.56) — Applies only to lighting diffusers forming part of a ceiling; excludes diffusers attached to soffit or suspended beneath the ceiling.

• Vol 1, Section 4, para 4.16 (p.56) — Thermoplastic diffusers may be used in ceilings to rooms/circulation spaces (not protected stairways) if exposed surfaces above comply with para 4.1 and diffuser is TP(a) rigid or TP(b).

• Vol 1, Section 4, Table 4.2 (p.57) — TP(a) rigid: no extent restrictions (except not in protected stairways). TP(b): limited extent (max area/percent/separation by space type).

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-V1-FLATS-STRUCT-ROOF-ONLY-EXCLUSION-01

UNKNOWN Low Score: 30

Flats: roof-only supporting structures excluded unless roof acts as floor/escape or stabilises required external wall

Part: B3 • Family: Other • Severity: medium

supportOnlyRoof missing

Missing info / action

• Confirm whether the structural member truly supports only the roof (and is not part of the building's stability system).

• If the roof is used as a floor (e.g., parking/terrace) or provides a means of escape, treat the supporting structure as an element of structure and provide the required fire resistance.

• If the structure is essential to a fire-resisting external wall's stability (e.g., compartmentation / limiting fire spread between buildings), treat it as an element of structure and provide the required fire resistance.

• Document the roof use and any dependency on external wall stability in the fire strategy and structural design narrative.

References

• Vol 1, Section 6, para 6.2(a) (p.57) — A structure that supports only a roof is excluded from 'element of structure' unless the roof functions as a floor/means of escape, or the structure is essential to stability of a fire-resisting external wall

B3-V1-FLATS-CONV-UPTO-3STOREYS-REI30-01

UNKNOWN Low Score: 30

Conversion to flats (≤3 storeys): REI 30 may be acceptable if means of escape meets Section 3

Part: B3 • Family: Other • Severity: medium

isConversionToFlats missing

Missing info / action

• Confirm total storey count (including ground storey) does not exceed three.

• Demonstrate full compliance of means of escape with Section 3 (protected routes, travel distances, compartmentation, etc.).

• If Section 3 compliance cannot be demonstrated, revert to Appendix B minimum fire resistance periods.

• Attach fire strategy and means of escape drawings as evidence.

References

• Vol 1, Section 6, para 6.6 (p.58) — In converted buildings with a maximum of three storeys, minimum REI 30 may be accepted for elements of structure if means of escape conform to Section 3.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-V1-STRUCT-ROOF-ONLY-EXCLUSION-01

UNKNOWN Low Score: 30

Roof-only structures are not 'elements of structure' unless the roof acts as a floor/escape route or stabilises a required fire-resisting external wall

Part: B3 • Family: Other • Severity: medium

structureSupportsOnlyRoof missing

Missing info / action

• Confirm whether the structure truly supports only a roof (and not part of overall stability system).

• If the roof is used as a floor/roof terrace or a means of escape, classify the roof-supporting structure as an 'element of structure' and apply the required fire resistance standard.

• If the roof-supporting structure is essential for stability of an external wall that must be fire resisting (e.g., compartmentation / boundary fire spread control), treat it as an 'element of structure' and apply the required fire resistance standard.

• Record the decision and justification in the fire strategy/structural fire note.

References

• Vol 1, Section 5, para 5.3(a)(i)–(ii) and note (p.50) — Roof-only supporting structures are excluded from 'element of structure' unless roof acts as floor/escape or the structure stabilises a required fire-resisting external wall

B3-V1-STRUCT-LOFT-CONVERSION-EXISTING-FLOOR-R30-01

UNKNOWN Low Score: 30

Existing first-storey construction in loft conversions should achieve R 30 (limited allowance for reduced integrity/insulation)

Part: B3 • Family: Other • Severity: medium

isLoftConversion missing

Missing info / action

• Assess existing first-storey floor construction and determine fire resistance.

• Upgrade existing floor to achieve minimum R 30 where required.

• Only apply integrity/insulation reduction where a single additional storey is created with no more than two habitable rooms and within area limits.

• Document justification clearly within the fire strategy.

References

• Vol 1, Section 5, para 5.4 (p.51) — In loft conversions, existing first-storey construction should achieve minimum R 30; integrity/insulation reduction allowed only under strict conditions.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B3-V1-COMP-GARAGE-DOOR-THRESHOLD-SPILL-01

UNKNOWN Low Score: 30

Garage-to-dwelling door openings must prevent fuel spill flow into the dwelling

Part: B3 • Family: Other • Severity: medium

hasDoorBetweenGarageAndDwelling missing

Missing info / action

• Confirm there is a door between the garage and the dwelling.

• Set garage floor levels so the floor falls away from the doorway towards the outside, OR raise the door threshold so the opening is at least 100mm above garage floor level.

• Verify with section/threshold detail and as-built levels/photos.

References

• Vol 1, Section 5, para 5.7; Diagram 5.1 (p.52) — Where a door is provided between dwellinghouse and garage, either the garage floor falls away from the door to outside, or the door opening is min 100mm above garage floor.

B3-V1-COMP-WALL-ROOF-JUNCTION-BROOF-01

UNKNOWN Low Score: 30

Roof covering at compartment wall junction should be BROOF(t4) for at least 1500mm either side

Part: B3 • Family: Other • Severity: medium

hasCompartmentWallToRoofJunction missing

Missing info / action

• Confirm location where compartment wall meets the roof covering.

• Specify roof covering classification BROOF(t4) for the controlled zone.

• Ensure BROOF(t4) zone extends at least 1500mm on each side of the wall junction.

• Retain classification evidence and roof plan/details.

References

• Vol 1, Section 5, Diagram 5.2 — Where compartment wall meets roof, provide roof covering BROOF(t4) for min 1500mm on each side of the wall.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-V2-CEILING-LIGHTING-DIFFUSER-SCOPE-01

UNKNOWN Low Score: 30

Ceiling classification: lighting diffusers forming part of ceiling lining are within scope

Part: B1 • Family: Other • Severity: medium

lightingDiffusersProvidedFlag missing

Missing info / action

• Confirm whether lighting diffusers are integrated into and form part of the ceiling lining.

• If yes, verify that the diffuser product achieves the required ceiling lining classification for the space (per Section 6 tables).

• Retain fire test/classification reports demonstrating compliance.

References

• Vol 2, Section 6, para 6.16 (p.67) — The guidance on ceiling linings includes lighting diffusers where they form part of the ceiling construction.

B1-V2-EXTWALL-DEFINED-ATTACHMENTS-01

UNKNOWN Low Score: 30

External wall attachments: identify whether attachment is a 'specified attachment' (Reg 7(2) scope) vs other attachments

Part: B1 • Family: Other • Severity: medium

externalWallAttachmentPresentFlag missing

Missing info / action

• List all façade attachments and tag their type (balcony, PV/solar panel, solar shading, signage, etc.).

• Mark which items are 'specified attachments' (Reg 7(2) scope) vs non-specified attachments.

• Do not classify shop front signs (and similar) as specified attachments.

• Even for non-specified attachments, assess whether they could increase fire spread risk over the wall.

References

• Vol 2, Section 12, para 12.16 (p.98) — External walls and specified attachments are defined in regulation 2(6) and include parts of the external wall plus balconies, solar panels and solar shading.

• Vol 2, Section 12, para 12.22(f) (p.98) — Regulation 7(2) only applies to specified attachments; shop front signs and similar attachments are not covered.

• Vol 2, Section 12, para 12.22(g) (p.98) — Even where Reg 7(2) applies, other attachments should be considered if they could impact fire spread over the wall.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-V2-FIRE-MAINS-BS9990-REFERENCE-01

UNKNOWN Low Score: 30

Fire mains: design/specification references BS 9990 where fire mains are provided

Part: B1 • Family: Other • Severity: medium

bs9990ReferencedInFireMainSpecFlag (or fireMainDesignStandard) missing

Missing info / action

• Update the fire strategy and fire main specification to state BS 9990 as the design/construction reference for fire mains.

• If dry fire mains are used, explicitly reference compliance with Section 8 of BS 9990 for inlet connection point provisions.

• Attach/issue a fire main riser/inlet detail sheet that cross-references BS 9990 clauses/sections used.

References

• Vol 2, Section 16, para 16.5 (p.306) — Guidance on design and construction of fire mains is given in BS 9990.

• Vol 1, Section 13, para 13.5(b) (flats with dry fire mains) (p.109) — Dry fire main inlet connection point should meet provisions in Section 8 of BS 9990.

B4-CANOPY-BOUNDARY-01

UNKNOWN Low Score: 15

Effect of canopies and projections on separation distance

Part: B4 • Family: Other • Severity: low

Cannot determine whether a canopy/projection exists.

Missing info / action

• Confirm if a canopy/projection exists and whether it is enclosed.

• Measure projection depth and the distance from the projection edge to the relevant boundary.

• If the projection reduces effective separation, update the space separation calculation and façade/opening strategy accordingly.

• Consider reducing projection size, relocating, or enclosing/protecting the projection in line with the fire strategy where needed.

References

• Vol 2, Section 13, paras 13.13–13.14 — Projections/canopies may affect separation distance calculations.

• Vol 2, Section 13, Diagram 13.6 — Shows how projections are treated for boundary separation.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B1-FLATS-COMMON-DOOR-VISION-PANELS-01

UNKNOWN Low Score: 15

Vision panels in doors that divide corridors or swing both ways (Vol 1, para 3.97)

Part: B1 • Family: Other • Severity: low

doorDividesCorridor missing

Missing info / action

• Specify/retrofit an appropriate vision panel for corridor subdivision doors and double-swing doors.

• Where the door is a fire doorset, ensure the vision panel detail is compatible with the door's fire performance.

References

• Vol 1, Section 3, para 3.97 — Doors on escape routes that divide corridors, and doors that swing both ways, should contain vision panels.

B2-LININGS-EXCLUSIONS-01

UNKNOWN Low Score: 15

Items not classed as wall/ceiling linings (exclusions)

Part: B2 • Family: Other • Severity: low

elementType missing

Missing info / action

• Confirm whether the element qualifies as a wall or ceiling lining under ADB Section 4 definitions.

• Exclude doors, frames, skirtings, architraves and similar trims from lining classification checks.

• Ensure lining rules are only applied to actual wall/ceiling surface materials.

References

• Vol 1, Section 4 (definitions/exclusions within Section 4) (p.41) — Certain trims and components (e.g., doors, frames, skirtings, architraves) are not treated as wall or ceiling linings for classification purposes.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B2-ROOF-EXCLUSIONS-CEILING-01

UNKNOWN Low Score: 15

Items excluded from ceiling lining checks

Part: B2 • Family: Other • Severity: low

elementType missing

Missing info / action

• Confirm whether the element is a true ceiling lining surface or a narrow member/frame.

• Exclude trap doors, rooflight/window frames, picture rails, mouldings, architraves, exposed beams and similar items from ceiling lining classification checks.

• Apply lining classification only to actual ceiling surfaces.

References

• Vol 1, Section 4, para 4.6 (p.42) — Certain items are not treated as ceilings for classification purposes (e.g., trap doors, rooflight/window frames, architraves/cover moulds/picture rails, exposed beams and similar narrow members).

B3-V1-CAVITIES-DEFINITION-01

UNKNOWN Low Score: 15

Concealed spaces are treated as cavities due to concealed fire/smoke spread risk

Part: B3 • Family: Other • Severity: low

hasConcealedSpaces missing

Missing info / action

• Identify all concealed spaces within walls, floors, ceilings, and roof voids.

• Classify each concealed space as a cavity for barrier assessment.

• Trigger cavity barrier and fire-stopping compliance checks.

References

• Vol 1, Section 5, para 5.16 — Concealed spaces are treated as cavities because they allow hidden fire and smoke spread.

Roof Spread

3 item(s) • UNKNOWN

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B4-ROOF-COVERING-CLASS-01

UNKNOWN Medium Score: 55

Roof covering fire performance classification (e.g., BROOF(t4) or equivalent)

Part: B4 • Family: Roof Spread • Severity: critical

Rule logic not implemented.

Missing info / action

• Confirm distance to relevant/notional boundary for the roof edge/covering assessment.

• Specify a roof covering/system with an appropriate external fire performance classification (e.g., BROOF(t4) or equivalent).

• Ensure the classification evidence matches the full build-up/system and installation orientation/conditions.

• Include the classification report/certificate in the fire strategy pack.

References

• Vol 2, Section 12, paras 12.1–12.3 (p.95) — Roof coverings should resist external fire spread; classification (e.g., BROOF(t4) or equivalent) depends on proximity to boundary and roof characteristics

B4-ROOF-SEPARATION-01

UNKNOWN Medium Score: 45

Roof spread to boundary compliance

Part: B4 • Family: Roof Spread • Severity: high

Boundary distance and roof covering classification are both missing.

Missing info / action

• Provide or confirm compliant roof covering classification.

• Increase boundary distance where feasible.

• Revise roof specification to an acceptable performance classification.

• Provide clearer boundary-distance and roof-specification evidence.

References

• Vol 2, B4 — Roof external fire spread should be assessed against boundary distance and roof covering performance.

Compliance Results (continued)

Automated compliance red-flag assessment (Fire Safety)

B4-V1-ROOF-SPREAD-01

UNKNOWN Medium Score: 45

Roof covering limits external fire spread (roof covering classification vs boundary distance)

Part: B4 • Family: Roof Spread • Severity: high

boundaryDistanceMeters missing

Missing info / action

• Select a higher-performing roof covering designation (e.g., BROOF(t4)) where close to boundaries.

• Increase separation distance to the relevant boundary where feasible (setback / roof geometry).

• Provide the roof covering classification evidence (test/classification report) and roof spec.

References

• Vol 1, Section 12, paras 12.1–12.3 (p.92) — Defines roof covering and separation distance to relevant boundary.

• Vol 1, Section 12, Table 12.1 (p.94) — Limits roof covering designation (BROOF/CROOF/DROOF/EROOF/FROOF) by boundary distance.

Unprotected Areas

1 item(s) • UNKNOWN

B4-V1-UNPROTECTED-AREAS-01

UNKNOWN Medium Score: 45

Vol 1 space separation and unprotected area compliance (dwellings)

Part: B4 • Family: Unprotected Areas • Severity: high

boundaryDistanceMeters missing

Missing info / action

• Increase boundary distance where possible by setting back the elevation.

• Reduce unprotected area by reducing or relocating openings.

• Use a compliant openings and wall strategy supported by drawings and schedules.

• For taller cases, provide formal assessment evidence to the para 11.16 / equivalent method.

References

• Vol 1, B4, paras 11.6–11.9 — Defines unprotected areas; sets rules for walls within 1000mm of boundary vs 1000mm or more.

• Vol 1, B4, para 11.11; Diagram 11.5 — Small unprotected areas may be disregarded if they meet the Diagram 11.5 conditions.

• Vol 1, B4, paras 11.16–11.20; Table 11.1 — Methods for calculating acceptable unprotected area (including simplified Table 11.1 route for lower buildings).