

```
// task 3: IOT Data Monitoring Dashboard
const int tempPin=A0;
const int potPin=A1;

void setup() {
  Serial.begin(9600);
}
void loop(){
  int rawTemp=analogRead(tempPin);
  int rawHumditiy=analogRead(potPin);

  float voltage =rawTemp*(5.0/1023.0);
  float temperatureC=(voltage-0.5)*100.0;
  float humidityPercent=map(rawHumditiy,0,1023,0,100);

  //Format specifically for Serial plotter:
  //Each labeled value separated by a comma + separate line on the graph
  Serial.print("Temperature:");
  Serial.print(temperatureC);
  Serial.println(",");
  Serial.print("Humidity:");
  Serial.println(humidityPercent);

  delay(500); //update twice a second for a smoother live graph
}
```