


AccessScan Compliance Audit Report

Audit Identifier Reference: 9382370c
Overall Compliance Valuation Score: 90% (Excellent Accessibility Profile)

Captured Audit Visual Instance Frame:



DSAPT Clause-by-Clause Evaluation Metrics:

Detected Feature	DSAPT Clause Reference	Compliance Evaluation	System Analysis & Observations
HANDRAIL	DSAPT Part 5.4	COMPLIANT	Accessibility component verified: Asset is present on-site[cite: 242].
HANDRAIL	DSAPT Part 5.4	COMPLIANT	Accessibility component verified: Asset is present on-site[cite: 242].
HANDRAIL	DSAPT Part 5.4	COMPLIANT	Accessibility component verified: Asset is present on-site[cite: 242].
TGSI	DSAPT Part 3.3	COMPLIANT	Accessibility component verified: Asset is present on-site[cite: 242].

RAMP	DSAPT Part 5.2	NON-COMPLIANT	Evaluated gradient is 12.0° — Violates the 1:14 threshold requirement limit[cite: 242].
TGSI	DSAPT Part 3.3	COMPLIANT	Accessibility component verified: Asset is present on-site[cite: 242].
KERB_CUT	DSAPT Part 4.1	COMPLIANT	Accessibility component verified: Asset is present on-site[cite: 242].
TGSI	DSAPT Part 3.3	COMPLIANT	Accessibility component verified: Asset is present on-site[cite: 242].
TGSI	DSAPT Part 3.3	COMPLIANT	Accessibility component verified: Asset is present on-site[cite: 242].
TGSI	DSAPT Part 3.3	COMPLIANT	Accessibility component verified: Asset is present on-site[cite: 242].