Product Type	Complaint Type	Issue Severity	Assigned To	Complaint Statu	Service Validatio Dispatch Red	ques Received by EPR Esti	nated Repair	Cost Approved (Y	Repair Complete Fi	nal Dispatch Da	Resolution Sumn TAT (Turnaro	und Time)
ower Adapter	Software Glitch	Medium	E. Patel	Under Repair	Remote Support Resolved	No					Resolved via phone support	
ower Adapter	Software Glitch	High	D. Verma	Under Repair	Needs Dispatch 6/13/2	2025 Yes	836.51	N	6/18/2025	6/19/2025	Replaced part an	9
nergizer	Power Issue	Medium	E. Patel	Under Repair	Remote Support Resolved	No					Resolved via phone support	
ate Motor Con	nt Software Glitch	Medium	D. Verma	Validated	Remote Support Resolved	No					Resolved via phone support	
nergizer	Software Glitch	High	E. Patel	Dispatched	Remote Support Resolved	No					Resolved via phone support	
ate Motor Con	nt Software Glitch	Medium	A. Sharma	Dispatched	Remote Support Resolved	No					Resolved via phone support	
nergizer	Software Glitch	High	A. Sharma	Under Repair	Remote Support Resolved	No					Resolved via phone support	
ate Motor Con	nt Physical Damage	High	E. Patel	Submitted	Remote Support Resolved	No					Resolved via phone support	
nergizer	Charging Fault	High	A. Sharma	Submitted	Remote Support Resolved	No					Resolved via phone support	
ate Motor Con	nt Overheating	Medium	D. Verma	Under Repair	Needs Dispatch 6/26/2	2025 Yes	942.86	Υ	6/28/2025	6/29/2025	Replaced part an	6
ower Adapter	Power Issue	Medium	A. Sharma	Validated	Needs Dispatch 7/21/2	2025 Yes	696.02	Υ	7/26/2025	7/27/2025	Replaced part an	9
ate Motor Con	nt Overheating	High	E. Patel	Dispatched	Needs Dispatch 7/8/2	2025 Yes	366.32	Υ	7/12/2025	7/14/2025	Replaced part an	7
ate Motor Con	nt Charging Fault	Low	B. Roy	Dispatched	Needs Dispatch 6/13/2	2025 Yes	560.24	Υ	6/18/2025	6/19/2025	Replaced part an	9
nergizer	Charging Fault	Medium	B. Roy	Dispatched	Needs Dispatch 6/4/2	2025 Yes	570.12	N	6/8/2025	6/10/2025	Replaced part an	8
ate Motor Con	nt Physical Damage	Medium	C. Mehta	Validated	Remote Support Resolved	No					Resolved via phone support	
ate Motor Con		Low	C. Mehta	Validated	Remote Support Resolved	No					Resolved via phone support	
nergizer	Physical Damage	Low	C. Mehta	Validated	Needs Dispatch 7/9/2	2025 Yes	767.32	N	7/13/2025	7/14/2025	Replaced part an	8
ate Motor Con	nt Overheating	Low	C. Mehta	Validated	Needs Dispatch 6/17/2	2025 Yes	864.14	N	6/19/2025	6/20/2025	Replaced part an	4
ower Adapter	Power Issue	Low	E. Patel	Dispatched	Remote Support Resolved	No					Resolved via phone support	
iate Motor Con	nt Physical Damage	High	B. Roy	Submitted	Needs Dispatch 6/13/2	2025 Yes	401.13	N	6/15/2025	6/17/2025	Replaced part an	7
nergizer	Charging Fault	Medium	E. Patel	Dispatched	Remote Support Resolved	No					Resolved via phone support	
ate Motor Con	nt Software Glitch	High	B. Roy	Validated	Remote Support Resolved	No					Resolved via phone support	
ate Motor Con	nt Software Glitch	High	B. Roy	Dispatched	Needs Dispatch 7/8/2	2025 Yes	227.3	N	7/13/2025	7/14/2025	Replaced part an	8
ower Adapter	Software Glitch	Medium	D. Verma	Validated	Needs Dispatch 6/20/2	2025 Yes	143.48	Υ	6/23/2025	6/25/2025	Replaced part an	8
nergizer	Physical Damage	Medium	B. Roy	Under Repair	Remote Support Resolved	No					Resolved via phone support	
ower Adapter	Power Issue	High	A. Sharma	Under Repair	Remote Support Resolved	No					Resolved via phone support	
nergizer	Overheating	High	E. Patel	Dispatched	Needs Dispatch 7/7/2	2025 Yes	315.38	N	7/9/2025	7/10/2025	Replaced part an	6
ower Adapter	Overheating	Low	E. Patel	Submitted	Needs Dispatch 8/1/2	2025 Yes	826.33	Υ	8/5/2025	8/7/2025	Replaced part an	8
ower Adapter	Overheating	High	C. Mehta	Under Repair	Needs Dispatch 6/30/2	2025 Yes	564.96	N	7/2/2025	7/4/2025	Replaced part an	7
ate Motor Con	nt Charging Fault	Medium	D. Verma	Validated	Needs Dispatch 6/25/2	2025 Yes	284.22	Υ	6/28/2025	6/30/2025	Replaced part an	8
ower Adapter	Power Issue	High	D. Verma	Submitted	Needs Dispatch 6/17/2	2025 Yes	395.74	Υ	6/20/2025	6/21/2025	Replaced part an	7
ate Motor Con	nt Charging Fault	Low	B. Roy	Submitted	Needs Dispatch 6/21/2	2025 Yes	733.03	Υ	6/26/2025	6/27/2025	Replaced part an	9
ower Adapter	Overheating	Low	C. Mehta	Under Repair	Needs Dispatch 7/24/2	2025 Yes	747.54	N	7/27/2025	7/29/2025	Replaced part an	6
nergizer	Charging Fault	Medium	A. Sharma	Dispatched	Needs Dispatch 6/8/2	2025 Yes	891.11	N	6/11/2025	6/12/2025	Replaced part an	6
ower Adapter	Charging Fault	Medium	D. Verma	Validated	Needs Dispatch 6/18/2	2025 Yes	147.61	N	6/23/2025	6/24/2025	Replaced part an	8
ate Motor Con	nt Power Issue	High	C. Mehta	Submitted	Remote Support Resolved	No					Resolved via phone support	
ower Adapter	Physical Damage	High	C. Mehta	Under Repair	Remote Support Resolved	No					Resolved via phone support	
ower Adapter	Software Glitch	Low	A. Sharma	Submitted	Needs Dispatch 6/28/2	2025 Yes	493.51	N	6/30/2025	7/2/2025	Replaced part an	6
ower Adapter	Physical Damage	High	B. Roy	Dispatched	Remote Support Resolved	No					Resolved via phone support	
ower Adapter	Overheating	Low	B. Roy	Validated	Remote Support Resolved	No					Resolved via phone support	
ower Adapter	Overheating	Low	E. Patel	Submitted		2025 Yes	743.93	Υ	7/23/2025		Replaced part an	5
ower Adapter	Power Issue	Low	C. Mehta	Under Repair	Remote Support Resolved	No					Resolved via phone support	
nergizer	Software Glitch	Medium	E. Patel	Validated	Remote Support Resolved	No					Resolved via phone support	
		Medium	B. Roy	Submitted	Remote Support Resolved	No					Resolved via phone support	
ower Adapter		Low	C. Mehta	Submitted	Remote Support Resolved	No					Resolved via phone support	
	nt Software Glitch	Low	D. Verma	Validated		2025 Yes	481.21	N	7/11/2025		Replaced part an	7
	nt Physical Damage		A. Sharma	Submitted	Remote Support Resolved	No					Resolved via phone support	
nergizer	Charging Fault	High	D. Verma	Dispatched		2025 Yes	931.11	N	6/15/2025		Replaced part an	7
-	Software Glitch	-	B. Roy	Dispatched	Remote Support Resolved	No					Resolved via phone support	

ower Adapter	Software Glitch	Low	D. Verma	Validated	Needs Dispatch	6/26/2025	Yes 4	63.52 Y	′ 6,	/28/2025 6/2	29/2025	5 Replaced part an	6
		Low	C. Mehta	Validated	Needs Dispatch	8/2/2025		54.44 Y				5 Replaced part an	6
ate Motor Con	t Physical Damage	High	B. Roy	Under Repair	Needs Dispatch	6/8/2025	Yes 1	95.07 Y	· 6,	/13/2025 6/3	15/2025	5 Replaced part an	10
nergizer	Physical Damage	Low	C. Mehta	Dispatched	Remote Support Re	solved	No					Resolved via phone support	
ower Adapter	Charging Fault	High	A. Sharma	Validated	Needs Dispatch	6/18/2025	Yes 1	97.58 Y	· 6,	/22/2025 6/2	24/2025	5 Replaced part an	8
nergizer	Charging Fault	Low	E. Patel	Validated	Remote Support Re	solved	No					Resolved via phone support	
nergizer	Software Glitch	Low	B. Roy	Under Repair	Remote Support Re	solved	No					Resolved via phone support	
ower Adapter	Power Issue	High	E. Patel	Dispatched	Remote Support Re	solved	No					Resolved via phone support	
ower Adapter	Software Glitch	Medium	E. Patel	Validated	Needs Dispatch	6/18/2025	Yes	385.4 N	۱ 6,	/23/2025 6/2	24/2025	5 Replaced part an	7
nergizer	Overheating	Medium	E. Patel	Dispatched	Needs Dispatch	7/26/2025	Yes 6	84.22 N	N 7,	/30/2025 7/3	31/2025	5 Replaced part an	6
nergizer	Overheating	High	C. Mehta	Validated	Needs Dispatch	7/28/2025	Yes 4	97.34 Y	7,	/31/2025 8,	/1/2025	5 Replaced part an	7
ate Motor Con	t Charging Fault	Medium	A. Sharma	Submitted	Needs Dispatch	6/18/2025	Yes 4	34.41 N	۱ 6,	/21/2025 6/2	23/2025	5 Replaced part an	8
ower Adapter	Power Issue	Low	A. Sharma	Submitted	Needs Dispatch	6/5/2025	Yes 9	84.49 Y	′ (6/9/2025 6/2	11/2025	5 Replaced part an	8
ate Motor Con	t Overheating	Low	E. Patel	Under Repair	Remote Support Re	solved	No					Resolved via phone support	
ower Adapter	Power Issue	High	A. Sharma	Submitted	Needs Dispatch	7/4/2025	Yes 5	80.21 Y	,	7/9/2025 7/2	11/2025	5 Replaced part an	10
ate Motor Con	t Power Issue	Low	D. Verma	Validated	Needs Dispatch	6/25/2025	Yes	160 Y	6,	/28/2025 6/3	30/2025	5 Replaced part an	8
ate Motor Con	t Charging Fault	Medium	A. Sharma	Dispatched	Remote Support Re		No					Resolved via phone support	
nergizer	Physical Damage	Medium	A. Sharma	Under Repair	Needs Dispatch	6/14/2025	Yes 4	27.84 Y	· 6,	/19/2025 6/2	21/2025	5 Replaced part an	10
ate Motor Con	t Software Glitch	High	C. Mehta	Under Repair	Needs Dispatch	7/23/2025	Yes 8	51.29 N	N 7,			5 Replaced part an	5
ower Adapter	Charging Fault	Low	D. Verma	Dispatched	Remote Support Re	solved	No					Resolved via phone support	
ate Motor Con	t Physical Damage	Low	D. Verma	Submitted	Remote Support Re	solved	No					Resolved via phone support	
nergizer	Physical Damage		E. Patel	Dispatched	Remote Support Re	solved	No					Resolved via phone support	
ate Motor Con	t Overheating	Low	A. Sharma	Submitted	Remote Support Re	solved	No					Resolved via phone support	
nergizer	Overheating	High	B. Roy	Under Repair	Needs Dispatch	7/20/2025	Yes 9	66.79 N	N 7,	/22/2025 7/2	24/2025	5 Replaced part an	5
ate Motor Con	t Overheating	High	A. Sharma	Submitted	Needs Dispatch	6/16/2025	Yes	689.4 N	N 6/	/20/2025 6/2	22/2025	5 Replaced part an	9
ate Motor Con	t Software Glitch	Low	D. Verma	Under Repair	Needs Dispatch	7/8/2025	Yes 5	53.33 Y	7 7,	/10/2025 7/2	12/2025	5 Replaced part an	6
nergizer	Power Issue	Medium	E. Patel	Validated	Remote Support Re	solved	No					Resolved via phone support	
nergizer	Charging Fault	Low	D. Verma	Validated	Remote Support Re	solved	No					Resolved via phone support	
ower Adapter	Overheating	Medium	C. Mehta	Dispatched	Needs Dispatch	6/8/2025	Yes 4	85.07 N	N 6/	/12/2025 6/3	13/2025	5 Replaced part an	6
ower Adapter	Physical Damage	Low	C. Mehta	Under Repair	Needs Dispatch	6/30/2025	Yes 4	17.96 Y	,	7/4/2025 7	/6/2025	5 Replaced part an	7
ower Adapter	Physical Damage	High	A. Sharma	Submitted	Needs Dispatch	7/3/2025	Yes 6	94.98 N	J .	7/5/2025 7,	/7/2025	5 Replaced part an	6
ower Adapter	Charging Fault	Low	B. Roy	Dispatched	Remote Support Re	solved	No					Resolved via phone support	
ower Adapter	Overheating	Low	C. Mehta	Under Repair	Needs Dispatch	7/4/2025	Yes 4	34.35 N	J .	7/8/2025 7/2	10/2025	5 Replaced part an	8
ower Adapter	Physical Damage	Low	E. Patel	Validated	Needs Dispatch	6/14/2025	Yes	426.2 N	N 6,	/16/2025 6/3	17/2025	5 Replaced part an	6
nergizer	Physical Damage	Medium	C. Mehta	Dispatched	Remote Support Re	solved	No					Resolved via phone support	
nergizer	Power Issue	High	B. Roy	Under Repair	Needs Dispatch	7/30/2025	Yes 8	68.54 N	N 8	8/1/2025 8,	/2/2025	5 Replaced part an	6
ate Motor Con	t Overheating	Medium	D. Verma	Dispatched	Remote Support Re	solved	No					Resolved via phone support	
	t Software Glitch	High	E. Patel	Validated	Needs Dispatch	6/19/2025	Yes 8	59.22 N	۱ 6,	/23/2025 6/2	24/2025	5 Replaced part an	6
nergizer	Overheating	Low	E. Patel	Validated	Needs Dispatch	7/6/2025		20.54 N				5 Replaced part an	8
nergizer	Overheating	High	C. Mehta	Under Repair	Needs Dispatch	6/29/2025		95.79 Y				5 Replaced part an	7
nergizer	_	Low	E. Patel	Dispatched	Needs Dispatch	7/24/2025		12.61 N				5 Replaced part an	5
	Physical Damage	High	C. Mehta	Under Repair	Needs Dispatch	7/19/2025		194.6 Y				5 Replaced part an	10
	t Software Glitch	-	B. Roy	Validated	Needs Dispatch	6/3/2025		64.02 N				5 Replaced part an	5
	Physical Damage		B. Roy	Submitted	Remote Support Re		No					Resolved via phone support	
		High	A. Sharma	Validated	Needs Dispatch	7/23/2025		84.45 Y	7,	/28/2025 7/2	29/2025	5 Replaced part an	9
nergizer	Charging Fault	Low	B. Roy	Submitted	Needs Dispatch	6/29/2025		88.62 N			•	5 Replaced part an	5
ower Adapter		Low	B. Roy	Submitted	Needs Dispatch	6/22/2025		67.96 Y				5 Replaced part an	5
	t Physical Damage		C. Mehta	Under Repair	Remote Support Re		No			,	,	Resolved via phone support	-
ower Adapter	Overheating	Medium	D. Verma	Validated	Needs Dispatch	7/8/2025		15.05 Y	7.	/12/2025 7/2	14/2025	5 Replaced part an	9
nergizer	Software Glitch		D. Verma	Under Repair	Needs Dispatch	6/8/2025		23.91 N	· · · · · · · · · · · · · · · · · · ·		•	5 Replaced part an	6

Gate Motor Cont Software Glitch High	A. Sharma	Submitted	Remote Support Resolved	No			Resolved via phone support	