
extended value viewer
watch: BX
word
byte
hex: 00
bin: 00000000
oct: 000
decimal 8 bit
unsigned: 0
signed: 0
ascii:
SAVE
ASSEMBLE
RUN
drive help
single step
run
step delay ms: 0
0100:000D
MOV SI, 01150h
MOV DI, 01250h
MOV CX, 00006h
CLD
MOVSB
LOOP 0Ah
RLT
NOP
original source c...
MOV SI, 1150H
MOV DI, 1250H
MOV CX, 0006H
CLD
REPEAT: MOVSB
LOOP REPEAT
Random Access Memory
0100:1250
update
table
list
02250
0100:1250 52 53 54 55 56 57 00 00-00 00 00 00 00 00 00 00 RSTUVW.....
0100:1260 00 00 00 00 00 00 00 00-00 00 00 00 00 00 00 00 ....
0100:1270 00 00 00 00 00 00 00 00-00 00 00 00 00 00 00 00 ....
0100:1280 00 00 00 00 00 00 00 00-00 00 00 00 00 00 00 00 ....
0100:1290 00 00 00 00 00 00 00 00-00 00 00 00 00 00 00 00 ....
0100:12A0 00 00 00 00 00 00 00 00-00 00 00 00 00 00 00 00 ....
0100:12B0 00 00 00 00 00 00 00 00-00 00 00 00 00 00 00 00 ....
0100:12C0 00 00 00 00 00 00 00 00-00 00 00 00 00 00 00 00 ....
IP 000D
SS 0100
SP FFFE
BP 0000
SI 1156
DI 1256
DS 0100
ES 0100
screen
source
reset
aux
vars
debug
stack