



## CERTIFIED REPORT

## **Hardware Information**

Computer Vendor: Dell Inc., Model: Latitude E5570, Serial HLDBVD2

Motherboard Vendor: Dell Inc., Model: 03MCRF

Processor Intel(R) Core(TM) i5-6300U CPU @ 2.40GHz

RAM 8192 MB, Memory banks filled Unavailable/1, DDR4 SODIMM NIC Intel Corporation, Wireless 8260, MAC address: Unavailable Intel Corporation, Ethernet Connection I219-LM, MAC address:

28:f1:0e:31:58:d9

Drive 1 Vendor: Toshiba, Model: TOSHIBA MQ01ACF050, Serial: 46KTTZGGT,

Size: 500.11 GB, Pre-wipe SMART health status: PASSED

Display Adapter Vendor: Intel Corporation, Model: HD Graphics 520

Multimedia Adapter Vendor: Intel Corporation, Model: Sunrise Point-LP HD Audio

USB Ports: 0, USB3 Ports: 0

## **Hardware Tests**

Motherboard Pass
Processor Pass
Memory Pass

## **Wipe Information**

Wipe Method NIST 800-88r1

Software used WipeDrive Enterprise 8.3 32-bit

Kernel Version 4.12.12-gentoo

Job UUID 8D7C34C9-FEFE-4C05-964C-686E1923E7BB

Job fields

Username Randy Prashad

 User2
 561157

 User3
 EquiLend

 User4
 18916

 \"Product\"
 Laptop

Target Drive 1 - Vendor: Toshiba, Model: TOSHIBA MQ01ACF050, Serial:

46KTTZGGT, Size: 500.11 GB , Pre-wipe SMART health status:

**PASSED** 

Action Result FAILURE

UUID 7836F2C2-2A1C-4B12-ABD1-DBFC1BC67F61

Time started Friday, 07 Feb 2020 at 16:58:46

Duration 01:20:41

Remapped sectors 88
Dirty Sectors 0
Drive Errors Detected 1

DCO found / removed No / No HPA found / removed No / No

AMAX found / removed No / No

Sectors overwritten	15440616
Sectors not overwritten	961332552
Sectors verified	0
NIST Method Type	Unknown

