Hardware Information

Computer Vendor: Apple Inc., Model: MacBook6,1, Serial W89477XS8PX

Motherboard Vendor: Apple Inc., Model: Mac-F22C8AC8

Processor Intel(R) Core(TM)2 Duo CPU P7550 @ 2.26GHz

RAM 4096 MB, Memory banks filled Unavailable/2, DDR3 SODIMM

NIC NVIDIA Corporation, MCP79 Ethernet, MAC address: d4:9a:20:bd:b6:ee
NIC Broadcom Inc. and subsidiaries, BCM43224 802.11a/b/g/n, MAC address:

d4:9a:20:70:a1:f8

DVD writer DVD-R UJ-898

Drive 1 Vendor: Hitachi, Model: Hitachi HTS545025B9SA02, Serial:

091103PBC2001SH6WMRL, Size: 250.06 GB, Pre-wipe SMART health

status: PASSED, Post-wipe SMART health status: PASSED

Display Adapter Vendor: NVIDIA Corporation, Model: C79 [GeForce 9400M]

Multimedia Adapter Vendor: NVIDIA Corporation, Model: MCP79 High Definition Audio

USB Ports: 5, USB2 Ports: 2, USB3 Ports: 0

Hardware Tests

Motherboard Pass Processor Pass Memory Pass

Wipe Information

Wipe Method DoD 5220.22-M - 3 Pass

Software Used WipeDrive Enterprise 9.1.3 64-bit

Kernel Version 4.14.65-gentoo

Job UUID 48C45AA6-9625-48C2-B868-E44851F11C65

User name ITAMG Computer ID Asset Tag#

User fields

Username Randy Prashad

Asset Number 563362

Lot Name Metropolitan Museum of Art

Lot Number 19037 \"Product\" Laptop

Target Drive 1 - Vendor: Hitachi, Model: Hitachi HTS545025B9SA02, Serial:

091103PBC2001SH6WMRL, Size: 250.06 GB, Pre-wipe SMART health

status: PASSED, Post-wipe SMART health status: PASSED

Action Result SUCCESS

UUID 3E441134-381B-4128-82AF-A7FA176E653B

Action Start Time Tuesday, 17 Mar 2020 at 16:25:34

Action Duration 04:17:47

Remapped sectors 0
Dirty Sectors 0

Drive Errors Detected	0
DCO Found / Removed	No / No
HPA Found / Removed	No / No
AMAX Found / Removed	No / No
Secure Erase Passes	1
Sectors Overwritten	488397168
Sectors Not Overwritten	0
Sectors Verified	488397168
NIST Method Type	Clear

