Hardware Information

Computer Vendor: Apple Inc., Model: iMac9,1, Serial W892423U0TG

Motherboard Vendor: Apple Inc., Model: Mac-F2218FA9

Processor Intel(R) Core(TM)2 Duo CPU E8135 @ 2.66GHz

RAM 8192 MB, Memory banks filled Unavailable/2, DDR3 SODIMM

NIC NVIDIA Corporation, MCP79 Ethernet, MAC address: 00:25:4b:d5:e1:56
NIC Broadcom Inc. and subsidiaries, BCM4322 802.11a/b/g/n Wireless LAN

Controller, MAC address: 00:25:4b:98:36:75

DVD writer DVD RW AD-5670S

Drive 1 Vendor: Hitachi, Model: Hitachi HDS721050CLA362, Serial:

JP1570HE2T32JK, Size: 500.11 GB, Pre-wipe SMART health status:

PASSED, Post-wipe SMART health status: PASSED

Display Adapter Vendor: NVIDIA Corporation, Model: C79 [GeForce 9400]

Multimedia Adapter Vendor: NVIDIA Corporation, Model: MCP79 High Definition Audio

USB Ports: 9, USB2 Ports: 2, USB3 Ports: 0

Hardware Tests

Motherboard Pass Processor Pass Memory Pass

Wipe Information

Wipe Method NIST 800-88r1

Software Used WipeDrive Enterprise 9.1.3 64-bit

Kernel Version 4.14.65-gentoo

Job UUID 15F52B92-9EBF-4280-82B8-123BAB38A2F5

User name ITAMG Computer ID Asset Tag#

User fields

Username Randy Prashad

Asset Number 553356
Lot Name 18834
Lot Number 18834
\"Product\" All_In_One

Target Drive 1 - Vendor: Hitachi, Model: Hitachi HDS721050CLA362, Serial:

JP1570HE2T32JK, Size: 500.11 GB, Pre-wipe SMART health status:

PASSED, Post-wipe SMART health status: PASSED

Action Result SUCCESS

UUID 6E5133F2-91EC-492A-818A-322BFB237B5D

Action Start Time Monday, 09 Mar 2020 at 19:35:36

Action Duration 01:20:50

Remapped sectors 0
Dirty Sectors 0

Drive Errors Detected	0
DCO Found / Removed	No / No
HPA Found / Removed	No / No
AMAX Found / Removed	No / No
Sectors Overwritten	976773168
Sectors Not Overwritten	0
Sectors Verified	97677317
NIST Method Type	Clear

