



CERTIFIED REPORT

Hardware Information

Computer Vendor: Dell Inc., Model: Latitude E7450, Serial 4SPLP32

Motherboard Vendor: Dell Inc., Model: 06HN6G

Processor Intel(R) Core(TM) i7-5600U CPU @ 2.60GHz

RAM 8192 MB, Memory banks filled Unavailable/1, DDR3 SODIMM NIC Intel Corporation, Ethernet Connection (3) I218-LM, MAC address:

34:e6:d7:5f:89:1c

NIC Intel Corporation, Wireless 7265, MAC address: Unavailable

Drive 1 Vendor: Samsung, Model: SAMSUNG SSD PM851 mSATA 256GB, Serial:

S1EVNSAG262097, Size: 256.06 GB, Pre-wipe SMART health status:

PASSED

Display Adapter Vendor: Intel Corporation, Model: HD Graphics 5500

Multimedia Adapter Vendor: Intel Corporation, Model: Broadwell-U Audio Controller

Multimedia Adapter Vendor: Intel Corporation, Model: Wildcat Point-LP High Definition Audio

Controller

USB Ports: 2, USB2 Ports: 1, USB3 Ports: 1

Hardware Tests

Motherboard Pass
Processor Pass
Memory Pass

Wipe Information

Wipe Method DoD 5220,22-M - 3 Pass

Software used WipeDrive Enterprise 8.3 32-bit

Kernel Version 4.12.12-gentoo

Job UUID 7AE4117B-BDA1-4656-B498-F5DB7B2123E5

Job fields

Username Randy Prashad

User2 538475

User3 PRA Health Sciences

User4 18703 \"Product\" Laptop

Target Drive 1 - Vendor: Samsung, Model: SAMSUNG SSD PM851 mSATA 256GB,

Serial: S1EVNSAG262097, Size: 256.06 GB, Pre-wipe SMART health

status: PASSED

Action Result FAILURE

UUID D2FE5193-597A-4E2C-B038-75C92C89DC22

Time started Tuesday, 26 Nov 2019 at 14:22:55

Duration 01:01:05

Remapped sectors 0
Dirty Sectors 0
Drive Errors Detected 1

DCO found / removed	No / No
HPA found / removed	No / No
AMAX found / removed	No / No
Secure Erase Passes	1
Sectors overwritten	500118192
Sectors not overwritten	0
Sectors verified	2
NIST Method Type	Unknown

