



CERTIFIED REPORT

Hardware Information

Computer Vendor: Apple Inc., Model: MacBook5,1, Serial W89201DF8QS

Motherboard Vendor: Apple Inc., Model: Mac-F42D89A9

Processor Intel(R) Core(TM)2 Duo CPU P7350 @ 2.00GHz

RAM 4096 MB, Memory banks filled Unavailable/2, DDR3 SODIMM

NIC NVIDIA Corporation, MCP79 Ethernet, MAC address: 00:25:4b:b7:79:a2
NIC Broadcom Limited, BCM4322 802.11a/b/g/n Wireless LAN Controller, MAC

address: Unavailable

DVD writer DVDRW GS21N

Drive 1 Vendor: Hitachi, Model: Hitachi HTS543216L9SA02, Serial:

090417FBE200LCKUZE1F, Size: 160.04 GB, Pre-wipe SMART health

status: PASSED, Post-wipe SMART health status: PASSED

Display Adapter Vendor: NVIDIA Corporation, Model: C79 [GeForce 9400M]

Multimedia Adapter Vendor: NVIDIA Corporation, Model: MCP79 High Definition Audio

USB Ports: 7, USB2 Ports: 2, USB3 Ports: 0

Hardware Tests

Motherboard Pass Processor Pass Memory Pass

Wipe Information

Wipe Method DoD 5220.22-M - 3 Pass

Software used WipeDrive Enterprise 8.3.2 64-bit

Kernel Version 4.16.15-gentoo

Job UUID 3534D777-A98E-42E0-B7B6-68FD58FDDEF6

User name ITAMG Computer ID Asset Tag#

User fields

Username Randy Prashad

Asset Number 131998
Lot Name Ogilvy
Lot Number 12332
\"Product\" Laptop

Target Drive 1 - Vendor: Hitachi, Model: Hitachi HTS543216L9SA02, Serial:

090417FBE200LCKUZE1F, Size: 160.04 GB, Pre-wipe SMART health

status: PASSED, Post-wipe SMART health status: PASSED

Action Result SUCCESS

UUID 68949819-3769-44D3-B8B6-D6A5C6FA8591

Time started Monday, 01 Jan 2001 at 00:12:24

Duration 03:28:34

Remapped sectors 0
Dirty Sectors 0

Drive Errors Detected	0
DCO found / removed	No / No
HPA found / removed	No / No
AMAX found / removed	No / No
Sectors overwritten	312581808
Sectors not overwritten	0
Sectors verified	312581808
NIST Method Type	Clear

