Operation Info

Wipe Method	NIST 800-88r1 (recommended)	Action Start Time	Wednesday, 20 May 2020 at 16:11:36
Action Result	SUCCESS	Action Duration	00:45:12
Target Drive	Vendor: Toshiba	Dirty Sectors	0
	Model: THNSF5256GPUK	Drive Errors	0
	Serial: 27NS120VTAMT	DCO Found / Removed	No / No
	Size: 256.06 GB	HPA Found / Removed	No / No
Software Used	WipeDrive Enterprise 9.3.2.1 64-bit	AMAX Found / Removed	No / No
Kernel Version	5.2.11-mac	OPAL Crypto Erase Passes	1
Job UUID	4328DF2B-680B-4004-A8CF-1ED009EC4C75	TRIM Passes	1
User Fields	Username: Randy Prashad	Sectors Overwritten	500118192
	User2: 600787	Sectors Not Overwritten	0
	User3: Best Made Co	Sectors Verified	50011820
	User4: 19421	NIST Method Type	Purge
		71	

Hardware Information

Drive 1

Computer	Vendor: LENOVO	Display Adapter	Vendor: Intel Corporation
	Model: 20JS0004US		Model: Skylake GT2 [HD Graphics 520]
	Serial: PC0KP44Y	Multimedia Adapter	Vendor: Intel Corporation
Motherboard	Vendor: LENOVO		Model: Sunrise Point-LP HD Audio
	Model: 20JS0004US	USB Ports	USB Ports: 5
Processor	Intel(R) Core(TM) i7-6600U CPU @ 2.60GHz		USB2 Ports: 0
RAM	8192 MB, Memory banks filled 2/2, DDR4 SODIMM		USB3 Ports: 0
NIC	Intel Corporation, Wireless 8260		
	MAC Address: 14:ab:c5:2f:5d:be		
NIC	Intel Corporation, Ethernet Connection I219-LM		
	MAC Address: c8:5b:76:ef:7c:0b		

Vendor: Toshiba Model: THNSF5256GPUK Serial: 27NS120VTAMT Size: 256.06 GB

Drive Media Type: NVME Firmware Version: 51025KLA EUI64: 00080d02001f061a