



## CERTIFIED REPORT

Hardware Information

Computer Vendor: Dell Inc., Model: Latitude E5520, Serial DRFWWL1

Motherboard Vendor: Dell Inc., Model: 03PH4G

Processor Intel(R) Core(TM) i3-2310M CPU @ 2.10GH

RAM 4096 MB, Memory banks filled Unavailable/2, DDR3 SODIMM

NIC Broadcom Limited, BCM4313 802.11bgn Wireless Network Adapter, MAC

address: Unavailable

NIC Broadcom Limited, NetXtreme BCM5761 Gigabit Ethernet PCIe, MAC

address: b8:ac:6f:c8:92:23

DVD reader DVD-ROM DV-28SW

Drive 1 Vendor: Toshiba, Model: TOSHIBA MK2561GSY, Serial: 41RGT59YT, Size:

250.06 GB, Pre-wipe SMART health status: PASSED, Post-wipe SMART

health status: PASSED

Display Adapter Vendor: Intel Corporation, Model: 2nd Generation Core Processor Family

Integrated Graphics Controller

Multimedia Adapter Vendor: Intel Corporation, Model: 6 Series/C200 Series Chipset Family High

**Definition Audio Controller** 

USB Ports: 0, USB2 Ports: 2, USB3 Ports: 0

**Hardware Tests** 

Motherboard Pass Processor Pass Memory Pass

Wipe Information

Wipe Method NIST 800-88r1

Software used WipeDrive Enterprise 8.3 32-bit

Kernel Version 4.12.12-gentoo

Job UUID C887DE7E-9ED2-4B2C-9D15-9E928E211D6D

Job fields

Username Randy Prashad

User2 561160
User3 EquiLend
User4 18916
\"Product\" Laptop

Target Drive 1 - Vendor: Toshiba, Model: TOSHIBA MK2561GSY, Serial:

41RGT59YT, Size: 250.06 GB, Pre-wipe SMART health status:

PASSED, Post-wipe SMART health status: PASSED

Action Result SUCCESS

UUID 996E9CA2-4E5C-4B11-AB6F-1A12397D4738

Time started Friday, 07 Feb 2020 at 16:32:29

Duration 01:01:48

Remapped sectors

Dirty Sectors	0
Drive Errors Detected	0
DCO found / removed	No / No
HPA found / removed	No / No
AMAX found / removed	No / No
Secure Erase Passes	1
Sectors overwritten	488397168
Sectors not overwritten	0
Sectors verified	48839717
NIST Method Type	Purae

