



CERTIFIED REPORT

Hardware Information

Vendor: Hewlett-Packard, Model: HP ProBook 6360b, Serial 2CE1240FWJ Computer

Motherboard Vendor: Hewlett-Packard, Model: 1621

Intel(R) Core(TM) i5-2410M CPU @ 2.30GHz Processor

RAM 4096 MB, Memory banks filled Unavailable/1, DDR3 SODIMM

Intel Corporation, 82579V Gigabit Network Connection, MAC address: NIC

b4:99:ba:56:2f:a7

NIC Broadcom Limited, BCM43224 802.11a/b/g/n, MAC address: Unavailable

DVD-RAM writer CDDVDW TS-L633J

Drive 1 Vendor: Toshiba, Model: TOSHIBA MK3261GSYN, Serial: 51HUD5PGB,

Size: 320.07 GB, Pre-wipe SMART health status: PASSED, Post-wipe

SMART health status: PASSED

Vendor: Intel Corporation, Model: 2nd Generation Core Processor Family Display Adapter

Integrated Graphics Controller

Vendor: Intel Corporation, Model: 6 Series/C200 Series Chipset Family High Multimedia Adapter

Definition Audio Controller

USB Ports USB Ports: 0, USB2 Ports: 2, USB3 Ports: 0

Hardware Tests

Motherboard **Pass** Processor **Pass** Memory **Pass**

Wipe Information

Wipe Method NIST 800-88r1

Software used WipeDrive Enterprise 8.3 32-bit

Kernel Version 4.12.12-gentoo

A3DB7A02-002E-4F08-852D-06BE0E8D7D1E Job UUID

Job fields

Username Randy Prashad

582680 User2

User3 Family Residences user3 = Lot Name Essential Enterprises, Inc.

User4 19172 \"Product\" Laptop

Target Drive 1 - Vendor: Toshiba, Model: TOSHIBA MK3261GSYN, Serial:

51HUD5PGB, Size: 320.07 GB, Pre-wipe SMART health status:

PASSED, Post-wipe SMART health status: PASSED

Action Result SUCCESS

UUID 7F6F402C-77D4-4E38-9594-09959014CDD5

Time started Tuesday, 01 Jan 1980 at 00:07:29

01:02:15 Duration

3 Remapped sectors 0 **Dirty Sectors**

| Drive Errors Detected | 0 |
|-------------------------|-----------|
| DCO found / removed | No / No |
| HPA found / removed | No / No |
| AMAX found / removed | No / No |
| Sectors overwritten | 625142448 |
| Sectors not overwritten | 0 |
| Sectors verified | 62514245 |
| NIST Method Type | Clear |

