



## CERTIFIED REPORT

Hardware Information

Vendor: Dell Inc., Model: Latitude E5530 non-vPro, Serial BW5C4X1 Computer

Motherboard Vendor: Dell Inc., Model: 05GRXT

Intel(R) Core(TM) i5-3230M CPU @ 2.60GHz Processor

**RAM** 4096 MB, Memory banks filled Unavailable/1, DDR3 SODIMM

Broadcom Limited, BCM43228 802.11a/b/g/n, MAC address: Unavailable NIC NIC

Broadcom Limited, NetXtreme BCM5761 Gigabit Ethernet PCIe, MAC

address: f0:1f:af:0e:8e:42

**DVD-RAM** writer DVD+-RW UJ8D1

Vendor: Toshiba, Model: TOSHIBA MK3261GSYN, Serial: 237PT79ET, Drive 1

Size: 320.07 GB, Pre-wipe SMART health status: PASSED, Post-wipe

SMART health status: PASSED

Vendor: Intel Corporation, Model: 3rd Gen Core processor Graphics Display Adapter

Controller

Vendor: Intel Corporation, Model: 7 Series/C216 Chipset Family High Multimedia Adapter

**Definition Audio Controller** 

**USB Ports** USB Ports: 0, USB2 Ports: 2, USB3 Ports: 1

Hardware Tests

Motherboard **Pass** Processor **Pass** Memory **Pass** 

**Wipe Information** 

Wipe Method DoD 5220.22-M - 3 Pass

Software used WipeDrive Enterprise 8.3 32-bit

Kernel Version 4.12.12-gentoo

3DE5024D-2DCE-4B59-96C3-8227AF72FFE7 Job UUID

Job fields

Username Randy Prashad

547955 User2

**Related Companies** User3

User4 17604 \"Product\" Laptop

**Target Drive** 1 - Vendor: Toshiba, Model: TOSHIBA MK3261GSYN, Serial:

237PT79ET, Size: 320.07 GB, Pre-wipe SMART health status: PASSED,

Post-wipe SMART health status: PASSED

SUCCESS **Action Result** 

**UUID** FCC9DC06-2D1E-4DB2-AC2C-AF9514E095E0

Time started Wednesday, 22 Jan 2020 at 11:08:17

03:39:53 Duration

Remapped sectors 0 0 **Dirty Sectors** 

Drive Errors Detected	0
DCO found / removed	No / No
HPA found / removed	No / No
AMAX found / removed	No / No
Secure Erase Passes	1
Sectors overwritten	625142448
Sectors not overwritten	0
Sectors verified	625142448
NIST Method Type	Clear

