

Pre-wipe SMART health status: PASSED

Operation Info

Wipe Method	NIST 800-88r1 (recommended)	UUID	8BAD7286-BCFE-42F3-B839-AEAB2C5673C2
Action Result	SUCCESS	Action Start Time	Tuesday, 01 Jan 1980 at 00:03:58
Target Drive	Vendor: Hitachi	Action Duration	01:06:21
	Model: Hitachi HTS723232A7A364	Dirty Sectors	0
	Serial: E3834563HMVBYN	Drive Errors	0
	Size: 320.07 GB	DCO Found / Removed	No / No
	Pre-wipe SMART Health Status: PASSED	HPA Found / Removed	No / No
Software Used	WipeDrive Enterprise 9.3.2.1 64-bit	AMAX Found / Removed	No / No
Kernel Version	5.2.11-mac	Sectors Overwritten	625142448
Job UUID	84E85BB9-EA21-4B6E-8C71-02AAF1D573BE	Sectors Not Overwritten	0
User Fields	Username: Randy Prashad	Sectors Verified	62514245
	User2: 595553	NIST Method Type	Clear
	User3: Virtua Health System		
	User4: 17451		

Hardware Information

Computer	Vendor: Hewlett-Packard	Display Adapter	Vendor: Intel Corporation
	Model: HP ProBook 6560b		Model: 2nd Generation Core Processor Family Integrated
	Serial: 4CZ1231JY2		Graphics Controller
Motherboard	Vendor: Hewlett-Packard	Multimedia Adapter	Vendor: Intel Corporation
	Model: 1619		Model: 6 Series/C200 Series Chipset Family High
Processor	Intel(R) Core(TM) i5-2410M CPU @ 2.30GHz		Definition Audio Controller
RAM	4096 MB, Memory banks filled 1/2, DDR3 SODIMM	USB Ports	USB Ports: 3
NIC	Intel Corporation, 82579V Gigabit Network Connection		USB2 Ports: 2
	MAC Address: 9c:8e:99:3d:d2:94		USB3 Ports: 0
NIC	Broadcom Inc. and subsidiaries, BCM43224 802.11a/b/g/n		
	MAC Address: ac:81:12:75:94:f9		
DVD-RAM writer	CDDVDW TS-L633J		
Drive 1	Vendor: Hitachi		
	Model: Hitachi HTS723232A7A364		
	Serial: E3834563HMVBYN		
	Size: 320.07 GB		
	Drive Media Type: Platter		
	Firmware Version: EC2OA60W		