## Operation Info

Wipe Method	NIST 800-88r1 (recommended)	Action Start Time	Thursday, 21 May 2020 at 09:17:53
Action Result	SUCCESS	Action Duration	01:04:26
Target Drive	Vendor: Samsung	Dirty Sectors	0
	Model: SAMSUNG MZ7TY256HDHP-000L7	Drive Errors	0
	Serial: S307NB0H816005	DCO Found / Removed	No / No
	Size: 256.06 GB	HPA Found / Removed	No / No
	Pre-wipe SMART Health Status: PASSED	AMAX Found / Removed	No / No
Software Used	WipeDrive Enterprise 9.3.2.1 64-bit	OPAL Crypto Erase Passes	1
Kernel Version	5.2.11-mac	TRIM Passes	1
Job UUID	84C6277A-9853-4537-88BB-75A6D091D9CF	Sectors Overwritten	500118192
User Fields	Username: Randy Prashad	Sectors Not Overwritten	0
	User2: 598102	Sectors Verified	50011820
	User3: NBA	NIST Method Type	Purge
	User4: 19390		
UUID	229E3596-B4D0-4AB9-A142-FCA2706E825D		

## Hardware Information

Drive 1

Computer	Vendor: LENOVO	Display Adapter	Vendor: Intel Corporation
	Model: 20FN002JUS		Model: Skylake GT2 [HD Graphics 520]
	Serial: PC0FL6KJ	Multimedia Adapter	Vendor: Intel Corporation
Motherboard	Vendor: LENOVO		Model: Sunrise Point-LP HD Audio
	Model: 20FN002JUS	USB Ports	USB Ports: 5
Processor	Intel(R) Core(TM) i5-6300U CPU @ 2.40GHz		USB2 Ports: 0
RAM	8192 MB, Memory banks filled 1/2, DDR3 SODIMM		USB3 Ports: 0
NIC	Intel Corporation, Wireless 8260		
	MAC Address: e4:a4:71:f9:ff:c4		
NIC	Intel Corporation, Ethernet Connection I219-LM		
	MAC Address: c8:5b:76:53:72:13		

Model: SAMSUNG MZ7TY256HDHP-000L7 Serial: S307NB0H816005 Size: 256.06 GB Drive Media Type: SSD Firmware Version: MAT05L6Q Pre-wipe SMART health status: PASSED

Vendor: Samsung