



CERTIFIED REPORT

Hardware Information

Computer Vendor: Microsoft Corporation, Model: Surface Laptop, Serial

006456772357

Motherboard Vendor: Microsoft Corporation, Model: Surface Laptop

Processor Intel(R) Core(TM) i5-7300U CPU @ 2.60GHz

RAM 8192 MB, Memory banks filled Unavailable/2, LPDDR3 Row Of Chips NIC Marvell Technology Group Ltd., 88W8897 [AVASTAR] 802.11ac Wireless,

MAC address: Unavailable

Drive 1 Vendor: 0x1179, Model: THNSN0256GTYA TOSHIBA, Serial:

47JY12A5YXEU, Size: 256.06 GB

Display Adapter Vendor: Intel Corporation, Model: HD Graphics 620

Multimedia Adapter Vendor: Intel Corporation, Model: Xeon E3-1200 v5/E3-1500 v5/6th Gen

Core Processor Imaging Unit

Multimedia Adapter Vendor: Intel Corporation, Model: Intel Corporation

Multimedia Adapter Vendor: Intel Corporation, Model: Sunrise Point-LP HD Audio

USB Ports: 0, USB2 Ports: 0, USB3 Ports: 0

Hardware Tests

Motherboard Pass
Processor Pass
Memory Pass

Wipe Information

Wipe Method NIST 800-88r1

Software used WipeDrive Enterprise 8.3.2 64-bit

Kernel Version 4.16.15-gentoo

Job UUID C427737B-4854-4022-A7A3-6454D00A9C95

User name ITAMG

Computer ID <BAD INDEX>

User fields

Username Randy Prashad

Asset Number 566604

Lot Name RefurbConnect

Lot Number 19067 "Product\" Laptop

Target Drive 1 - Vendor: 0x1179, Model: THNSN0256GTYA TOSHIBA, Serial:

47JY12A5YXEU, Size: 256.06 GB

Action Result SUCCESS

UUID 1EA47A13-BDEC-4683-B1C0-42D1E451310B

Time started Thursday, 09 Jan 2020 at 13:31:10

Duration 01:54:39

Dirty Sectors 0
Drive Errors Detected 0

| DCO found / removed | No / No |
|-------------------------|-----------|
| HPA found / removed | No / No |
| AMAX found / removed | No / No |
| Sectors overwritten | 500118192 |
| Sectors not overwritten | 0 |
| Sectors verified | 50011820 |
| NIST Method Type | Clear |

