



CERTIFIED REPORT

Hardware Information

Computer Vendor: Dell Inc., Model: Latitude E6320, Serial 8ZV16Q1

Motherboard Vendor: Dell Inc., Model: 0GJF11

Processor Intel(R) Core(TM) i5-2520M CPU @ 2.50GH

RAM 4096 MB, Memory banks filled Unavailable/2, DDR3 SODIMM

NIC Intel Corporation, 82579LM Gigabit Network Connection (Lewisville), MAC

address: 5c:26:0a:5c:64:c8

NIC Intel Corporation, Centrino Advanced-N 6205 [Taylor Peak], MAC address:

Unavailable

DVD-RAM writer DVD+-RW GU40N

Drive 1 Vendor: Toshiba, Model: TOSHIBA MK2561GSYN, Serial: 73VQTYDHT,

Size: 250.06 GB, Pre-wipe SMART health status: PASSED, Post-wipe

SMART health status: PASSED

Display Adapter Vendor: Intel Corporation, Model: 2nd Generation Core Processor Family

Integrated Graphics Controller

Multimedia Adapter Vendor: Intel Corporation, Model: 6 Series/C200 Series Chipset Family High

Definition Audio Controller

USB Ports: 4, USB2 Ports: 2, USB3 Ports: 0

Hardware Tests

Motherboard Pass Processor Pass Memory Pass

Wipe Information

Wipe Method DoD 5220.22-M - 3 Pass

Software used WipeDrive Enterprise 8.3 32-bit

Kernel Version 4.12.12-gentoo

Job UUID 9542F053-69A7-464C-886C-C0F0AFF9F748

Job fields

Username Randy Prashad

User2 547080

User3 PRA Health Sciences

User4 18832 \"Product\" Laptop

Target Drive 1 - Vendor: Toshiba, Model: TOSHIBA MK2561GSYN, Serial:

73VQTYDHT, Size: 250.06 GB, Pre-wipe SMART health status:

PASSED, Post-wipe SMART health status: PASSED

Action Result FAILURE

UUID 4A310D64-B171-4F74-80F7-802556CC7A2C

Time started Thursday, 12 Dec 2019 at 09:20:46

Duration 04:00:24

Remapped sectors 0

| Dirty Sectors | 325 |
|-------------------------|-----------|
| Drive Errors Detected | 2 |
| DCO found / removed | No / No |
| HPA found / removed | No / No |
| AMAX found / removed | No / No |
| Secure Erase Passes | 1 |
| Sectors overwritten | 488397168 |
| Sectors not overwritten | 0 |
| Sectors verified | 488397168 |
| NIST Method Type | Unknown |

