Operation Info

Wipe Method	NIST 800-88r1 (recommended)	Action Start Time	Thursday, 14 May 2020 at 18:42:59
Action Result	SUCCESS	Action Duration	00:00:40
Target Drive	Vendor: Apple	Dirty Sectors	0
	Model: SSD SM0256L	Drive Errors	0
	Serial: C02722607Y7J1HM1H	DCO Found / Removed	No / No
	Size: 251.00 GB	HPA Found / Removed	No / No
Software Used	WipeDrive Enterprise 9.3.2.1 64-bit	AMAX Found / Removed	No / No
Kernel Version	5.2.11-mac	Secure Erase Passes	1
Job UUID	EAD19A0E-5EB2-428E-843E-AD9D2508B293	TRIM Passes	1
User Fields	Username: Randy Prashad	Sectors Overwritten	61279344
	II 2 (007/0	Sectors Not Overwritten	0
	User2: 600768	Sectors Not Overwritten	0
	User3: Best Made Co	Sectors Verified	6127935

Hardware Information

Computer	Vendor: Apple Inc.	Display Adapter	Vendor: Advanced Micro Devices, Inc. [AMD/ATI]
	Model: MacBookPro14,3		Model: Baffin [Radeon RX 460/560D / Pro
	Serial: C02TT3BZHTD7		450/455/460/555/555X/560/560X]
Motherboard	Vendor: Apple Inc.	Multimedia Adapter	Vendor: Advanced Micro Devices, Inc. [AMD/ATI]
	Model: Mac-551B86E5744E2388		Model: Baffin HDMI/DP Audio [Radeon RX 550 640SP /
Processor	Intel(R) Core(TM) i7-7700HQ CPU @ 2.80GHz		RX 560/560X]
RAM	16384 MB, Memory banks filled 2/2, LPDDR3 SODIMM	Multimedia Adapter	Vendor: Intel Corporation
NIC	Broadcom Inc. and subsidiaries, BCM43602 802.11ac		Model: 100 Series/C230 Series Chipset Family HD Audio
	Wireless LAN SoC		Controller
	MAC Address: 00:90:4c:0d:f4:3e	USB Ports	USB Ports: 2
Drive 1	Vendor: Apple		USB2 Ports: 0
	Model: SSD SM0256L		USB3 Ports: 0
	Serial: C02722607Y7J1HM1H	Thunderbolt Ports	Thunderbolt Ports: 0
	Size: 251.00 GB		Thunderbolt2 Ports: 0
	Drive Media Type: NVME		Thunderbolt3 Ports: 2
	Firmware Version: CXS5EA0Q		
	EUI64: 00253838df244c13		