



## CERTIFIED REPORT

Hardware Information

Vendor: Dell Inc., Model: Latitude E6320, Serial 3QQT3R1 Computer

Motherboard Vendor: Dell Inc., Model: 0GJF11

Intel(R) Core(TM) i5-2520M CPU @ 2.50GH Processor

**RAM** 4096 MB, Memory banks filled Unavailable/2, DDR3 SODIMM

Intel Corporation, 82579LM Gigabit Network Connection (Lewisville), MAC NIC

address: 5c:26:0a:7a:90:3d

NIC Intel Corporation, Centrino Advanced-N 6205 [Taylor Peak], MAC address:

Unavailable

**DVD-RAM** writer DVD+-RW DU-8A3S

Drive 1 Vendor: Toshiba, Model: TOSHIBA MK2561GSYN, Serial: 82PHFPTMS,

Size: 250.06 GB, Pre-wipe SMART health status: PASSED, Post-wipe

SMART health status: PASSED

Display Adapter Vendor: Intel Corporation, Model: 2nd Generation Core Processor Family

Integrated Graphics Controller

Multimedia Adapter Vendor: Intel Corporation, Model: 6 Series/C200 Series Chipset Family High

**Definition Audio Controller** 

**USB Ports** USB Ports: 2, USB2 Ports: 2, USB3 Ports: 0

**Hardware Tests** 

Motherboard **Pass** Processor **Pass** Memory **Pass** 

Wipe Information

Wipe Method DoD 5220.22-M - 3 Pass

Software used WipeDrive Enterprise 8.3 32-bit

Kernel Version 4.12.12-gentoo

Job UUID 7B884CFA-0C63-42F6-97CD-4C853FC88FCB

Job fields

Randy Prashad Username

546943 User2

User3 PRA Health Sciences

User4 18743 \"Product\" Laptop

**Target Drive** 1 - Vendor: Toshiba, Model: TOSHIBA MK2561GSYN, Serial:

82PHFPTMS, Size: 250.06 GB, Pre-wipe SMART health status:

PASSED, Post-wipe SMART health status: PASSED

**Action Result SUCCESS** 

**UUID** 0D961A94-B49E-4591-A2B0-5F58854E970D

Time started Thursday, 05 Dec 2019 at 15:16:02

Duration 03:07:24

0 Remapped sectors

Dirty Sectors	0
Drive Errors Detected	0
DCO found / removed	No / No
HPA found / removed	No / No
AMAX found / removed	No / No
Secure Erase Passes	1
Sectors overwritten	488397168
Sectors not overwritten	0
Sectors verified	488397168
NIST Method Type	Clear

