Hardware Information

Computer Vendor: Apple Inc., Model: MacBookPro7,1, Serial W80490XXATQ

Motherboard Vendor: Apple Inc., Model: Mac-F222BEC8

Processor Intel(R) Core(TM)2 Duo CPU P8800 @ 2.66GHz

RAM 4096 MB, Memory banks filled Unavailable/1, DDR3 SODIMM

NIC Broadcom Inc. and subsidiaries, BCM4322 802.11a/b/g/n Wireless LAN

Controller, MAC address: f0:b4:79:22:52:5f

NIC Broadcom Inc. and subsidiaries, NetXtreme BCM5764M Gigabit Ethernet

PCIe, MAC address: 10:9a:dd:54:6c:0e

DVD writer DVD-R UJ-898

Drive 1 Vendor: Hitachi, Model: Hitachi HTS545032B9SA02, Serial:

101112PBSC00PYG3226S, Size: 320.07 GB, Pre-wipe SMART health

status: PASSED, Post-wipe SMART health status: PASSED

Display Adapter Vendor: NVIDIA Corporation, Model: MCP89 [GeForce 320M]

Multimedia Adapter Vendor: NVIDIA Corporation, Model: MCP89 High Definition Audio

USB Ports: 10, USB2 Ports: 2, USB3 Ports: 0

Hardware Tests

Motherboard Pass
Processor Pass
Memory Pass

Wipe Information

Wipe Method NIST 800-88r1

Software Used WipeDrive Enterprise 9.1.3 64-bit

Kernel Version 4.14.65-gentoo

Job UUID B25CCD8F-1B52-481B-ABD5-96F9B7D021B0

User name ITAMG
Computer ID Not Specified

User fields

Username Randy Prashad

Asset Number 583072

Lot Name Geometry Global

Lot Number 19117
"Product\" Laptop

Target Drive 1 - Vendor: Hitachi, Model: Hitachi HTS545032B9SA02, Serial:

101112PBSC00PYG3226S, Size: 320.07 GB, Pre-wipe SMART health

status: PASSED, Post-wipe SMART health status: PASSED

Action Result SUCCESS

UUID A6764B62-5204-4351-9B20-0D64C322D6FB

Action Start Time Monday, 01 Jan 2001 at 22:59:27

Action Duration 01:39:42

Remapped sectors (

Dirty Sectors	0
Drive Errors Detected	0
DCO Found / Removed	No / No
HPA Found / Removed	No / No
AMAX Found / Removed	No / No
Secure Erase Passes	1
Sectors Overwritten	625142448
Sectors Not Overwritten	0
Sectors Verified	62514245
NIST Method Type	Purge