



CERTIFIED REPORT

Hardware Information

Vendor: Dell Inc., Model: OptiPlex 7010, Serial 2JZWDZ1 Computer

Vendor: Dell Inc., Model: 0WR7PY Motherboard

Intel(R) Core(TM) i5-3475S CPU @ 2.90GHz Processor

RAM 4096 MB, Memory banks filled Unavailable/1, DDR3 DIMM

NIC Intel Corporation, 82579LM Gigabit Network Connection (Lewisville), MAC

address: f8:b1:56:9b:41:05

DVD-RAM writer **DVD+-RW GTA0N**

Drive 1 Vendor: Kingston, Model: DataTraveler 2.0, Serial: 0, Size: 7.75 GB Display Adapter

Vendor: Advanced Micro Devices, Inc. [AMD/ATI], Model: Caicos XT

[Radeon HD 7470/8470 / R5 235/310 OEM]

Vendor: Advanced Micro Devices, Inc. [AMD/ATI], Model: Caicos HDMI Multimedia Adapter

Audio [Radeon HD 6450 / 7450/8450/8490 OEM / R5 230/235/235X OEM]

Multimedia Adapter Vendor: Intel Corporation, Model: 7 Series/C216 Chipset Family High

Definition Audio Controller

USB Ports USB Ports: 3, USB2 Ports: 2, USB3 Ports: 1

Hardware Tests

Motherboard **Pass** Processor **Pass Pass** Memory

Wipe Information

Wipe Method DoD 5220.22-M - 3 Pass

Software used WipeDrive Enterprise 8.3 32-bit

Kernel Version 4.12.12-gentoo

Job UUID A68B0A73-B173-46D2-B8C5-C7D01958A32C

Job fields

Username Randy Prashad

User2 563412

User3 Metropolitan Museum of Art

User4 19037 \"Product\" Computer

Target Drive 1 - Vendor: Kingston, Model: DataTraveler 2.0, Serial: 0, Size: 7.75 GB

Action Result FAILURE

UUID 262F1CE4-9094-4170-86AA-AC70E09F6FC8

Time started Friday, 21 Feb 2020 at 11:32:44

Duration 00:00:26

Dirty Sectors 0 **Drive Errors Detected** 1

No / No DCO found / removed

HPA found / removed No / No AMAX found / removed No / No

Sectors overwritten	356352
Sectors not overwritten	14775284
Sectors verified	0
NIST Method Type	Unknown

