

Hardware Information

Computer Vendor: IBM, Model: Not Specified, Serial XxXxXxX

Motherboard Vendor: IBM, Model: 49Y6512

Processor Intel(R) Xeon(R) CPU E5520 @ 2.27GHz
Processor Intel(R) Xeon(R) CPU E5520 @ 2.27GHz

RAM 131072 MB, Memory banks filled Unavailable/16, Other DIMM

NIC Broadcom Inc. and subsidiaries, NetXtreme II BCM5709 Gigabit Ethernet,

MAC address: e4:1f:13:2c:10:28

NIC Broadcom Inc. and subsidiaries, NetXtreme II BCM5709 Gigabit Ethernet,

MAC address: e4:1f:13:2c:10:2a

NIC Unavailable, Unavailable, MAC address: e6:1f:13:25:60:2b

DVD reader UJDA782 DVD/CDRW

Drive 1 Vendor: IBM-ESXS, Model: ST973452SS, Serial:

3TA0K2YV00009012ME6P, Size: 73.41 GB

Drive 2 Vendor: IBM-ESXS, Model: ST973452SS, Serial:

3TA0A3TQ00009012RMBZ, Size: 73.41 GB

Display Adapter Vendor: Matrox Electronics Systems Ltd., Model: MGA G200EV

USB Ports: 9, USB2 Ports: 2, USB3 Ports: 0

Hardware Tests

MotherboardPassProcessorPassMemoryPass

Wipe Information

Wipe Method DoD 5220.22-M - 3 Pass

Software Used WipeDrive Enterprise 9.1.3 64-bit

Kernel Version 4.14.65-gentoo

Job UUID E6DFCC6E-43F1-405F-B264-B453D4286C16

User name ITAMG Computer ID none

User fields

Username Randy Prashad

Asset Number 571397

Lot Name Northwell Health

Lot Number 18978 "Product\" Server

Target Drive 1 - Vendor: IBM-ESXS, Model: ST973452SS, Serial:

3TA0K2YV00009012ME6P, Size: 73.41 GB

Action Result FAILURE

UUID AB53B2E8-D6F3-4923-BDB0-5EEFFAB6C2A0

Action Start Time Wednesday, 29 Jan 2020 at 16:07:57

Action Duration 00:28:49

Remapped sectors 2048 **Dirty Sectors** 0 **Drive Errors Detected** 1 DCO Found / Removed No / No HPA Found / Removed No / No AMAX Found / Removed No / No Sectors Overwritten 143374000 Sectors Not Overwritten 0 Sectors Verified 500736 **NIST Method Type** Unknown

Target Drive 2 - Vendor: IBM-ESXS, Model: ST973452SS, Serial:

3TA0A3TQ00009012RMBZ, Size: 73.41 GB

Action Result FAILURE

UUID 2B204BAA-970C-426A-9670-182C6FACB553

Action Start Time Wednesday, 29 Jan 2020 at 16:12:00

Action Duration 00:05:54

Dirty Sectors 0
Drive Errors Detected 1

DCO Found / Removed No / No
HPA Found / Removed No / No
AMAX Found / Removed No / No
Sectors Overwritten 0

Sectors Not Overwritten 143374744

Sectors Verified 0

NIST Method Type Unknown